

Vehicle No.SFV 1226 Y

MODEL:MERC.GLC 250

QTY	DESCRIPTION	REPAIRER'S ESTIMATE(S\$)	SURVEYORS ADJUSTMENT
	PARTS (LIST ITEMS)		
1	Rear bumper	Bumper 1150.00	✓
2	Rear bumper side retainer RHS & LHS	2x 135.00	X
1	Rear end panel	1x 1350.00	X
1	Rear bumper lower lid	Red lid 495.00	✓
1	Rear reinforcement bar	745.00	?
1	Rear bumper lower trim chrome	465.00	?
		10% 4340.00	
		10% 434.00	
		3906.00	

Not with the

Resurvey B4 paint

2-3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



PG.3

Vehicle No.SFV 1226 Y

MODEL:MERC.GLC 250

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYORS ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	500.00	250
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	400.00	300
3	To remove and replace reverse sensors , reverse camera and check for proper function	150.00	60
4	To provide anti-rust treatment on affected areas	nn 120.00	X
5	Perfrom diagnotis on vehicle	250.00	?
	Labour Total :	1420.00	
	TOTAL (PARTS & LABOUR)	5766.00	