

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

3-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6809 J

		\$	531.00
1 pc	Front bumper <i>Xmp</i>	\$	44.00
1 pc	Front bumper emblem <i>X</i>	\$	174.00
1 pc	Front bumper centre grille <i>X</i>	\$	134.00
1 pc	Front bumper lower stiffer <i>X</i>	\$	14.00
1 pc	Front bumper tow hook cover <i>X</i>	\$	110.00
1 pc	Front bumper inner sponge <i>X</i>	\$	328.00
1 pc	Front bumper reinforcement <i>X</i>	\$	32.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 <i>X</i>	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 <i>X</i>	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 <i>X</i>	\$	696.00
1 pc	Rear bumper <i>/</i>	\$	206.00
1 pc	Rear bumper lower cover <i>/</i>	\$	58.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X</i>	\$	114.00
1 pc	Rear bumper inner sponge <i>?</i>	\$	607.00
1 pc	Rear bumper reinforcement <i>?</i>	\$	108.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X</i>	\$	36.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X</i>	\$	3,292.00
		\$	329.20
	Less 10%	\$	2,962.80

S/NETT

1 set	Rear bumper clips <i>/</i>	\$	48.00
1 set	Reverse sensor <i>/</i>	\$	280.00 200
1 pc	Rear bumper top protector <i>/</i>	\$	80.00 50
1 pc	Front no. plate with casing <i>/</i>	\$	50.00 30
1 pc	Front bumper clips <i>X</i>	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00 <i>X</i>	\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00 <i>X</i>	\$	6.00

3-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6809 J

Sundry	\$	50.00 20
To check for wiring and to focus head lamps	\$	80.00 X
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc	\$	950.00 400
To putty and spray painting on front bumper, rear bumper, end panel	\$	600.00 360
To apply rustproofing on the repaired and replaced panels.	\$	120.00 X
	\$	<u>5,586.80</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

1/Calvin (11/11/18)

3/12/18 1530

3 Days

45

After Repair p Lds

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: