來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267
UEN: 199407592C

Your Ref: SHC 3681D

Our Ref: SFY 999R - 2018/JL

2 September 2019

WITHOUT PREJUDICE

India International Insurance Pte Ltd 64 Cecil Street #04-#05 IOB Building Singapore 049711 Attention: Motor Claims

Dear Sirs

ACCIDENT INVOLVING VEHICLE NOS. SFY 999R AND SHC 3681D ON 29/11/2018 AT ORCHARD ROAD

We refer to the above matter wherein your insured's vehicle no. SHC 3681D was involved in an accident with our client's vehicle no. SFY 999R.

As the accident was caused by your insured's negligence, our client is now claiming for the following losses:

Repair cost:

\$1,135.11 (include of GST)

7.49

Loss of use:

\$ 200.00 (2 days x \$100 per day)

LTA search fee: \$
 Table

Total: \$1,342,60

Relevant documents in support of our client's claim are enclosed for your kind attention.

Please do not hestitate to contact Jenny Lim at telephone 64538110 or email jenny.lim@laihuat.com.sg should you need any additional information.

Meanwhile, we look forward to receiving your affirmative response soon enough.

Thank you.

Yours faithfully,

Qhi,

LAI HUAT (MENG KEE) MOTOR PTE LTD

encs

来發(明記)摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267 GST No: M2-0128609-3 UEN: 199407592C

TAX INVOICE

EST No.: EST0020902

Yu Russell Ashby

Attn:

GST Reg No M2-0128609-3

Your ref. TP-SHC 3681D India

Payment

Date 31/12/2018

Vehicle No ...: SFY 999R Vehicle Model : Toyota Vellfire Accident on ...: 29/11/2018

Quantity Uni	t Description	Unit price Disc. pct.		Amount
	Supply of Parts:			
	Rear bumper Rear bumper lower clips	580.80 3.50	25.00 25.00	435.60 5.25
	Labour & Misc:			
1.00	To repair/realign tail lamp lower trim garnish LH and renew of parts	220.00		220.00
1.00	To check/erase fault code	50.00		50.00
1.00	To spray paint (Pearl white)	350.00		350.00

 Sub-Total
 1,060.85

 GST 7.00%
 74.26

 Total
 S\$ 1,135.11

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外,还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Enquire Vehicle Insurer

SHC3681D 29 Nov 2018 / 20:45:00

Successful 105

INDIA INT'L INS PTE LTD

Previous

ОК



Lai Mei Ling Deborah has successfully logged out. Your last login date and time was 30 Nov 2018, 10:07:32. To return to ONE.MOTORING, please click here

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

5/No. J	Asset Type	Asset ID	Asset Owner ID	Transaction Type		
1	Vehicle	SHC3681D	-	18.32 Insurance Enquiry (GIRO Pay		
 Log Date/Time 30 Nov 2018 / 10:07:57 						