

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0020902
Yu Russell Ashby

Page 1 of 1
Your ref. TP-SHC 3681D India
Job No. 70034
Our ref. 18.11.48
Payment
Date 3/12/2018

Attn

Vehicle No SFY 999R
Vehicle Model : Toyota Vellfire
Accident on ... 29/11/2018

Not Not here
1-B-1
Resurvey Bepany
2 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear bumper	580.80	25.00	<i>Adicm</i> 435.60 ✓
2.00	Pcs	Rear bumper lower clips	3.50	25.00	<i>Msc</i> 5.25 ✓
Labour & Misc:					
1.00		To repair/realign tail lamp lower trim garnish LH and renew of parts	250.00		250.00 <i>2201</i>
1.00		To check/erase fault code	50.00		50.00 <i>7</i>
1.00		To spray paint (Pearl white)	450.00		450.00 <i>3501</i>

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature: _____
Date: _____

S\$ 1,190.85
83.36
1,274.21

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."