

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 07 Dec 2018)**Parts:** 143 MERCEDES-BENZ C180 1.6 AVANT GARDE (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ETHOZ Protect Pte Ltd/SKV1916E/07/12/2018 14:30**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP LOWER BRACKET LH	<i>one</i> 0.00	0.00	*68.00 E ✓
2	1		*HEADLAMP WASHER PRESSOR SENSOR WITH HOSE	<i>Two</i> 0.00	0.00	*165.00 F ✓
3	1	<i>ADD</i>	*FRONT PARKING SENSOR WIRINGS	<i>Two</i> 0.00	0.00	*150.00 E ✓
4	1		*FRONT GRILLE BASE	<i>Two</i> 0.00	0.00	*145.00 F ✓

F=Franchise part.

Total Parts (S\$) **528.00**

ETHOZ Protect Pte Ltd/SKV1916E/07/12/2018 14:30. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

ETHOZ Protect Pte Ltd/SKV1916E/07/12/2018 14:30. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

Company Registration No. 199005791M

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>



(SUPPLEMENTARY)

INSURER:

FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00010759	Date of Loss:	02/12/2018
Vehicle Reg. No.:	SKV1916E	Driveable?	
Driver Age/Info:	60 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HO WENG FOON	Contact No:	+6591441083
Driver:	HO WENG FOON		
Make/Model:	MERCEDES-BENZ C180, 1.6 AVANT GARDE (A)	Vehicle Reg. Date:	01/09/2015
Vehicle Colour:	GREY	Chassis No:	WDD2050402R094938
Engine No:	27491030414647		
Odometer:	66858 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	ETHOZ PROTECT PTE LTD (TAMPINES)		

COST OF CLAIMS

	Amount
Parts	136.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	136.00
+ GST 7.00% (\$)	9.52
Nett Amount (\$)	145.52
+ Previous Estimates (\$)	13,692.79
Claim Total (\$)	13,838.31

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Dec 2018)
Parts: 143 MERCEDES-BENZ C180 1.6 AVANT GARDE (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKV1916E)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET LOCK SENSOR RH	0.00	0.00	*68.00 F
2	1		*BONNET LOCK SENSOR LH	0.00	0.00	*68.00 F
Total Parts (S\$)						136.00

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD 30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>
Company Registration No. 199005791M

EURO AUTOPART TRADE

YOUR ONE STOP AUTOPARTS SOLUTION

TAX INVOICE

To COMPANY: ETHOZ PROTECT PTE LTD

INV NO: PF201812-10693

ATTENTION TO SALES PERSON:

KAI

DATE: 7-Dec-18

P/O

167783

VEHICLE NO: SKV1916E MERS C180

30 DAYS

SEND TO : 30 BUKIT BATOK CRES

S/NO.	PART NO.	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1		BONNET	1	\$ 1,550.00	\$ 1,550.00
2		BONNET LOGO	1	\$ 78.00	\$ 78.00
3		HEADLAMP LH	1	\$ 2,300.00	\$ 2,300.00
4		HEADLAMP CONTROL UNIT LH	1	\$ 450.00	\$ 450.00
5		FRT BUMPER	1	\$ 1,250.00	\$ 1,250.00
6		FRT BUMPER CLIPS	10	\$ 4.80	\$ 48.00
7		FRT BUMPER RETAINER LH	1	\$ 58.00	\$ 58.00
8		FOGLAMP COVER LH	1	\$ 90.00	\$ 90.00
9		FOGLAMP COVER CHROME TOP	1	\$ 78.00	\$ 78.00
10		FOGLAMP COVER CHROME LOWER	1	\$ 78.00	\$ 78.00
11		FRT FENDER LH	1	\$ 850.00	\$ 850.00
12		FRT FENDER INNERSHIELD LH FRT	1	\$ 135.00	\$ 135.00
13		FRT FENDER INNERSHIELD CLIP	10	\$ 5.00	\$ 50.00
14		FRT PARKING SENSOR OUTED	1	\$ 145.00	\$ 145.00
15		FRT PARKING SENSOR INNER	1	\$ 145.00	\$ 145.00
16		FRT PARKING SENSOR ORING OUT	1	\$ 15.00	\$ 15.00
17		FRT PARKING SENSOR ORING INN	1	\$ 15.00	\$ 15.00
18		FRT SPORT RIM LH	1	\$ 950.00	\$ 950.00
19		HEADLAMP LOWER BRACKET LH	1	\$ 68.00	\$ 68.00
20		PRESSURE SENSOR WITH PIPE	1	\$ 165.00	\$ 165.00
21		FRT GRILLE BASE	1	\$ 145.00	\$ 145.00
22		PARKING SENSOR WIYER	1	\$ 150.00	\$ 150.00
23					\$ -
24		DELIVERY ST92 TAMPINES			\$ -
25					\$ -
SUB-TOTAL					\$ 8,813.00
GST @ 7%					\$ 616.91
GRAND TOTAL					\$ 9,429.91

NOTE: GOODS SOLD ARE NON RETURNABLE

RECEIVED BY:

AUTHORISED BY:

NO. 50 PLAYFAIR ROAD #03-02F

NOEL BUILDING S(367995)

BRN:53225532A / GST REG NO: M90370620L

TEL: 6635 8238 FAX: 6280 5805 HP: 9451 5113 / 9457 4513

EURO AUTOPART TRADE

YOUR ONE STOP AUTOPARTS SOLUTION

TAX INVOICE

TO COMPANY: ETHOZ PROTECT PTE LTD

INV NO: PF201812-10703

ATTENTION TO SALES PERSON: KAI

DATE: 10-Dec-18

P/O 167783

VEHICLE NO: SKV1916E MERS C180

30 DAYS

SEND TO: 30 BUKIT BATOK CRES

S/NO.	PART NO.	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1		FRT BUMPER SPONGE	1	\$ 135.00	\$ 135.00
2		BONNET ACTUATOR RH/LH	2	\$ 158.00	\$ 316.00
3		BONNET LOCK SENSOR RH/LH	2	\$ 68.00	\$ 136.00
4					\$ -
5					\$ -
6					\$ -
7					\$ -
8					\$ -
9					\$ -
10					\$ -
11					\$ -
12					\$ -
13					\$ -
14					\$ -
15					\$ -
16					\$ -
17					\$ -
18					\$ -
19					\$ -
20					\$ -
21					\$ -
22					\$ -
23					\$ -
24					\$ -
25		DELIVERY ST92 TAMPINES			\$ -
				SUB-TOTAL	\$ 587.00
				GST @ 7%	\$ 41.09
				GRAND TOTAL	\$ 628.09

NOTE: GOODS SOLD ARE NON RETURNABLE

RECEIVED BY:

AUTHORISED BY:

NO. 50 PLAYFAIR ROAD #03-02F

NOEL BUILDING S(367995)

BRN:53225532A / GST REG NO: M90370620L

TEL: 6635 8238 FAX: 6280 5805 HP: 9451 5113 / 9457 4513

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Dec 2018 Sendback Est	04 Dec 2018 15:17 S\$12,269.00	04 Dec 2018 15:22 Edit Adj Rpt	S\$10,940.00 Edit Estimates	S\$10,940.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	07 Dec 2018 14:28	07 Dec 2018 14:30 S\$528.00	07 Dec 2018 14:30			(Combined)	Combined with Main Uncombine Suppl.
Supp #2	11 Dec 2018 08:55	11 Dec 2018 10:02 S\$136.00	11 Dec 2018 10:02			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	HO WENG FOON, ID: S1293410F, Tel: +6591441083, Email: ivanhwf1@hotmail.com		
Vehicle Reg. No.:	SKV1916E	Date of Loss:	02/12/2018 19:00 - :59 [39 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800017136	Policy/Cover Note No.:	PNPV2018-00010759 (Comprehensive)
		Excess:	S\$600.00
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 13/12/2018]		
Driver/Custodian:	HO WENG FOON (60 / Male), NRIC: S1293410F, Tel: +6591441083		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

- FWD_SG (12/12/2018): Alert - Adj Mandate Approved (S\$10940.00) - SKV1916E - Claim Handler: Clara Li Z...
- FWD_SG (06/12/2018): Alert - Adj Mandate Approved (S\$10786.00) - SKV1916E - Claim Handler: Clara Li Z...

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKV1916E (1201800017136)

OD

Dec 2 2018 7:00PM

[HO WENG FOON]

ETHOZ Protect Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View
[View in Browser](#)

Video			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	03/12/18 16:03	Video - Accident [Linked Accident Report Documents]	Load MP4	

Assessment Reports			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	04/12/18 15:17	Repairer Estimates	Load HTM	
2	07/12/18 14:30	Repairer Estimates Suppl. #1	Load HTM	
3	11/12/18 10:02	Repairer Estimates Suppl. #2	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/12/18 14:39	Adjuster Immediate Advice	Load HTM	
2	12/12/18 12:03	Adjuster Immediate Advice	Load HTM	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/12/18 14:35	Chassis Number	Load JPG	☒
2	06/12/18 14:35	Odometer Reading	Load JPG	☒
3	06/12/18 14:35	General View	Load JPG	☒
4	06/12/18 14:35	General View	Load JPG	☒
5	06/12/18 14:35	General View	Load JPG	☒
6	06/12/18 14:35	General View	Load JPG	☒
7	06/12/18 14:35	General View	Load JPG	☒
8	06/12/18 14:35	General View	Load JPG	☒
9	06/12/18 14:35	General View	Load JPG	☒
10	06/12/18 14:35	General View	Load JPG	☒
11	06/12/18 14:35	General View	Load JPG	☒
12	06/12/18 14:35	General View	Load JPG	☒
13	06/12/18 14:35	General View	Load JPG	☒
14	06/12/18 14:35	General View	Load JPG	☒
15	06/12/18 14:35	General View	Load JPG	☒
16	06/12/18 14:35	General View	Load JPG	☒
17	06/12/18 14:35	General View	Load JPG	☒
18	06/12/18 14:35	General View	Load JPG	☒
19	06/12/18 14:35	General View	Load JPG	☒
20	06/12/18 14:35	General View	Load JPG	☒
21	06/12/18 14:35	General View	Load JPG	☒
22	06/12/18 14:35	General View	Load JPG	☒
23	06/12/18 14:35	General View	Load JPG	☒
24	06/12/18 14:35	General View	Load JPG	☒
25	06/12/18 14:35	General View	Load JPG	☒

Video			1 per page ▼	✓
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
26	06/12/18 14:35	General View	 Load JPG	✓
27	06/12/18 14:35	General View	 Load JPG	✓
28	06/12/18 14:35	General View	 Load JPG	✓
29	06/12/18 14:35	General View	 Load JPG	✓
30	06/12/18 14:35	General View	 Load JPG	✓
31	06/12/18 14:35	General View	 Load JPG	✓
32	06/12/18 14:35	General View	 Load JPG	✓
33	06/12/18 14:35	General View	 Load JPG	✓
34	06/12/18 14:35	General View	 Load JPG	✓
35	06/12/18 14:35	General View	 Load JPG	✓
36	06/12/18 14:35	General View	 Load JPG	✓
37	06/12/18 14:35	General View	 Load JPG	✓
38	06/12/18 14:35	General View	 Load JPG	✓
39	06/12/18 14:35	General View	 Load JPG	✓
40	06/12/18 14:35	General View	 Load JPG	✓
41	06/12/18 14:35	General View	 Load JPG	✓
42	06/12/18 14:35	General View	 Load JPG	✓
43	06/12/18 14:35	General View	 Load JPG	✓
44	06/12/18 14:35	General View	 Load JPG	✓
45	06/12/18 14:35	General View	 Load JPG	✓
46	06/12/18 14:35	General View	 Load JPG	✓
47	06/12/18 14:35	General View	 Load JPG	✓
48	06/12/18 14:35	General View	 Load JPG	✓
49	06/12/18 14:35	General View	 Load JPG	✓
50	06/12/18 14:35	General View	 Load JPG	✓
51	06/12/18 14:35	General View	 Load JPG	✓
52	06/12/18 14:35	General View	 Load JPG	✓
53	06/12/18 14:35	General View	 Load JPG	✓
54	06/12/18 14:35	General View	 Load JPG	✓
55	06/12/18 14:35	General View	 Load JPG	✓
56	06/12/18 14:35	General View	 Load JPG	✓
57	06/12/18 14:35	General View	 Load JPG	✓
58	06/12/18 14:35	General View	 Load JPG	✓
59	06/12/18 14:35	General View	 Load JPG	✓
60	06/12/18 14:35	General View	 Load JPG	✓
61	06/12/18 14:35	General View	 Load JPG	✓
62	06/12/18 14:35	General View	 Load JPG	✓
63	06/12/18 14:35	General View	 Load JPG	✓
64	06/12/18 14:35	General View	 Load JPG	✓
65	06/12/18 14:35	General View	 Load JPG	✓
66	18/12/18 14:36	Reinspection Photo	 Load JPG	✓
67	18/12/18 14:36	Reinspection Photo	 Load JPG	✓
68	18/12/18 14:36	Reinspection Photo	 Load JPG	✓
69	18/12/18 14:36	Reinspection Photo	 Load JPG	✓
70	18/12/18 14:36	Reinspection Photo	 Load JPG	✓
71	18/12/18 14:36	Reinspection Photo	 Load JPG	✓
72	18/12/18 14:36	Reinspection Photo	 Load JPG	✓
73	18/12/18 14:36	Reinspection Photo	 Load JPG	✓

Video			1 per page	
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
74	18/12/18 14:36	Reinspection Photo	 Load JPG	
75	18/12/18 14:36	Reinspection Photo	 Load JPG	
76	18/12/18 14:36	Reinspection Photo	 Load JPG	
77	18/12/18 14:36	Reinspection Photo	 Load JPG	
78	18/12/18 14:36	Reinspection Photo	 Load JPG	
79	18/12/18 14:36	Reinspection Photo	 Load JPG	
80	18/12/18 14:36	Reinspection Photo	 Load JPG	
81	18/12/18 14:36	Reinspection Photo	 Load JPG	
82	18/12/18 14:36	Reinspection Photo	 Load JPG	
83	18/12/18 14:36	Reinspection Photo	 Load JPG	
84	18/12/18 14:36	Reinspection Photo	 Load JPG	
85	18/12/18 14:36	Reinspection Photo	 Load JPG	
86	18/12/18 14:36	Reinspection Photo	 Load JPG	
87	18/12/18 14:36	Reinspection Photo	 Load JPG	
88	18/12/18 14:36	Reinspection Photo	 Load JPG	
89	18/12/18 14:36	Reinspection Photo	 Load JPG	
90	18/12/18 14:36	Reinspection Photo	 Load JPG	
91	18/12/18 14:36	Reinspection Photo	 Load JPG	
92	18/12/18 14:36	Reinspection Photo	 Load JPG	
93	18/12/18 14:36	Reinspection Photo	 Load JPG	
94	18/12/18 14:36	Reinspection Photo	 Load JPG	
95	18/12/18 14:36	Reinspection Photo	 Load JPG	
96	18/12/18 14:36	Reinspection Photo	 Load JPG	
97	18/12/18 14:36	Reinspection Photo	 Load JPG	
98	18/12/18 14:36	Reinspection Photo	 Load JPG	
99	18/12/18 14:36	Reinspection Photo	 Load JPG	
100	18/12/18 14:36	Reinspection Photo	 Load JPG	
101	18/12/18 14:36	Reinspection Photo	 Load JPG	
102	18/12/18 14:36	Reinspection Photo	 Load JPG	
103	18/12/18 14:36	Reinspection Photo	 Load JPG	
104	18/12/18 14:36	Reinspection Photo	 Load JPG	
105	18/12/18 14:36	Reinspection Photo	 Load JPG	
106	18/12/18 14:36	Reinspection Photo	 Load JPG	
107	18/12/18 14:36	Reinspection Photo	 Load JPG	
108	18/12/18 14:36	Reinspection Photo	 Load JPG	
109	18/12/18 14:36	Reinspection Photo	 Load JPG	
110	18/12/18 14:36	Reinspection Photo	 Load JPG	
111	18/12/18 14:36	Reinspection Photo	 Load JPG	
112	18/12/18 14:36	Reinspection Photo	 Load JPG	
113	18/12/18 14:36	Reinspection Photo	 Load JPG	
114	18/12/18 14:36	Reinspection Photo	 Load JPG	
115	18/12/18 14:36	Reinspection Photo	 Load JPG	
116	18/12/18 14:36	Reinspection Photo	 Load JPG	
117	18/12/18 14:36	Reinspection Photo	 Load JPG	
118	18/12/18 14:36	Reinspection Photo	 Load JPG	

Documentation

1 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/12/18 14:35	ESTIMATE	 Load PDF	

Video			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
2	19/12/18 14:40	PARTS INVOICE	Load PDF	
3	19/12/18 14:40	SUPPLEMENTARY	Load PDF	

Linked Accident Report Documents

Video			View	View in Browser	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print	
1	03/12/18 16:03	Video - Accident	Load MP4		

Assessment Reports			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	03/12/18 16:03	Accident Statement	Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	03/12/18 14:22	Accident Photo	Load JPG	☒
2	03/12/18 14:22	Accident Photo	Load JPG	☒
3	03/12/18 14:22	Accident Photo	Load JPG	☒
4	03/12/18 14:22	Accident Photo	Load JPG	☒
5	03/12/18 14:22	Accident Photo	Load JPG	☒
6	03/12/18 14:22	Accident Photo	Load JPG	☒
7	03/12/18 14:22	Accident Photo	Load JPG	☒
8	03/12/18 14:22	Accident Photo	Load JPG	☒
9	03/12/18 14:22	Accident Photo	Load JPG	☒
10	03/12/18 14:22	Accident Photo	Load JPG	☒
11	03/12/18 14:22	Accident Photo	Load JPG	☒
12	03/12/18 16:03	Accident Photo	Load JPG	☒
13	03/12/18 16:03	Accident Photo	Load JPG	☒
14	03/12/18 16:03	Accident Photo	Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	03/12/18 14:21	INSURANCE CERT	Load TIF	
2	03/12/18 14:21	DRIVER DL	Load JPG	☒
3	03/12/18 14:45	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18021823/UQD3S2

Date: 19/12/2018

REFERENCE

Insured/Claimant:	HO WENG FOON	Policy No:	PNPV2018-00010759	
Date of Loss:	02/12/2018	Nature of Claim:	OD	Claim No: 1201800017136

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV1916E		
Make & Model:	MERCEDES-BENZ C180, 1.6 AVANT GARDE (A)	Engine No:	27491030414647
Reg. Date:	01/09/2015 (Man. Year: 2015)	Chassis No:	WDD2050402R094938
Colour:	Grey	Odometer:	66858 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$112,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,788.00	9,400.00	1,388.00	12.87
Miscellaneous Items	35.00	0.00	35.00	100.00
Labour	2,110.00	1,540.00	570.00	27.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,933.00	10,940.00	1,993.00	15.41
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	12,933.00	10,340.00	2,593.00	20.05
+ GST 7.00/7.00% (S\$)	905.31	723.80	181.51	20.05
Nett Amount (S\$)	13,838.31	11,063.80	2,774.51	20.05

INSPECTION

Date of Assignment:	04/12/2018	Present Location:	ETHOZ Protect Pte Ltd (Bukit Batok)
Date Inspected:	05/12/2018	Inspected At:	22 TAMPINES ST 92
Estimated Period of Repair:	5.0 days	Repairer:	ETHOZ Protect Pte Ltd

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Dec 2018)

Parts: 143 MERCEDES-BENZ C180 1.6 AVANT GARDE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV1916E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent / Buckled	1,550.00 F	*1,550.00 F
2	1		*BONNET LOGO	Necessary	78.00 F	*78.00 F
3	1		*BONNET ACTUATOR RH	Activated	158.00 F	*158.00 F
4	1		*BONNET ACTUATOR LH	Activated	158.00 F	*158.00 F
5	1		*BONNET INSULATION	Not Necessary	240.00 F	*- F
6	10		*BONNET INSULATION CLIPS	Not Necessary	45.00 F	*- F
7	1		*BONNET SPRING RH	Not Necessary	45.00 F	*- F
8	1		*BONNET SPRING LH	Not Necessary	45.00 F	*- F
9	1		*FRONT HEADLAMP LH	Broken	2,300.00 F	*2,300.00 F
10	1		*HEADLAMP CONTROL UNITS LH	Cracked	450.00 F	*450.00 F
11	1		*FRONT BUMPER	Distorted	1,250.00 F	*1,250.00 F
12	10		*FRONT BUMPER CLIPS	Necessary	48.00 F	*48.00 F
13	1		*FROTN BUMPER SIDE RETAINER RH	Not Necessary	58.00 F	*- F
14	1		*FROTN BUMPER SIDE RETAINER LH	Cracked	58.00 F	*58.00 F
15	1		*FOG LAMP COVER LH	Twisted	90.00 F	*90.00 F
16	1		*FOG LAMP COVER CHROME MOULDING LH(TOP)	Scratched	78.00 F	*78.00 F
17	1		*FOG LAMP COVER CHROME MOULDING LH(BOTTOM)	Scratched	78.00 F	*78.00 F
18	1		*FRONT BUMPER SPONGE	Torn	135.00 F	*135.00 F
19	1		*FRONT BUMPER REINFORCEMENT	Serviceable	420.00 F	*- F
20	1		*FRONT FENDER LH	Buckled	850.00 F	*850.00 F
21	1		*FRONT FENDER INNER SHIELD LH(FRONT)	Torn	135.00 F	*135.00 F
22	1		*FRONT FENDER INNER SHIELD LH(REAR)	Not Necessary	135.00 F	*- F
23	10		*FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 F	*50.00 F
24	1		*FRONT PARKING SENSOR OUTER LH	Shorted	145.00 F	*145.00 F
25	1		*FRONT PARKING SENSOR INNER LH	Shorted	145.00 F	*145.00 F
26	1		*FRONT PARKING SENSOR O-RING OUTER LH	Necessary	15.00 F	*15.00 F
27	1		*FRONT PARKING SENSOR O-RING INNER LH	Necessary	15.00 F	*15.00 F
28	1		*FRONT SPORT RIM LH	Cut	950.00 F	*950.00 F
29	1		*FRONT DOOR LH	Repair	-	*- F
			(NPA)			
30	1		*FRONT SUPPORT PANEL	Repair	-	*- F
			(NPA)			
31	1		*SIDE MIRROR COVER LH	Repair	190.00 F	*- F
32	1		*SIDE MIRROR LAMP LH	Not Necessary	210.00 F	*- F
Supplementary #1						
33	1		*HEADLAMP LOWER BRACKET LH	Cracked	68.00 F	*68.00 F
34	1		*HEADLAMP WASHER PRESSOR SENSOR WITH HOSE	Torn	165.00 F	*165.00 F
35	1		*FRONT PARKING SENSOR WIRINGS	Torn	150.00 F	*150.00 F
36	1		*FRONT GRILLE BASE	Torn	145.00 F	*145.00 F
Supplementary #2						
37	1		*BONNET LOCK SENSOR RH	Shorted	68.00 F	*68.00 F
38	1		*BONNET LOCK SENSOR LH	Shorted	68.00 F	*68.00 F

F=Franchise part.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (\$\$)	10,788.00	9,400.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	COOLANT (NOT NECESSARY)	35.00	0.00
Sub Total (S\$)			35.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILIATE REPAIR	New	900.00	660.00
2	LABOUR TO SPRAY PAINT AFFECTED AREAS	New	850.00	720.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	20.00
4	TO RESET ENGINE WARNING LIGHT	New	250.00	80.00
5	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGMENT	New	80.00	60.00
Gross Labour Cost (S\$)			2,110.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >