

The Motor Claims Department  
AIG ASIA PACIFIC INSURANCE PTE LTD  
BLK 78 #08-16  
SHENTON WAY  
CHARTIS BUILDING  
SINGAPORE 079120

File No :  
Date : 19-November-2018

*Not Authored  
Resurvey B4paint*

*3 days*

Estimated cost of repair for vehicle no: SLA1101M HYUNDAI ELANTRA  
Accident involving vehicle no: SLA1101M & SGN2880G on 10-November-2018

Description	Quantity	List Price
Front bumper	1	\$ <i>Actual</i> 481.30 ✓
<i>LH</i> head lamp	1	\$ <i>Actual</i> 1,756.40 ✓
<i>LH</i> bumper focus lamp	1	\$ <i>Actual</i> 335.50 ✓
		\$ 2,573.20
	Less 10%	\$ 257.32
		\$ 2,315.88
RH bumper parking sensor	1	SN \$ <i>Ref/Scr</i> 260.00 <i>Ref</i>
To spray paint bonnet bumper and accident repair areas.	1	\$ 450.00 <i>400</i>
Labour charges to fixed and removed front bumper, head lamp, and install damaged areas.	1	\$ 380.00 <i>300</i>
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.	1	\$ 25.00 <i>20</i>
		\$ 3,430.88

T/Party: AIG ASIA PACIFIC INSURANCE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: