

ASS. REC. BY:

REP: CS/FCI/8021832/K/sd3¹²

Special Instruction:

Surveyor:

Kelvin

ASSIGNMENT (Office)

CWS

From (Person):

Jeanne Yang

of

FCI

Date/Time:

5:06pm @ 4/12/18

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 1354G

Insured:

SHD 3327Y

at Workshop m/s

Premier Automotive

Tel:

65446676

of

23 Changi South Ave 2 #03-02

Policy No:

Claim No:

D18008559 MPSTH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04/12/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

Cup

5/12/18
H.O.D. Endorsement:

Date/Time:

5:47pm @ 4/12/18

Person Contacted:

wee dek

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD1354G - NJA/INC10013792/YI DOA: 13/7/2010
	SHD3327Y - NSI/INC10006373/FD DOA: 30/3/2010
06/2/18	@ 17:39 p.m. revised PA to Jeanne Yang via email.
13/12/18	Confirmed HS \$2,550/- @ 3 days with Kelvin. (\$2,165.14 Red - 46%)

DATE: 12/12/18

Kaluh

REF: FCI

ASSIGNMENT

From: _____ Date: 5/12/18

Estimated Cost: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHD1354G

at Workshop m/s: premier Automotive

of: 23 changi south Ave 2 #03-02

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD 1354G Yr Regn: 31 May 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Hyundai I30 c.c. 1582

Colour: silver A/C: Insul / Std / NI / NA

Sp Reading: 153924 T/Radio: Insul / Std / NI / NA

Eng/No: _____

C/No: TMAP2814VHJ119077

Gen. Cond: Good / / Poor / Burnt

Steering: Inord / Jammed / Leaked / Burnt. or

Brake: Inord / Jammed / Leaked / Burnt. or

Modi: Nil / S/Rim / ST A/Rim or

Tyre Size: F: 195/65R5 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Maxxi3

Front	Rear
R/Bal. 7 mm	R/Bal. 7 mm
L/Bal. 7 mm	L/Bal. 7 mm
D.O.A. 4/2/8	D.O.I. 5/12/8

Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Bot.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
12/12/18	Check 45 \$2550 / 2 hrs. P11
RECEIVED 13 DEC 2018	

Date/Time, File Pass to? 13/12/18

1) Typist

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$) 2,550 / 4/5

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

Survey Fee: 135

Transportation: 50

Photos: 50

Others: 30

TOTAL: 265



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008559MFSH

Date: 06 December 2018

Our Ref: CS/FCI18021832/K1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1354G

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/12/2018 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>SS 4,715.14</u>
Revised Estimate Amount	: <u>SS 3,243.98</u>
"Check" Items Amount	: <u>SS</u>
Market Value	: <u>SS</u>
LTA Reimbursement Value	: <u>SS</u>
Nett Value	: <u>SS</u>

Description of Damage:

The vehicle sustained damages at the n/s body.



Comments/ Present Status:

Damages Consistent.
Repair days: 3 Days

Yours faithfully,
Kalvin Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-12-2018	Our Ref No. D18008559MFSH
Accident Date	04-12-2018	Claim Type. Third Party
Insured Vehicle	SHD3327Y	Third Party Vehicle. SHD1354G
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GOH WEE DEK	
Contact No.	65446676/ 0	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 6 December 2018 5:39 PM
To: 'Joanne Yong Lai fong'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18008559MFSH/1
Attachments: SHD 1354G - Preli Advise .pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SHD 1354G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 4 December 2018 5:51 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joaneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008559MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 05/12/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 4 December 2018 5:05 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joaneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008559MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1354G
 Previous Vehicle No.: -
 Effective Date of Ownership: 31 May 2017
 Original Regn Date: 31 May 2017
 Registration Date: 31 May 2017
 Year of Manufacture: 2016
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: TMAD281UVHJ119077
 Engine No.: D4FBGZ096064
 Engine Capacity/Power Rating: 1582 cc / -
 Maximum Power Output: 100.0 kW (134 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1496 kg
 Maximum Laden Weight: 1940 kg
 Open Market Value: S20,966.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 30 May 2025
 Minimum PARF Benefit: S8,311.00
 No. of Transfers: 0
 IU Label No.: 1050700179
 COE No.: 2017053101004246N
 COE Expiry Date: 30 May 2025
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
 Quota Premium (QP) / Prevailing Quota Premium: - / \$50,665.00
 PQP Paid: S40,532.00
 QP (Regn Cat): -
 OPC Cash Rebate Eligibility: No

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

4-Dec-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1354 G

1 pc	Rear n/s door	<i>— dent</i>			\$ 2,017.48
1 pc	Rear n/s door checker	<i>X sm</i>			\$ 53.00
1 pc	Rear n/s door module	<i>X sm</i>			\$ 507.94
2 pcs	Rear n/s door hinge @\$39.00	<i>X sm</i>			\$ 78.00
					\$ 2,656.42
			Less 20%		\$ 531.28
					\$ 2,125.14

S/NETT

1 set	n/s door sticker	<i>nee</i>			\$ 100.00 <i>—</i>
1 set	Rear n/s fender sticker	<i>nee</i>			\$ 60.00 <i>—</i>
	Sundry	<i>nee</i>			\$ 50.00 <i>20</i>
	To dismantle and refit the inner component of the rear n/s door into new shell door				\$ 150.00 <i>50</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.				\$ 180.00 <i>50</i>
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the front n/s door, rear n/s fender, rear bumper, n/s rocker panel				\$ 900.00 <i>400</i>
	To putty and spray painting on the front n/s door, rear n/s door, n/s rocker panel, rear n/s fender, rear bumper				\$ 1,000.00 <i>900</i>
	To apply rustproofing on the repaired and replaced panels				\$ 150.00 <i>50</i>
			Total		\$ 4,715.14

LKK Auto Consultants hence notify the following:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

- To resurvey before painting
- Damaged part(s) during repair
- Confirmation
- Third party survey
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Kahle 11/11/18

3 Apr.

P/P

Before print p/lt



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18021832/K1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-12-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3327Y	Veh. Inspected	SHD 1354G
Policy No.		Coverage (\$)	0.00
Claim No.	D18008559MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	04/12/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I30	c.c	1582
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	TMAD281UVHJ119077	Colour	SILVER
Odometer	153924	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	MAXXIS	7 mm
L/H Front Tyre	195/65 R15	MAXXIS	7 mm
R/H Rear Tyre	195/65 R15	MAXXIS	7 mm
L/H Rear Tyre	195/65 R15	MAXXIS	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/12/2018	Inspection Date	05/12/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1354G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR N/S DOOR	DENTED	2,017.48	2,017.48
1	REAR N/S DOOR CHECKER	SERVICEABLE	53.00	-
1	REAR N/S DOOR MODULE	SERVICEABLE	507.94	-
2	REAR N/S DOOR HINGE @\$39.00	SERVICEABLE	78.00	-
	LESS 20% DISCOUNT		-531.28	-403.50
			2,125.14	1,613.98
<u>SPECIAL NETT ITEMS</u>				
1	SET N/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	SET REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			210.00	180.00
<u>LABOUR</u>				
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF THE REAR N/S DOOR INTO NEW SHELL DOOR.		150.00	50.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING TO KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE OF THE FRONT N/S DOOR, REAR N/S FENDER, REAR BUMPER, N/S ROCKER PANEL.		900.00	400.00
	TO PUTTY AND SPRAY PAINTING ON THE FRONT N/S DOOR, REAR N/S DOOR, N/S ROCKER PANEL, REAR N/S FENDER, REAR BUMPER.		1,000.00	900.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	50.00
	-		-	-
	-		-	-
	-		-	-
			2,380.00	1,450.00
GRAND TOTAL			4,715.14	3,243.98



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,550.00
---	--	--	----------

Report Ref No. CS/FCI18021832/K1sd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.