

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Dec 2018 Edit Reg		03 Dec 2018 00:00 Edit Adj Rpt	S\$6,300.00 Edit Estimates	S\$6,300.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	ONEBUILDER PTE LTD, Co. Reg. No.: A200305666Z		
Main Claimant:	GARY TAN TRANSPORT SERVICE, Co. Reg. No.: 52859216E		
Vehicle Reg. No.:	PC6671T	Date of Loss:	30/11/2018 00:00 - :59 [13 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6976146983SG	Policy/Cover Note No.:	1800092945 (Comprehensive)
Vehicle Reg. No. (Insured):	GBH6182C	Policy No. (Claimant):	5087461199-01
		Excess:	
Repairer:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 13/12/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (07/06/2019): Alert - Adj Mandate Approved (S\$8500.00) - PC6671T - Claim Handler: Chan, Kian-M...
- AIG_SG_EXPRESS (04/06/2019): Alert - Adj Mandate Approved (S\$8000.00) - PC6671T - Claim Handler: Chan, Kian-M...
- AIG_SG (05/12/2018): Request to upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***PC6671T (6976146983SG)
[GBH6182C]**

TP

**GARY TAN TRANSPORT SERVICE
Nov 30 2018 12:00AM
[ONEBUILDER PTE LTD]
RICO 60 AUTO SERVICES PTE LTD**

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/06/19 15:05	General View	Load JPG	☒
2	03/06/19 15:05	General View	Load JPG	☒
3	03/06/19 15:05	General View	Load JPG	☒
4	03/06/19 15:05	General View	Load JPG	☒
5	03/06/19 15:05	General View	Load JPG	☒
6	03/06/19 15:05	General View	Load JPG	☒
7	03/06/19 15:05	General View	Load JPG	☒
8	03/06/19 15:05	General View	Load JPG	☒
9	03/06/19 15:05	General View	Load JPG	☒
10	03/06/19 15:05	General View	Load JPG	☒
11	03/06/19 15:05	General View	Load JPG	☒
12	03/06/19 15:05	General View	Load JPG	☒
13	03/06/19 15:05	General View	Load JPG	☒
14	03/06/19 15:05	General View	Load JPG	☒
15	03/06/19 15:05	General View	Load JPG	☒
16	03/06/19 15:05	General View	Load JPG	☒
17	03/06/19 15:05	General View	Load JPG	☒
18	03/06/19 15:05	General View	Load JPG	☒
19	03/06/19 15:05	General View	Load JPG	☒
20	03/06/19 15:05	General View	Load JPG	☒
21	03/06/19 15:05	General View	Load JPG	☒
22	03/06/19 15:05	General View	Load JPG	☒
23	03/06/19 15:05	General View	Load JPG	☒
24	03/06/19 15:05	General View	Load JPG	☒
25	03/06/19 15:05	General View	Load JPG	☒
26	03/06/19 15:05	General View	Load JPG	☒
27	03/06/19 15:05	General View	Load JPG	☒
28	03/06/19 15:05	General View	Load JPG	☒
29	03/06/19 15:05	General View	Load JPG	☒
30	03/06/19 15:05	General View	Load JPG	☒
31	03/06/19 15:05	General View	Load JPG	☒
32	03/06/19 15:05	General View	Load JPG	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	03/06/19 15:05	General View	 Load JPG	☒
34	03/06/19 15:05	General View	 Load JPG	☒
35	03/06/19 15:05	General View	 Load JPG	☒
36	03/06/19 15:05	General View	 Load JPG	☒
37	03/06/19 15:05	General View	 Load JPG	☒
38	03/06/19 15:05	General View	 Load JPG	☒
39	03/06/19 15:05	General View	 Load JPG	☒
40	03/06/19 15:05	General View	 Load JPG	☒
41	03/06/19 15:05	General View	 Load JPG	☒
42	03/06/19 15:05	General View	 Load JPG	☒
43	03/06/19 15:05	General View	 Load JPG	☒
44	03/06/19 15:05	General View	 Load JPG	☒
45	03/06/19 15:05	General View	 Load JPG	☒
46	03/06/19 15:05	General View	 Load JPG	☒
47	03/06/19 15:05	General View	 Load JPG	☒
48	03/06/19 15:05	General View	 Load JPG	☒
49	03/06/19 15:05	General View	 Load JPG	☒
50	03/06/19 15:05	General View	 Load JPG	☒
51	03/06/19 15:05	General View	 Load JPG	☒
52	03/06/19 15:05	General View	 Load JPG	☒
53	03/06/19 15:05	General View	 Load JPG	☒
54	03/06/19 15:05	General View	 Load JPG	☒
55	03/06/19 15:05	General View	 Load JPG	☒
56	03/06/19 15:05	General View	 Load JPG	☒
57	03/06/19 15:05	General View	 Load JPG	☒
58	03/06/19 15:05	General View	 Load JPG	☒
59	03/06/19 15:05	General View	 Load JPG	☒
60	03/06/19 15:05	General View	 Load JPG	☒
61	03/06/19 15:05	General View	 Load JPG	☒
62	03/06/19 15:05	General View	 Load JPG	☒
63	03/06/19 15:05	General View	 Load JPG	☒
64	03/06/19 15:05	General View	 Load JPG	☒
65	03/06/19 15:05	General View	 Load JPG	☒
66	03/06/19 15:05	General View	 Load JPG	☒
67	03/06/19 15:05	General View	 Load JPG	☒
68	03/06/19 15:05	General View	 Load JPG	☒
69	03/06/19 15:05	General View	 Load JPG	☒
70	03/06/19 15:05	General View	 Load JPG	☒
71	03/06/19 15:05	General View	 Load JPG	☒
72	03/06/19 15:05	General View	 Load JPG	☒
73	03/06/19 15:05	General View	 Load JPG	☒
74	03/06/19 15:05	General View	 Load JPG	☒
75	03/06/19 15:05	General View	 Load JPG	☒
76	03/06/19 15:05	General View	 Load JPG	☒
77	03/06/19 15:05	General View	 Load JPG	☒
78	03/06/19 15:05	General View	 Load JPG	☒
79	03/06/19 15:05	General View	 Load JPG	☒
80	03/06/19 15:05	General View	Load JPG	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	03/06/19 15:05	General View	 Load JPG	☒
82	03/06/19 15:05	General View	 Load JPG	☒
83	03/06/19 15:06	Reinspection Photo	 Load JPG	☒
84	03/06/19 15:06	Reinspection Photo	 Load JPG	☒
85	03/06/19 15:06	Reinspection Photo	 Load JPG	☒
86	03/06/19 15:06	Reinspection Photo	 Load JPG	☒
87	03/06/19 15:06	Reinspection Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/18 18:00	EMAIL FROM AIG DD 03122018	 Load PDF	
2	04/12/18 18:00	NOTICE	 Load PDF	
3	07/12/18 08:51	TP ESTIMATE- MARKED	 Load PDF	
4	07/12/18 08:51	TP GIA REPORT	 Load PDF	
5	12/03/19 17:40	GIA LTA SEARCH	 Load PDF	
6	12/03/19 17:40	RENTAL RECEIPT	 Load PDF	
7	25/06/19 14:20	LETTER TO OI	 Load PDF	
8	25/06/19 14:20	AUTHORISATION TO ACT	 Load PDF	
9	25/06/19 14:20	RELEASE VOUCHER	 Load PDF	
10	25/06/19 14:20	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	05/12/18 10:55	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBH6182C (Insd veh)	Model:	TOYOTA HIACE 3.0 (A)
	PC6671T (TP veh)		
Date of Accident:	30/11/2018		

Global Sum Settlement	:	☒ Yes	☐ No	
Repair Estimate	:	\$		26,255.55
Final Repair Cost	:	\$		8,500.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		9 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (GLOBAL SUM)	:	\$		8,500.00

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	RICO 60 AUTO SERVICES PTE. LTD.	: \$	8,500.00
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

25 Jun
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18021834/UJB3S2

Date: 25/06/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800092945
Claimant Vehicle No :	PC6671T	Insured Vehicle No :	GBH6182C
Date of Loss:	30/11/2018	Nature of Claim:	TP
		Claim No:	6976146983SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC6671T	Engine No:	1KD2657603
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	KDH2118007479
Reg. Date:	06/10/2017 (Man. Year: 2016)	Odometer:	75169 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,447.90	5,398.35	12,049.55	69.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,090.00	2,340.00	4,750.00	67.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,537.90	7,738.35	16,799.55	68.46
Approved Total (Overridden) (S\$)		6,300.00		
(S\$)	24,537.90	6,300.00	18,237.90	74.33
+ GST 7.00/7.00% (S\$)	1,717.65	441.00	1,276.65	74.33
Nett Amount (S\$)	26,255.55	6,741.00	19,514.55	74.33
+ Car Rental (9.0 x S\$200.00/day) (S\$)		1,800.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		8,577.45		
Global Sum Settlement (S\$)		8,500.00		

INSPECTION

Date of Assignment: 03/12/2018

Date Inspected: 05/12/2018 Inspected At:

RICO 60 AUTO SERVICES PTE LTD (HQ)
8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	549.60 FL	*- FL
2	1		*FRONT BONNET LOGO	Necessary	54.90 FL	*54.90 FL
3	2		*FRONT BONNET HINGE L+R	Not Necessary	242.80 FL	*- FL
4	1		*FRONT BONNET RUBBER	Not Necessary	108.40 FL	*- FL
5	1		*FRONT BONNET LOCK	Not Necessary	135.40 FL	*- FL
6	1		*FRONT GRILLE ASSY	Not Necessary	481.40 FL	*- FL
7	1		*FRONT BUMPER	Distorted	681.40 FL	*681.40 FL
8	1		*FRONT BUMPER BEAM	Distorted	289.90 FL	*289.90 FL
9	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	381.40 FL	*- FL
10	1		*FRONT BUMPER RETAINER L+R	O/s Cracked	262.40 FL	*131.20 FL
11	2		*FRONT BUMPER BRACKET L+R	Not Necessary	232.60 FL	*- FL
12	1		*FRONT BUMPER TOWING COVER	Not Necessary	41.20 FL	*- FL
13	2		*FRONT BUMPER FOG LAMP	Not Necessary	282.60 FL	*- FL
14	1		*FRONT BUMPER FOG LAMP GARNISH	Scratched	134.20 FL	*134.20 FL
15	1		*FRONT HEADLAMP L+R	O/s Broken	1,562.40 FL	*781.40 FL
16	1		*FRONT HEADLAMP PANEL RH	Repair	289.40 FL	*- FL
17	1		*SIDE PANEL RH	Buckled	362.40 FL	*362.40 FL
18	1		*FRONT SUPPORT PANEL	Repair	482.40 FL	*- FL
19	1		*FRONT BRACE PANEL	Not Necessary	161.20 FL	*- FL
20	1		*WIRE HARNESS	Not Necessary	338.50 FL	*- FL
21	1		*AIR CON CONDENSER	Not Necessary	1,012.40 FL	*- FL
22	1		*RADIATOR	Not Necessary	1,514.50 FL	*- FL
23	1		*RADIATOR SPARE TANK	Not Necessary	387.40 FL	*- FL
24	1		*TURBO COOLER	Not Necessary	2,142.00 FL	*- FL
25	1		*WASHER TANK	Not Necessary	161.40 FL	*- FL
26	1		*WASHER TANK MOTOR	Not Necessary	162.60 FL	*- FL
27	1		*FRONT DOOR RH	Dented / Bent	1,683.40 FL	*1,683.40 FL
28	2		*FRONT DOOR HINGE UP AND DOWN	Not Necessary	248.30 FL	*- FL
29	1		*FRONT DOOR CHECKER	Not Necessary	164.30 FL	*- FL
30	1		*FRONT DOOR WINDOW MOULDING	Not Necessary	124.30 FL	*- FL
31	1		*FRONT DOOR LOWER STEP PANEL	Repair	246.50 FL	*- FL
32	1		*FRONT DOOR LOWER STEP PANEL GARNISH	Torn	123.40 FL	*123.40 FL
33	1		*REAR FENDER RH	Badly Dented	1,795.90 FL	*1,455.10 FL
34	1		*REAR FENDER GLASS MOULDING RH	Not Necessary	135.80 FL	*- FL
35	1		*REAR FENDER DOOR RAILING RH	Bent	340.50 FL	*340.50 FL
36	1		*RADIATOR COOLER	Not Necessary	120.00 FS	*- FS
37	10		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
38	1		*FRONT BUMPER LOWER SPOILER	Cracked	4,000.00 FS	*800.00 FS
39	1		*REAR FENDER SEALANT	Not Necessary	120.00 FS	*- FS
40	1		*REAR FENDER GLASS SEALANT	Necessary	120.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	21,777.20	6,907.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,329.30	1,509.45
Total Parts (\$\$)	17,447.90	5,398.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RNR ACCIDENT DAMAGE PARTS, CUT / WELD, KNOCK & REALIGN.	New	3,000.00	1,100.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.	New	3,000.00	1,000.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA.	New	120.00	80.00
4	TO RNR FRONT DOOR MECHANISM.	New	200.00	60.00
5	TO RNR A/C CONDENSER ASSY AND REFILL GAS.	New	250.00	0.00
6	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS.	New	150.00	20.00
7	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD.	New	250.00	0.00
8	TO RNR REAR FENDER DOOR RAILING AND CHECK FUNCTION.	New	120.00	80.00
Gross Labour Cost (\$\$)			7,090.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >