

# AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

ROHANA BTE AHMAD

c/o 46 Lentor Plain

Singapore 786548

*Not Authorized*  
*11 Rm @ ?*  
*Resurvey After Paint*  
*Today*

Date: 03/12/2018

| QUANTITY                                      | PARTICULARS                         | AMOUNT (\$) |
|-----------------------------------------------|-------------------------------------|-------------|
| <b>RE : TOYOTA COROLLA ALTIS / SJR 6963 T</b> |                                     |             |
| 1 pc                                          | rear boot lid                       | 688.00 ✓    |
| 1 pc                                          | rear boot emblem ' 1.6 '            | 56.80 ✓     |
| 1 pc                                          | rear boot emblem ' ALTIS '          | 57.40 ✓     |
| 1 pc                                          | rear boot emblem ' COROLLA '        | 61.50 ✓     |
| 1 pc                                          | rear boot emblem ' LOGO '           | 75.40 ✓     |
| 2 pcs                                         | rear boot hinge @ 192.40            | 384.80 X    |
| 1 pc                                          | rear boot lock                      | 187.50 ✓    |
| 1 pc                                          | rear boot lock catch                | 55.30 X     |
| 2 pcs                                         | rear boot reflector @ 376.30        | 752.60 ✓    |
| 1 pc                                          | rear boot weatherstrip              | 180.70 50%  |
| 2 pcs                                         | rear number plate lamp @ 198.30     | 396.60 X    |
| 1 pc                                          | rear bumper                         | 597.40 ✓    |
| 2 pcs                                         | rear bumper bracket @ 83.40         | 166.80 ?    |
| 4 pcs                                         | rear bumper clips @ 3.00            | 12.00 ✓     |
| 1 pc                                          | rear bumper foam                    | 372.30 ✓    |
| 1 pc                                          | rear bumper reinforcement bar       | 165.40 ?    |
| 2 pcs                                         | rear bumper side retainer @ 73.60   | 147.20 ✓    |
| 2 pcs                                         | rear bumper corner retainer @ 59.70 | 119.40 X    |
| 2 pcs                                         | rear bumper reflector @ 126.40      | 252.80 X    |
| 1 pc                                          | rear end panel                      | 476.90 ✓    |
| 1 pc                                          | rear end panel garnish              | 285.00 ✓    |
| 2 pcs                                         | rear fender inner trim @ 264.90     | 529.80 X    |
| Sub-total                                     |                                     | 6,021.60    |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

|       |                                                                                                               |                |                                 |              |
|-------|---------------------------------------------------------------------------------------------------------------|----------------|---------------------------------|--------------|
|       | Balance brought forward                                                                                       |                | 6,021.60                        |              |
| 1 pc  | rear spare tyre board                                                                                         |                | <i>Sn</i> 258.60                | <i>X</i>     |
| 1 pc  | rear exhaust silencer                                                                                         |                | <i>R</i> 963.80                 | <i>X</i>     |
| 2 pcs | rear tail lamp assy                                                                                           | <i>N/S cmf</i> | <i>@ 568.70</i> 1,137.40        | <i>✓</i>     |
| 2 pcs | rear tail lamp housing panel                                                                                  |                | <i>@ 275.80</i> <i>R</i> 551.60 | <i>X</i>     |
|       |                                                                                                               | sub-total      | 8,933.00                        |              |
|       |                                                                                                               | less 25%       | 2,233.25                        |              |
|       |                                                                                                               | sub-total      | 6,699.75                        |              |
| 1 pc  | number plate                                                                                                  | s.nett         | <i>Sn</i> 35.00                 | <i>X</i>     |
| 1 set | reverse sensor                                                                                                | s.nett         | <i>Sn</i> 220.00                | <i>2001.</i> |
| 1 set | sundries ( clips, bolts, nuts etc.)                                                                           | s.nett         | <i>nn</i> 50.00                 | <i>X</i>     |
|       | To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas. |                | <i>Scal</i> 1,200.00            |              |
|       | To check wiring system.                                                                                       |                | <i>201</i> 40.00                |              |
|       | To spray painting on affected areas.                                                                          |                | <i>Scal</i> 1,200.00            |              |
|       | To remove trimming to enable repair.                                                                          |                | <i>601</i> 100.00               |              |
|       | To carry out exhaust works.                                                                                   |                | <i>nn</i> 120.00                | <i>X</i>     |
|       | To remove and replace reverser sensor.                                                                        |                | <i>501</i> 80.00                |              |
|       | To apply rust proofing.                                                                                       |                | <i>601</i> 120.00               |              |
|       | To apply waterproof sealant on weilded panels.                                                                |                | <i>301</i> 120.00               |              |
|       |                                                                                                               | <b>Total</b>   | <b>9,984.75</b>                 |              |