

15/02/18

INS. CASE OWNER:

CC 4/AIG1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP: 97766655

D.O.A:

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

(\$ 80 x 5 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

Global Sum SS: 3,900.00

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

KANG AUTO ENGINEERING ME LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

X

Payee 3: (Strike if N.A.)

SS

Name 3:

X

COPY SENT

Sanjour

REF:

ALG

ASSIGNMENT

From

Date:

5/12/2018

Estimated Cost:

OD/TP WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

GBD 2021G

at Workshop n/s

Kang Auto

of 160 Sin Ming Drive #02-16

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBD 2021G

Yr Regn:

07 14

Type: M.Car / M.Cycle / Bus / Van / Corry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Dmp

C.C.

2982

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

155613

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

K04231

8015888

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: B.5

195R 15X8

W: 164

155R12X8(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

22

mm

L/Bal.

9

mm

L/Bal.

22

mm

D.O.A.

1/12/18

D.O.I.

5/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/12 File pcn to Customer

16-1-19 45 \$3,500

R(\$4,747.38/58%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + R. \$

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18021837/jb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 04-12-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SFM 9300K	Veh. Inspected	GBD 2021G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/12/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/12/2018	Inspection Date	
Survey held at	KANG AUTO ENGINEERING PTE LTD 160 SIN MING DRIVE #02-16 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

- Pre repair inspection request - GBD2021G VS SFM9300K (OI) DOA 01/12/2018

From: Chan, Yoke Shi
To: ASSIGNMENTS@LKKAUTO.COM, Admin A
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Azlan, Syazairdina, Hor, Yinrul
Sent: 4/12/2018 2:00:03 PM
Attachments:  tmpEAC.TIF

Hi,

Please refer to the enclosed request from Kang Auto engineering Pte Ltd

Claim no : 9059429119SG003
Case Owner : CHAN KIAN MENG

If you have any queries/concerns, please let us know.
Kindly assist to assign Mr Kenneth as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

yokeshi.chan@aig.com | www.aig.com

From: kangauto@singnet.com.sg [mailto:kangauto@singnet.com.sg]
Sent: Tuesday, December 04, 2018 1:43 PM
To: Chan, Yoke Shi
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Azlan, Syazairdina, Hor, Yinrul
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFM9300K AND GBD2021G ON 01/12/2018

Chan

Please assign LKK Auto - Mr Kenneth for the survey with thanks

Kang Auto engineering Pte Ltd

May Ang

From: Chan, Yoke Shi
Sent: Tue, 4 Dec 2018 05:19:02 +0000
To: kangauto@singnet.com.sg
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Azlan, Syazairdina, Hor, Yinrul
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFM9300K AND GBD2021G ON 01/12/2018

Without Prejudice

Your Reference : GBD2021G
Our Reference : 9059429119SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd

202pm @ 4/12/2018
penon May
vehicle In

Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you,

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

yokeshi.chan@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Kj

KANG**AUTO ENGINEERING PTE LTD****Sin Ming Auto City**

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015

Email: kangauto@singnet.com.sg



M/S 3S SOLID SURFACE PTE LTD
18 SUNGEI KADUT
STREET 6
SINGAPORE 728863

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP18/12/1125
VEHICLE NO : GBD2021G
MAKE/MODEL : TOY. DYNA
DATE OF ACCIDENT : 01.12.18

Not Attributed
C/L 8350 dr
Resurvey After Paint

5 days

REVISE

- 1 PC TAIL BOARD ALUMINIUM
1 PC TAILGATE
1 PC TAILGATE SAFETY BAR
2 PCS TAILGATE HINGES
2 PCS TAILGATE SIDE HINGES
1 PC TAILLAMP ASSY (LH)
1 PC TAILLAMP REFLECTOR (LH)
1 PC TOOL BOX
1 PC SPARE TYRE BRACKETS
1 PC STEP PANEL
1 PC REAR LEFT MUGFLAP

1588.00

SS	1,692.70	✓	805.00
R	2512.50	✓	
NH	1203.00	X	
\$ 79.80 EA	159.60	✓	
\$ 90.80 EA	181.60	X	
CM	195.60	✓	
JL	260.60	X	
B	580.90	✓	
R	210.00	X	
B	205.00	✓	
AN	95.00	✓	
SS	7,296.50		
LESS 25%	1,824.13		
SS	5,472.38		

- 1 PC COMPANY STICKERS REPASTING ON DAMAGE
1 PC TAILGATE 70 KM/H STICKER
1 PC TAILGATE 'DYNA' STICKER
1 PC TAILGATE '6 PAX' STICKER
1 PC REAR NUMBER PLATE

SS	280.00	S'NETT	805.00
SS	15.00	✓	
SS	18.00	✓	
SS	12.00	✓	
CM	40.00	✓	

TO REMOVE & REFIX NEW TAILGATE
TO APPLY RUST PROOFING ON REPAIRED PANELS
TO PUTTY AND SPRAY PAINT
LABOUR CHARGE

SS	250.00	X	
	360.00	601	
	800.00	6001	
	1,000.00	7001	
SS	8,247.38		

YOURS FAITHFULLY,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City



160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg

M/S 3S SOLID SURFACE PTE LTD
18 SUNGEI KADUT
STREET 6
SINGAPORE 728863

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP18/12/1125
VEHICLE NO : GBD2021G
MAKE/MODEL : TOY. DYNA
DATE OF ACCIDENT : 01.12.18

*Not Ashore
C/L 8?
Resurvey After Paint*

5 days

REVISE

- 1 PC TAIL BOARD ALUMINIUM
- 1 PC TAILGATE
- 1 PC TAILGATE SAFETY BAR
- 2 PCS TAILGATE HINGES
- 2 PCS TAILGATE SIDE HINGES
- 1 PC TAILLAMP ASSY (LH)
- 1 PC TAILLAMP REFLECTOR (LH)
- 1 PC TOOL BOX
- 1 PC SPARE TYRE BRACKETS
- 1 PC STEP PANEL
- 1 PC REAR LEFT MUGFLAP

<i>Me</i>	S\$	<i>in</i>	1,692.70	<i>✓</i>
		<i>R</i>	2512.50	<i>✓</i>
		<i>NH</i>	1203.00	<i>X</i>
\$	79.80	EA	<i>dis</i> 159.60	<i>✓</i>
\$	90.80	EA	<i>R</i> 181.60	<i>X</i>
		<i>CM</i>	195.60	<i>✓</i>
		<i>in</i>	260.60	<i>X</i>
		<i>R</i>	580.90	<i>✓</i>
			210.00	<i>?</i>
		<i>R</i>	205.00	<i>✓</i>
		<i>An</i>	95.00	<i>✓</i>
	S\$		7,296.50	
	LESS 25%		1,824.13	
	S\$		5,472.38	

- 1 PC COMPANY STICKERS REPASTING ON DAMAGE
- 1 PC TAILGATE 70 KM/H STICKER
- 1 PC TAILGATE 'DYNA' STICKER
- 1 PC TAILGATE '6 PAX' STICKER
- 1 PC REAR NUMBER PLATE

<i>Me</i>	280.00	S'NETT	<i>Sum</i>
<i>Me</i>	15.00		
<i>Me</i>	18.00		
<i>Me</i>	12.00		
<i>CM</i>	40.00		

TO REMOVE & REFIX NEW TAILGATE
TO APPLY RUST PROOFING ON REPAIRED PANELS
TO PUTTY AND SPRAY PAINT
LABOUR CHARGE

S\$	250.00	<i>X</i>
	360.00	<i>bol</i>
	800.00	<i>bol</i>
	1,000.00	<i>Foot</i>
S\$	8,247.38	

YOURS FAITHFULLY,

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City



160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg

M/S **AIG Asia Pacific Insurance Pte Ltd**
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attn: Motor Claims Dept

Date : 15/01/2019

DIRECT SETTLEMENT
Your Insured: SFM9300K
Our Ref: TP18/12/1125

LETTER OF DEMAND

RE: ACCIDENT INVOLVING VEHICLE GBD2021G & SFM9300K ON 01.12.2018
ALONG SELETAR WEST LINK TOWARDS YISHUN AVENUE 1.

Details as follows:-

Cost of Repair	\$ 3,500.00
Loss of Use (\$80 X 5Days)	\$ 400.00
LTA Search Fees	\$ 7.45

\$ 3,907.45

SGD THREE THOUSAND NIN HUNDRED SEVEN AND CENTS FORTY-FIVE ONLY.

YOURS FAITHFULLY,


KANG AUTO ENGINEERING PTE LTD

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Thursday, 24 January 2019 6:28 PM
To: 'ngcecellia@yahoo.com'; 'ngcecellia@yahoo.com'
Cc: Admin A
Subject: ACCIDENT INVOLVING SFM 9300K AND GBD 2021G ON 01/12/2018

Our ref: **CC4/AIG18021837/Kjb3**

NG BEE HOON

Policy Holder

Dear Sir/Madam,

ACCIDENT INVOLVING SFM 9300K AND GBD 2021G ON 01/12/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us.

We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Your Insured **SFM9300K**

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attn: Motor Claims Dept

Dear Sirs/Mdm

LETTER OF AUTHORITY

RE: ACCIDENT INVOLVING VEHICLE GBD2021G & SFM9300K ON 01.12.2018
ALONG SELETAR WEST LINK TOWARDS YISHUN AVENUE 1.

We, 3S Solid Surface Pte Ltd , owner of Motor Vehicle No. GBD2021G at all material times of the above accident, hereby irrevocably authorise you to pay my workshop, **Kang Auto Engineering Pte Ltd** , the compensation sum for my loss and damage suffered in the above accident involving your insured motor vehicle no. **SFM9300K**.

Yours Sincerely,



Signed without prejudice for
any claim for personal injury

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, KANG AUTO ENGINEERING PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,900.00 (Global Sum) for vehicle no. GBD 2021G that was damaged pursuant to the accident which occurred on 01/12/2018 (date) along SELETAR WEST LINK (location) involving vehicle no/s SFM 9300K. This is pursuant to the inspection conducted on 05/12/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner 3S SOLID SURFACE PTE LTD ("the third party claimant") of vehicle no. GBD 2021G make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GBD 2021G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 30th (day) of Jan (month) **2019** (year)



Signed by appointed surveyor

Kang Auto Engineering Pte Ltd
Sin Ming Auto City, Sin Ming Drive
#02-16 Singapore 575722
Tel: 6556 0103 (3 Lines) Fax: 6556 1015
kangauto@singnet.com.sg

Signed by "the workshop" (with chop)



707

INVOICE : 00002691

Bill To :

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120

Our Ref: : TP18/12/1125

Date : 30/1/2019

Vehicle No : GBD2021G

Make/Model No : Toy Hiace

Date of Accident : 1/12/2018

Date Discharge : 7/12/2018

Attn: Motor Claims Dept

Tel : 64191891 Fax : 683574716

Description	Quantity	Unit Price	Amount
Cost of Repair (All-In) Your Reference: SFM9300K	1 1	\$3,900.00	\$3,900.00
Total Payable			\$3,900.00

Goods sold are not returnable.

Specialised in Motor Insurance Claims. Repairs all Types of Motor Cars.
All Vicom Inspection Service, Sourcing "Cheaper Premium" for your vehicle.

Received the above in good order and condition

YOURS FAITHFULLY


KANG AUTO ENGINEERING PTE LTD

Kang Auto Engineering Pte Ltd

Sin Ming Auto City 160 Sin Ming Drive #02-16 Singapore 575722 Tel: 65560103 (3Lines) Fax: 6556 1015
Email: kangauto@singnet.com.sg

Co. Reg. No: 200617880K

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 03 Dec 2018 / 14:41:37

Receipt Date/Time : 03 Dec 2018 / 14:41:37

Tax Invoice/Receipt

Receipt No. : ITNET-00000-181203-002017

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SFM9300K				
As at 01 Dec 2018/16:30:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SFM9300K Enquiry Fee 20181203144103493644	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
xxxxxxxxxxxx0459		Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Dec 2018 Edit Reg		04 Dec 2018 00:00 Edit Adj Rpt	S\$3,500.00 Edit Estimates	S\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured: **NG BEE HOON**, ID: S1535597B

Main Claimant: **3S SOLID SURFACE PTE LTD**, Co. Reg. No.: 200722216Z

Vehicle Reg. No.: GBD2021G	Date of Loss: 01/12/2018 16:00 - :59 [52 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type: TP / 9059429119SG	Policy/Cover Note No.: 1700021056 (Comprehensive) Coverage: 30/06/2018 - 29/06/2019
Vehicle Reg. No. (Insured): SFM9300K	Policy No. (Claimant):
Excess:	

Repairer: **Kang Auto Engineering Pte Ltd ()** 160 Sin Ming Drive, #02-16, Sin Ming AutoCity, 575722 Sin Ming - Tel:

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (Express)** - Tel: 65-6419-3000 ... [Handled by **Chan, Kian-Meng**]
Kianmeng.Chan1@aig.com

Claimant's Insurer: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **KENNETH KONG**] ... **[Final Rpt due 13/12/2018]**

[View All](#)
[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBD2021G (9059429119SG)
[SFM9300K]
TP
3S SOLID SURFACE PTE LTD
Dec 1 2018 4:00PM
[NG BEE HOON]
Kang Auto Engineering Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#) |
 [Upload Video](#) |
 [Upload Audio](#)

View View in Browser

Video 1 per page ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/01/19 19:04	VIDEO FROM TP	Load MP4	<input type="checkbox"/>

Letters/Correspondences 1 per page ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	<input type="checkbox"/>

Photos/Images 3 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
2	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
3	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
4	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
5	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
6	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
7	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
8	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
9	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
10	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
11	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
12	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
13	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
14	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
15	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
16	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
17	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
18	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
19	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
20	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
21	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
22	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>
23	28/01/19 19:05	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation 1 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/18 18:21	TP EST & GIA REPORT	Load PDF	<input type="checkbox"/>
2	04/12/18 18:21	EMAIL FROM AIG DD 04122018	Load PDF	<input type="checkbox"/>
3	07/12/18 10:17	TP ESTIMATE- MARKED	Load PDF	<input type="checkbox"/>
4	11/02/19 15:07	WORKSHOP INVOICE	Load PDF	<input type="checkbox"/>
5	11/02/19 15:07	AUTHORISATION TO ACT FORM	Load PDF	<input type="checkbox"/>
6	11/02/19 15:07	Release Voucher	Load PDF	<input type="checkbox"/>

Video			1 per page	<input type="checkbox"/>
No	Finalized On		Thumbnail	Print
7	11/02/19 15:07	LKK Auto Consultants Pte Ltd (HQ)		Load PDF
8	11/02/19 15:07	LTA SEARCH		Load PDF
		LETTER TO OI	Thumbnail	Print
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Load PDF
1	05/12/18 09:47	OI GIA REPORT		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SFM9300K (Insd veh)	Model:	TOYOTA DYNA 1.5T 3.0 (A)
	GBD2021G (TP veh)		
Date of Accident:	01/12/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	8,247.37
Final Repair Cost	:	\$	3,900.00
Loss of Use	:	\$	5.00 days at \$80.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	3,900.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kang Auto Engineering Pte Ltd	:	\$ 3,900.00
2)		:	\$
3)		:	\$

HUEY YON

11 Feb
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18021837/KJB3N2
Date: 12/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700021056
 Claimant Vehicle No: GBD2021G Insured Vehicle No: SFM9300K
 Date of Loss: 01/12/2018 Nature of Claim: TP Claim No: 9059429119SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD2021G**
 Make & Model: TOYOTA DYNA 1.5T, 3.0 (A) Engine No: 1KD2405252
 Reg. Date: 31/07/2014 (Man. Year: 2014) Chassis No: KDY2318015888
 Colour: Silver Odometer: 155613 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 155 R12X8 (D)
 Front Left Side: Bridgestone 9 mm Rear Left Side: West Lake 2/2 mm
 Front Right Side: Bridgestone 9 mm Rear Right Side: West Lake 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,837.37	3,023.22	2,814.15	48.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,410.00	1,360.00	1,050.00	43.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,247.37	4,383.22	3,864.15	46.85
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	8,247.37	3,500.00	4,747.37	57.56
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,907.45		
Global Sum Settlement (S\$)		3,900.00		

INSPECTION

Date of Assignment: 04/12/2018

Date Inspected: 05/12/2018 Inspected At:

Kang Auto Engineering Pte Ltd
160 Sin Ming Drive, #02-16, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAIL BOARD ALUMINIUM	Necessary	1,269.52 FS	*800.00 FS
2	1	*TAILGATE	Bent	2,512.50 FL	*1,588.00 FL
3	1	*TAILGATE SAFETY BAR	No such part	1,203.00 FL	*- FL
4	2	*TAILGATE HINGES	Distorted (1 PCS ONLY)	159.60 FL	*79.80 FL
5	2	*TAILGATE SIDE HINGES	Repair	181.60 FL	*- FL
6	1	*TAILLAMP ASSY (LH)	Cracked	195.60 FL	*195.60 FL
7	1	*TAILLAMP REFLECTOR (LH)	Serviceable	260.60 FL	*- FL
8	1	*TOOL BOX	Bent	580.90 FL	*580.90 FL
9	1	*SPARE TYRE BRACKETS	Repair	210.00 FL	*- FL
10	1	*STEP PANEL	Bent	205.00 FL	*205.00 FL
11	1	*REAR LEFT MUGFLAP	Buckled	95.00 FL	*95.00 FL
12	1	*COMPANY STICKERS REPASTING ON DAMAGE	Necessary	280.00 FS	*80.00 FS
13	1	*TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
14	1	*TAILGATE DYNA STICKER	Necessary	18.00 FS	*18.00 FS
15	1	*TAILGATE 6PAX STICKER	Necessary	12.00 FS	*12.00 FS
16	1	*REAR NUMBER PLATE	Cracked	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,238.32	3,709.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,400.95	686.08
Total Parts (\$\$)	5,837.37	3,023.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO APPLY RUST PROOFING ON REPAIRED PANELS	New	360.00	60.00
2	TO PUTTY AND SPRAY PAINT	New	800.00	600.00
3	LABOUR CHARGE }	New	1,000.00	700.00
4	TO REMOVE & REFIX NEW TAILGATE }	New	250.00	0.00
Gross Labour Cost (\$\$)			2,410.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >