



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

03/12/2018

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TPA16.

Xiao Tony SJNFEAJ11U1721587.

Accident date: 01/12/2018

Estimated repair cost for vehicle no: SLK7583M NISSAN QASHQAI 1.2 A '17

CHASSIS: SJNFEAJ11U1721587

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Bonnet <i>dent</i>		\$961.40 ✓
2	2	Front Bonnet Hinge	\$56.10	\$112.20 x
3	1	Front Bonnet Lock		\$236.60 x
4	1	Front Bonnet Inner Rubber <i>HP</i>		\$85.10 x
5	1	Front Bonnet Insulator <i>new</i>		\$185.50 x
6	8	Front Bonnet Insulator Clip	\$6.50	\$52.00 x
7	2	Front Head Lamp <i>cracked</i>	\$2,960.00	\$5,920.00 1538
8	2	Front Head Lamp Lower Bracket <i>new</i>	\$38.10	\$76.20 x
9	1	Front Grille <i>cracked</i>		\$498.30 ✓
10	8	Front Grille Clip <i>new</i>	\$6.50	\$52.00 20
11	1	Front Grille Emblem Logo <i>new</i>		\$64.60 ✓
12	1	Front Grille Chrome Moulding <i>new</i>		\$285.00 ✓
13	1	Front Bumper <i>dent</i>		\$614.60 ✓
14	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30
15	2	Front Bumper Side Retainer <i>new</i>	\$65.20	\$130.40 ✓
16	1	Front Bumper Number Plate <i>cracked</i>		\$50.00 ✓
17	1	Front Bumper Towing Cover <i>new</i>		\$21.00 x
18	1	Front Bumper Inner Sponge <i>cracked</i>		\$195.70 ✓
19	1	Front Bumper Reinforcement <i>best</i>	134.30	\$675.40 35760
20	1	Front Bumper Reinforcement Bracket <i>best</i>	134.30	\$268.60 ✓
21	1	Front Bumper Lower Reinforcement Cover		\$264.10 x
22	2	Front Bumper Centre Side Inner Bracket		\$123.70 x
23	2	Front Bumper Fog Lamp	\$323.70	\$647.40 x
24	2	Front Bumper Fog Lamp Cover	\$74.70	\$149.40 x
25	2	Front Fender <i>new</i>	\$622.70	\$1,245.40 x
26	2	Front Fender Protector <i>new</i>	\$483.00	\$966.00 x
27	1	Front Support Panel <i>repair</i>		\$617.50 x
28	1	Front Support Panel Top Cover <i>dent</i>		\$125.10 ✓
29	8	Front Support Panel Top Cover Clip <i>new</i>	\$6.50	\$52.00 20

30	1	Rear Boot Lid <i>Dented</i>		\$2,936.80	✓
31	2	Rear Boot Lid Hinge <i>2 New</i>	\$65.30	\$130.60	X
32	2	Rear Boot Lid Shock Absorber <i>2 New</i>	\$209.80	\$419.60	X
33	1	Rear Boot Lid Emblem Logo <i>2 New</i>		\$66.40	✓
34	1	Rear Boot Lid Qashqai Logo <i>2 New</i>		\$87.00	✓
35	2	Rear Boot Lid Side Reflector <i>cut</i>	\$315.90	\$631.80	✓
36	1	Rear Boot Lid Inner Lock <i>2 New</i>		\$267.70	✓
37	1	Rear Boot Lid Inner Rubber <i>New</i>		\$158.70	X
38	1	Rear Boot Lid Inner Trim Board <i>New</i>		\$416.50	X
39	1	Rear Boot Lid Windscreen Moulding <i>2 New</i>		\$125.00	✓
40	1	Rear Boot Lid Windscreen Seal		\$60.00	✓
41	1	Rear Boot Lid Camera <i>New</i>		\$680.00	X
42	2	Rear Tail Lamp <i>cut</i>	\$323.70	\$647.40	✓
43	2	Rear Tail Lamp Panel <i>Repair</i>	\$218.90	\$437.80	X
44	1	Rear Bumper <i>Deformed</i>		\$717.00	✓
45	10	Rear Bumper Clip <i>New</i>	\$6.50	\$65.00	30
46	2	Rear Bumper Side Retainer <i>New</i>	\$55.20	\$110.40	✓
47	2	Rear Bumper Side Reflector <i>2 New</i>	\$63.30	\$126.60	63.30
48	1	Rear Bumper Towing Cover <i>Missing</i>		\$16.80	✓
49	1	Rear Bumper Inner Sponge <i>cracked</i>		\$183.80	✓
50	1	Rear Bumper Reinforcement <i>Bent</i>		\$619.20	✓
51	2	Rear Fender Protector <i>2 New</i>	\$483.00	\$966.00	483
52	2	Rear Fender Inner Trim Board <i>New</i>	\$361.70	\$723.40	X
53	1	Rear End Panel <i>Dented</i>		\$582.60	✓
54	1	Rear End Panel Top Garnish <i>Deformed</i>		\$185.00	✓
55	1	Rear Spare Tyre Panel <i>Repair</i>		\$1,680.00	X
56	1	Rear Spare Tyre Panel Top Cover <i>New</i>		\$294.70	X
57	1	Rear Spare Tyre Panel Top Sponge <i>Cracked</i>		\$504.00	325
58	1	Rear Exhaust <i>Dented</i>		\$825.90	✓
59	1	Rear Exhaust Aluminium Cover <i>New</i>		\$244.40	X
60	1	Rear Centre Exhaust <i>New</i>		\$829.10	X
61	2	Rear Bumper Reinforcement Bracket <i>Bent</i>	126	252	✓
			Subtotal :-	\$30,848.50	

14375.40

1293786

S/n	Qty	Items / Special Nett	U/price	Amount
61	1	Front Air-Con Condenser Bent.		\$658.20 ✓
62	1	Front Air-Con Section Pipe 2nd		\$238.60 x
63	1	Front Air-Con Discharge Pipe 1st		\$242.20 x
64	1	Front Radiator Bent.		\$687.40 ✓
65	1	Front Radiator Fan Motor Assy Cracked.		\$621.70 ✓
66	1	Front Radiator Spare Tank ?		\$123.50 x
67	1	Front Radiator Top Bracket 1st new		\$225.00 x
68	1	Front Wiper Tank		\$162.50 x
69	1	Front Air Cleaner Air Duct 2nd		\$135.90 ✓
70	1	Front Intercooler Dented		\$2,121.60 x 1850.
71	1	Front Oil Coolant Assy Dented		\$850.40 (2nd/SN)
72	1	Rear End Panel Lock Sensor new		\$169.90 x
73	1	Rear Spare Tyre Panel & End Panel Sealant Not new		\$450.00 x
74	1	Rear Exhaust		\$825.90 x
75	1	Rear Exhaust Aluminium Cover } Repeated		\$244.40 x
76	1	Rear Centre Exhaust		\$829.10 x

Subtotal :- \$8,586.30

3953.20

S.N: 1850

3557.88

Labour charges

To remove & refit air-con condenser, radiator, fan motor
& top up gas

~~\$380.00~~ 120.

To remove & refit cushion & trim board

~~\$280.00~~ 80

To remove & refit rear & centre exhaust

~~\$380.00~~ 80

To remove & refit reverse sensor

~~\$100.00~~ 50

To remove & refit rear camera

~~\$180.00~~ 50

To remove & refit rear windscreen

\$120.00 ✓

Gum

\$50.00 ✓

Towing fee

~~\$100.00~~ 60

To check wiring

3630

~~\$100.00~~ 60

Tuff kote

~~\$150.00~~ 60

Panel beating

~~\$2,800.00~~ 1500

Spray painting

~~\$2,200.00~~ 1400

Subtotal :- \$6,840.00

Total:- \$46,274.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 20625.74

1/s: 16.5K

120 days

16.5K