

INSDM

INS CASE OWNER:

CC 3/AIG1802

LKK:

IDAC:

Surveyor:

TASUL

DOI:

ASSIGNMENT

14/12/18

Date / Time:

4/12/18

Registered in Merimen:

4/12/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJD 711m

Name of Insured:

UM WEE FINE

Insured Tel No.:

HP: A+6011111

Excess Sec II :SS

D.O.A: 02/12/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

47076467654

Policy No.:

NORMANB-05

Make / Model:

JULIANE

Place of Accident:

ED MTRIOE 6 SURKISEME

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SEE 81176

INSRS:
WSP:
Tel:
Liability:
RMKS:

Performance

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

4/12/18
VIC

SEE 81176 - 4

SJD 711m

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI

After call 1st to OI: 11/12/18 - VIC

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorization to Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

11/12/18

FILE PROVIDED. OI HIT PARKED TP.
GARD LETTER BY BULH TO OI TO
NOTIFY TP CLAIM BY NCB ISSUES.
BULH LIABILITY CLERK
TO MINUTES COE.
MINUTES
ORIGINAL TP LOG IN

08/05/19

TYPE REPORT FOR WARRANT APPROVAL.

14/8/19

FILE PASS TO LSP TO CLONE

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

P/P SS 12,739.10 (9 days / Reduction: 12 %

Confirm by:

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 3/8/19

Confirm with: Caroline

Email ☒ Call ☐

Final Liability:

100 (Agreed / Assessed) BOLA S/N No.: 22

If NO or B 28, Ass. Lia:

Repair Cost:

COT/GOOD SS 13,620.84

(OI HIT PARKED TP)

Loss of Rental (LOR):

SS - (days)

Loss of Use (LOU):

SS 1,120.00 x 14 (days)

Loss of Income (LOI):

SS - (5 x days)

LOR only ☐ LOU only ☒LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search:

SS -

Medical:

SS -

Disbursement:

SS - (e.g. Tow / Independent)

Legal Cost:

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: 3320

Total:

SS 14,750.84 Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 13630.84

Name 1:

PERFORMANCE MOTORO LIMITED

Payee 2: (Strike if N.A.)

SS 1120.00

Name 2:

CHAN CHI PING

Payee 3: (Strike if N.A.)

SS -

Name 3:

-

W. H. HOPE

Form


REF:

h

4248E

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **SKK 8117G**
 at Workshop min: **PERFORMANCE**
 of: **303, ALEXANDRA RD**
 Insured: **ALH**
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **64K**
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: **1** days Res: Yes or No
 Lum Sum: **-** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Van No: **SKK 8117G** Regn: **2013 ALH**
 Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or:
 Make: **B.M.W 116I** CC: **1598**
 Colour: **WHITE** A/C: Insured / Std / NI / NA
 Sp Reading: **75147** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **WPA1A120303209695**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Mod: ☒ Nil / STD A/Rim or
 Tyre Size F: **205/55R16**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A: **02/12/18** D.O.I: **14/12/18**
 Survey held at: **PERFORMANCE**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S REAR
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

17/12/18 Call up Kevin that ^{repair limit} for this case is 13K. and agreed
 P/P \$12,739.10
 (KED: \$1,720.20 (12%))

Date/Time: File Pass to: ☐ : Prel. Report
☐ : Final Report

Days Of Repair:
 Resurvey No. of Trip:

Survey Fee

Date/Time: File Return to:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Insp (\$)
☐ Weekend (\$)

Transportation

Report Format:

Lump Sum / I.B.I: \$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18021842/hb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 04-12-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJD 311M	Veh. Inspected	SKK 8117G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/12/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	02/12/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Karpang Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190833/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

03 DEC 2018

Estimate No. : b1 49316
Date Estimated : 03/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chan Chi Ping
6 Sunrise Avenue

Singapore 806668

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK8117G	J209695	30/08/2013	116iA/5	0

DESCRIPTION

To replace rear right side panel, rear bumper & all attachments cause by accident.

Painting on rear right side panel, rear bumper & rear RH trunk floor.

To remove and install fuel tank to facilitate repairs including extract fuel and conduct leak tests.

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

To check steering geometry and conduct wheel alignment according to BMW specification (1x)

To replace tyre and wheel rim including balancing. (1x).

To check electrical wiring systems at the rear section for proper function.

To carry out body cavity preservation.
(For cut panel).

Sundries.

VALUE

850 + 4250 = 5100 ~~5,950.00~~~~2208~~ 2,454.00~~451~~ 531.00~~742~~ 878.00~~451~~ 531.00~~80~~ 94.00~~150~~ 177.00~~451~~ 531.00~~?~~ 150.00

Total Labour 1: 11,291.00

DESCRIPTION

RR RH FENDER RA/

REINFORCEMENT PLATE C-PILLAR RH ? x nn

REINFORCEMENT PLATE ROCKER PLATE RH ? x nn

REINFORCEMENT PLATE UNIVERSAL ? x nn

RR BUMPER RH SIDE GUIDE ? n

REAR BUMPER PRIMED (LINES) DE

REAR RH WHEEL HOUSING COVER ? x nn

QTY PRIC

1 1,328.35

1 50.45

1 50.45

1 28.45

1 49.05

1 924.75

1 131.10

VALUE

1,328.35

50.45

50.45

28.45

49.05

924.75

131.10

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770288, Kampong Arang Road
East Coast Centre
Singapore 428180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49316
Date Estimated : 03/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK8117G	J209695	30/08/2013	116iA/5	0

DESCRIPTION

DECOUPLING RING PDC TORQUE CONVERTE ^{?XAN}
 BLIND RIVET AVIBVLB ^{na}
 SCREW (SF PLUS M5X15) ^{na}
 (DG/SL) BODY ADHESIVE K5B (195ML) ^{} na}
 (DG) BODYWORK ADHESIVE K5A (50ML)
 (DG) CLEANER R1 (100ML)
 PUNCH RIVET N4
 (S/L) SEAM SEAL 300ML

QTY	PRIC	VALUE
4	5.05	20.20
7 (0pc)	0.55	3.85
3 (0pc)	0.55	1.65
1	326.80	326.80
1	112.70	112.70
1	26.15	26.15
32 (40)	0.55	17.60
1	33.80	33.80

+ SUPP

Total Parts : 3,105.35

Claims OD / And Party / Uninsured Losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 14/12/18 @ 1030 Expires SS _____

Surveyor's Name RAMEL Sign _____

Surveyor's Tel 90010068 Authorized Yes / No _____

Authorized Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ FILE Yes / No _____

Surveyor's E-mail _____

No. of Working Days Required 9 days

LKK Auto Consultants hereby notify the Reparer of the following:

- To remedy defects after repair
- To display damaged parts after recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary claim(s) must be submitted and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature: _____

Date: _____

Labour 1	:	11,291.00
Parts	:	3,105.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,007.74
Grand Total	:	15,404.09

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

14,459.30

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401155W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 49316
Date Estimated : 03/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Chan Chi Ping
6 Sunrise Avenue

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 806668

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKK8117G	J209695	30/08/2013	116iA/5	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SET MOUNTS PDC SENSOR REAR *	62.95	1.00		62.95 <i>ph</i>

Total Labour :	
Total Parts :	62.95
Total Labour & Parts :	62.95

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401535W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 49316
Date Estimated : 03/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Chan Chi Ping
6 Sunrise Avenue

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 806668

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEAGE	
SKK8117G	J209695	30/08/2013	1161A/5	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
* To replace rear bumper and attachments, rear RH fender include making good the rear RH trunk floor and knocking out dents caused by the accident	5100.00		5,100.00		
To spray paint rear RH fender, rear bumper and rear RH trunk floor	2208.00		2,208.00		
To remove and install fuel tank to facilitate repairs include extracting fuel and conducting tests for leak	451.00		451.00		
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs	742.00		742.00		
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00		
To remove and install wheel rim include balancing (1x)	80.00		80.00		
To check electrical wiring systems at the rear section for proper function.	150.00		150.00		
To carry out body cavity preservation (For cut panel)	451.00		451.00		
Sundries	150.00		150.00		

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR RH FENDER	1,328.35	1.00		1,328.35
RR BUMPER RH SIDE GUIDE	49.05	1.00		49.05
REAR BUMPER PRIMED (LINES)	924.75	1.00		924.75
# SET MOUNTS PDC SENSOR REAR *	62.95	1.00		62.95
BLIND RIVET AVIBVLB	0.55	20.00		11.00
SCREW (SF PLUS M5X15)	0.55	10.00		5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	326.80	1.00		326.80
PUNCH RIVET N4	0.55	40.00		22.00
(DG) BODYWORK ADHESIVE K5A (50ML)	112.70	1.00		112.70
(DG) CLEANER R1 (100ML)	26.15	1.00		26.15

Performance Motors Limited

A member of the Stone Carby Group
Co. Reg. No. 191401559W GST Reg. No. M2-0020081-X



FINAL REPORT

✈ (DG/SL) ADHESIVE SET K6 •
(S/L) SEAM SEAL 300ML

2/2

53.05	1.00
33.80	1.00

53.05
33.80

(5) ✓

SUPPLEMENTARY ITEMS

Total Labour :	9,783.00
Total Parts :	2,956.10
Total Labour & Parts :	12,739.10
Deduction for Excess :	0.00
Total Repair Costs less Excess:	12,739.10
GST @7%:	891.74
Grand Total :	13,630.84

Vic (LKKAUTO)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Monday, 28 January, 2019 4:20 PM
To: Rasul (LKKAUTO); Vic (LKKAUTO)
Subject: FINAL REPORT / SKK8117G
Attachments: Final Report SKK8117G_2.pdf; Final Report SKK8117G.pdf

Dear Rasul and Vic

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 9,783.00
Total Parts : 2,956.10
Total Labour & Parts : 12,739.10

Repair days: 9 week days + 4 weekends + 1 PH

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Enquire PARF/COE Rebate for Registered Vehicle

424BE

\$21,182.00

\$14,827.00

\$50,391.00

OK

$$\begin{array}{r} 64,000 \\ 50,391 \\ \hline 13,609 \end{array}$$



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

11 DECEMBER 2018

**LIM WEE KIAK
28 SUNRISE AVENUE
SINGAPORE 806685**

By Post and By Email

Dear Sir/Madam,

OUR REF : CC3/AIG18021842/hb3

YOUR REF : SJD 311M

**ACCIDENT INVOLVING SJD 311M AND SKK 8117G ALONG SUNRISE AVENUE ON
02.12.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SKK 8117G against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SKK 8117G. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

weekiak@starhub.net.sg
(Email)

View Received Message

This mail is associated with :

*SKK8117G (0470764676SG)
[SJD311M]
TP
CHAN CHI PING
Dec 2 2018 12:00PM
[LIM WEE KIAK]
Performance Motors Limited

Reply Reply All Mark as Unread Print Message Delete Message Forward

From **AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS)**, sent on **29/07/2019 16:07 PM**.
To LKK_HQ
Subject **Alert - Adj Mandate Approved (S\$14750.84) - SKK8117G - Claim Handler: Foo, Chit Yan**

Approved:14750.84:Subject to Final Repair Bill

DOCUMENTS SUMMARY
There are no documents.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SKK 8117G	Model:	BMW
Date of Accident:	2-12-2018		

Global Sum Settlement:	<input type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	: \$	15404.09
Final Repair Cost	: \$	13630.84
Loss of Use	: \$	1120.00
Rental (if any)	: \$	
LTA / GIA Search Fee	: \$	
Others	: \$	
	: \$	
Final Settlement Sum	: \$	14750.84

Is Third Party Workshop GIA Registered? ☐ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Application: Yes / No
BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown

1)	Performance Motor Limited	: \$	13630.84
2)	Chan Chi Ping	: \$	1120.00
3)		: \$	

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.

Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;

Survey Report; Medical Report / Bill (if any)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Tuesday, 11 December, 2018 9:35 AM
To: weekiak@starhub.nets.sg
Cc: Admin A; Vic (LKKAUTO)
Subject: YOUR REF: SJD 311M_ACCIDENT INVOLVING SJD 311M AND SKK 8117G ALONG SUNRISE AVENUE ON 02.12.2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

11 DECEMBER 2018

LIM WEE KIAK
28 SUNRISE AVENUE
SINGAPORE 806685

By Post and By Email

Dear Sir/Madam,

OUR REF : CC3/AIG18021842/hb3

YOUR REF : SJD 311M

ACCIDENT INVOLVING SJD 311M AND SKK 8117G ALONG SUNRISE AVENUE ON 02.12.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SKK 8117G against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SKK 8117G. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the Involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Chan Chi Ping ("the third party claimant")
of 6 Sunrise Avenue S(806668) (address),
owner of SKK 8117 G (vehicle no.) hereby authorize
Performance Motors Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SKK 8117 G that was
damaged pursuant to the accident which occurred on 2-12-2018 (date) along
Sunrise Avenue (location)
involving vehicle no/s SJD 311M ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment furtherto settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 28 day of 12 (month) 20 18 (year)

Signed by "the third party claimant"

KEVIN LEONG WAI KIT Performance Motors Limited 303 Alexandra Road Sime Darby Performance Centre Singapore 159941
--

Signed by "the workshop"

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0022881-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190180 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190886 (AfterSales)
Fax: 63449777

116, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/535 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1323494

Date IN : 17/12/2018

Cust. Svc. Advisor: Kevin Leong Wai Kit

Page No. : 1 of 2

Invoice Number : 2061925 / WSB

Invoice Date : 31/01/2019

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Chan Chi Ping
6 Sunrise Avenue

Singapore 806668

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK8117G	J209695	30/08/2013	116IA/5	75147

- - - - LABOUR 1 - - - -

NETT

To replace rear right fender, rear bumper and attachments
etc including to make good the rear right trunk floor and
knock out dented area caused

5,100.00

by the accident. To remove and install body parts in order to carry
out painting job.

To respray rear right fender, rear bumper and rear right
trunk floor.

2,208.00

To remove and install fuel tank to facilitate repairs
including extract fuel and conduct leak tests.

451.00

To remove and install rear hat-tray, rear seat, carpet
and roof top lining to facilitate repairs.

742.00

To check steering geometry and conduct wheel alignment
according to BMW specification

451.00

To remove and install rear right wheel rim include wheel
balancing.

80.00

To check electrical wiring systems at the rear section
for proper function.

150.00

To carry out body cavity preservation.
(For cut panel).

451.00

Sundries.

150.00

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

0.00

DATE OF ACCIDENT : 2.12.2018. 3RD PARTY CAR : SJD311M.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO
CONSULTANTS PTE LTD ON 14.12.2018 AT 10.30 AM.
AUTHORISED REPAIR BY MR VIC ALPEH FROM LKK ON
11.12.2018 VIA E-MAIL.

PROPOSE LOSS OF USE = \$80X14. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

0.00

Total Labour 1: 9,783.00

- - - - PARTS - - - -

RR BUMPER RH SIDE GUIDE
RR RH FENDER

Qty	Retail Price
1	49.05
1	1,328.35

NETT

49.05

1,328.35

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-x

101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63390100 (Sales & Admin)
63390111 (AfterSales)
Fax. 64787770

288, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63390888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63390528 (AfterSales)
63390533/315 (Motorrad)
Fax. 64798601 (AfterSales)
64798628 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. : B1 1323494	Page No. : 2 of 2
Date IN : 17/12/2018	Invoice Number : 2061925 / WSB
Cust. Svc. Advisor: Kevin Leong Wai Kit	Invoice Date : 31/01/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

BLIND RIVET AVIBVLB	20	0.55	11.00
SCREW (SF PLUS M5X15)	10	0.55	5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	1	326.80	326.80
(DG) BODYWORK ADHESIVE K5A (50ML)	1	112.70	112.70
(DG) CLEANER R1 (100ML)	1	26.15	26.15
PUNCH RIVET N4	40	0.55	22.00
(S/L) SEAM SEAL 300ML	1	33.80	33.80
REAR BUMPER PRIMED (LINES)	1	924.75	924.75
(DG/SL) ADHESIVE SET K6	1	53.05	53.05
SET MOUNTS PDC SENSOR REAR	1	62.95	62.95
Total Parts :			2,956.10

- - - - LABOUR 2 - - - -

NETT

0.00

Total Labour 2: **0.00**

Labour Charges :	9,633.00	Total Labour & Parts Charges :	S\$ 12,739.10
Parts Charges :	2,956.10	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	150.00	Invoice Total Amount Exclude GST :	S\$ 12,739.10
		GST @ 7% :	S\$ 891.74
		Invoice Total Amount Include GST :	S\$ 13,630.84

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 13,630.84**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



1 ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

EXPIRY DATE

23 Jul 1992
23 Jul 1992

Motorcycles ≤ 200 cc
Motor cars with unladen weight ≤ 3000 kg with ≤ 7
passengers, exclusive of driver; and other motor
vehicles with unladen weight ≤ 2500 kg



Licence No: S2594248E

128A

6 SUNRISE AVENUE
SINGAPORE 806868
NRIC No: S2594248E

Blood Group: A+ Date of Issue: 16-01-2001

Date: 04-07-2008

NRIC No: S2594248E

REPUBLIC OF SINGAPORE DRIVING LICENCE

CHAN CHI PING

09 Jan 1952 23 Mar 2018

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S2594248E

CHAN CHI PING

曾志清

Chinese

09-01-1952 M

Country of Birth: MALAYSIA

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express






























CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Dec 2018 Edit Reg		14 Dec 2018 00:00 Edit Adj Rpt	\$512,739.10 Edit Estimates	\$512,739.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LIM WEE KIAK , ID: S6847995I								
Main Claimant:	CHAN CHI PING , ID: S2594248E								
Vehicle Reg. No.:	SKK8117G	Date of Loss:	02/12/2018 12:00 - :59 [63 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0470764676SG	Policy/Cover Note No.:	2100337286 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJD311M	Policy No. (Claimant):							
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/12/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (29/07/2019): Alert - Adj Mandate Approved (\$514750.84) - SKK8117G - Claim Handler: Foo, Chit ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKK8117G (0470764676SG)
[SJD311M]
TP
CHAN CHI PING
Dec 2 2018 12:00PM
[LIM WEE KIAK]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	
Photos/Images				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/02/19 10:17	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	07/02/19 10:17	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
4	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
5	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
6	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
7	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
8	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
9	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
10	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
11	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
12	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
13	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
14	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
15	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
16	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
17	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
18	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
19	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
20	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
21	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
22	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
23	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
24	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
25	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
26	07/02/19 10:18	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation				
			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/18 19:02	TP ESTIMATE	 Load PDF	
2	04/12/18 19:02	TP GIA REPORT	 Load PDF	
3	11/12/18 09:37	EMAIL TO OI	 Load PDF	
4	11/12/18 09:37	LETTER TO OI	 Load PDF	
5	17/12/18 18:41	TP ESTIMATE- MARKED	 Load PDF	
6	19/12/18 10:43	EMAIL FROM OI	 Load PDF	

Letters/Correspondences			1 per page	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
7	16/08/19 09:30	WORKSHOP INVOICE		Load PDF
8	16/08/19 09:30	AUTHORISATION TO ACT FORM		Load PDF
9	16/08/19 09:30	Release Voucher		Load PDF
10	16/08/19 09:30	TP IC		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	05/12/18 09:14	OI GIA REPORT		Load PDF
2	01/07/19 16:12	Clear Report		Load XLSX

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJD311M (Insd veh)	Model:	BMW 116I 1.6 (A)
	SKK8117G (TP veh)		
Date of Accident:	02/12/2018		

Global Sum Settlement	: [] Yes	[X] No	
Repair Estimate	: \$	15,544.69	
Final Repair Cost	: \$	13,630.84	
Loss of Use	: \$	1,120.00	14.00 days at \$80.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	0.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	14,750.84	

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: _____ 100 (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	: \$	13,630.84
2)	Chan Chi Ping	: \$	1,120.00

JOANNE LEE KHANG MIN

16 Aug
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18021842/R1DB3Q2

Date: 16/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100337286
Claimant Vehicle No: SKK8117G **Insured Vehicle No:** SJD311M
 Date of Loss: 02/12/2018 Nature of Claim: TP Claim No: 0470764676SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK8117G**
 Make & Model: BMW 116I, 1.6 (A) Engine No: B240J462N13B16A
 Reg. Date: 30/08/2013 (Man. Year: 2013) Chassis No: WBA1A12030J209695
 Colour: White Odometer: 75147 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,386.75	3,106.10	280.65	8.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,141.00	9,633.00	1,508.00	13.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,527.75	12,739.10	1,788.65	12.31
+ GST 7.00/7.00% (S\$)	1,016.94	891.74	125.20	12.31
Nett Amount (S\$)	15,544.69	13,630.84	1,913.85	12.31
+ Loss of Use (14.0 x S\$80.00/day) (S\$)		1,120.00		
Nett Liability (S\$)		14,750.84		

INSPECTION

Date of Assignment: 14/12/2018
 Date Inspected: 14/12/2018 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941
 Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*RR RH FENDER	Bent	1,328.35 FS	*1,328.35 FS
3	1		*REINFORCEMENT PLATE C-PILLAR RH	Not Necessary	50.45 FS	*- FS
4	1		*REINFORCEMENT PLATE ROCKER PLATE RH	Not Necessary	50.45 FS	*- FS
5	1		*REINFORCEMENT PLATE UNIVERSAL	Not Necessary	28.45 FS	*- FS
6	1		*RR BUMPER RH SIDE GUIDE	Necessary	49.05 FS	*49.05 FS
7	1		*REAR BUMPER RPIMED (LINES)	Deformed	924.75 FS	*924.75 FS
8	1		*REAR RH WHEEL HOUSING COVER	Not Necessary	131.10 FS	*- FS
9	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
10	10		*BLIND RIVET AVIBVLB	Necessary	11.00 FS	*11.00 FS
11	10		*SCREW (SF PLUS M5X15)	Necessary	5.50 FS	*5.50 FS
12	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	326.80 FS	*326.80 FS
13	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	112.70 FS	*112.70 FS
14	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
15	1		*PUNCH RIVET N4 (40 PCS)	Necessary	22.00 FS	*22.00 FS
16	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS
17	1		*SET MOUNTS PDC SENSOR REAR	Necessary	62.95 FS	*62.95 FS
18	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS

F=Franchise part. S=SpcNetl.

Total Parts (\$\$)	3,386.75	3,106.10
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR RIGHT SIDE PANEL,REAR BUMPER & ALL ATTACHMENTS CAUSE BY ACCIDENT	New	5,950.00	5,100.00
2	PAINTING ON REAR RIGHT SIDE PANEL,REAR BUMPER & REAR RH TRUNK FLOOR	New	2,454.00	2,208.00
3	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS INCLUDING EXTRACT FUEL AND CONDUCT LEAK TESTS	New	531.00	451.00
4	TO REMOVE AND INSTALL REAR HAT-TRAY ,REAR SEAT ,CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	742.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	451.00
6	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	80.00
7	TO CHECK ELECTRICAL WIRING SYSTEM AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
Gross Labour Cost (S\$)			11,141.00	9,633.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >