

CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

CHINA/LONPAC

DOA: 29/11/2018@1040

LONPAC INSURANCE LTD

03/12/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SLF 1850 H - LEXUS IS250 AUTO STD FL
CHASSIS NO: JTHBK262605086763 (01/2009)

1 pc	Front grille chrome	\$ 257.90	ena ✓
1 pc	Front grille	\$ 501.50	?
1 pc	Front bumper	\$ 766.30	de ✓
1 pc	Front bumper sponge	\$ 105.70	?
1 pc	Rear boot	\$ 758.40	Ry
1 pc	Rear boot emblem 'LEXUS'	\$ 78.60	net ✓
1 pc	Rear boot emblem 'IS250' emblem	\$ 76.10	net ✓
1 pc	Rear boot lower garnish	\$ 529.80	ena ✓
1 pc	Rear bumper	\$ 801.70	de ✓
1 pc	Rear bumper sponge	\$ 106.70	?
1 pc	Rear bumper reinforcement	\$ 461.90	?
		\$ 4,444.60	
	LESS 10%	\$ 444.46	
		\$ 4,000.14	

1 pc	Reverse sensor (S/NETT)	\$ 200.00	?
1 pc	Front no.plate (S/NETT)	\$ 35.00	int ✓

Remove necessary parts: jacking, panel beating, repair and straightne front inner panel, front support panel, front bonnet and front bumper.


\$ 400.00 250

Putty and respray front inner panel, front bonnet, front bumper and front support panel.

\$ 480.00 250

Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear end panel, rear boot, rear boot garnish and rear bumper.

\$ 480.00 300.



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

SLF 1850 H - LEXUS IS250 AUTO STD FL

Putty and respray rear inner panel, rear end panel, rear boot, rear boot garnish and rear bumper.


\$	650.00	500
\$	6,245.14	
\$	437.16	
\$	6,682.30	

ADD 7% GST

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....


Page 2 of 2

Tanpin 97495749
WP
6/2/18 @ 310pm
Resurvey after repair.
5 days
Sho@hleanp.com.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: