

INS. BASE OWNER:

Wang Kefu

CC 4, Asm 180

21861, Tigay

LKK:
IDAC:

85714

ASSIGNMENT

Surveyor:

Taufik

DOI:

12/12/18

Date / Time:

4/12/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No:

S/N 3141P

Name of Insured:

Oh Wei Ling

Insured Tel No:

HP:

Excess Sec II :SS

D.O.A:

11/12/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S8m01s8y

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:

pml

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

p/p

SS 4522.68

(3 days)

Reduction:

\$1186.27

% 21

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(w/loss)

SS 4839.27

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS 320.00

(980 x 4 days)

Loss of Income (LOI):

SS

(5 x days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS

200

Medical:

SS

-

Disbursement:

SS

-

(e.g Tow/ Independent)

Legal Cost

SS

-

Total:

SS

5161.27

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

5161.27

Name 1:

Performance Motors Limited

Payee 2 (S/N if P.N.A.):

SS

Name 2:

Payee 3 (S/N if P.N.A.):

SS

Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350-

REF:

AXA


28/11/18

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No _____
 Claims No _____
 Sum Insured _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 968K
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lump Sum: 17-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT
Kevin

Veh No: SJS71724 Yr Regn: 2013 Sep
 Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: BMW 316F CC: 1500
 Colour: Red A/C: _____ Insured / Std / NI / NA
 Sp. Reading: 55955 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBA3A120903721244
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R14
 R: 205/60R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. _____ D.O.I. 17/12/18
 Survey held at: PMU

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rebate: \$57,780
 NV: \$10,220.60

2/8 \$4522.68(Red = \$1186.77 / 11%)* 3 repair days + 1 PRP = 4 days

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Survey Fee:

2)

Transportation:

Add Fee: ☐ Site Insp (\$

) \$ + RS \$

☐ Interview (\$

) Photos

☐ Tech Invs (\$

) Others

☐ Weekend (\$

) TOTAL

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Performance Motors Limited

A member of the Sino Dairy Group
Co. Reg. No. 197401039W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 49322
Date Estimated : 03/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
See Seow Peng (Xu Xiaoping)
42 Pavilion Place

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Singapore 658378

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SJS7172Y	J721244	26/09/2013	316iA/4	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00	10.00	765.00		
* To spray paint rear bumper	882.00	10.00	793.80		
To check electrical wiring systems at the rear section for proper function.	150.00	10.00	135.00		
* To diagnose and replace rear electronic module (REM) control unit include programming and conducting tests for proper function	425.00	10.00	382.50	Now ✓	
Sundries	80.00	0.00	80.00		

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
RR BUMPER BOTTOM REINFORCEMENT	67.75	1.00	3.00	65.72	
REAR BUMPER CARRIER (ECE)	443.70	1.00	3.00	430.39	
REAR BUMPER PANEL PRIMED BASIS	1,127.80	1.00	3.00	1,093.97	
REAR PDC HOLDER SET	23.70	1.00	3.00	22.99	
# TRUNK LID LOCK *	217.15	1.00	3.00	210.64	dis ✓
# PLUG BLACK D=5MM *	0.90	6.00	3.00	5.24	rec ✓
# CONTROL UNIT REM *	501.00	1.00	3.00	485.97	shipped ✓
(DG/SL) ADHESIVE SET K6	53.05	1.00	3.00	51.46	

SUPPLEMENTARY ITEMS

Total Labour :	2,156.30
Total Parts :	2,366.38
Total Labour & Parts :	4,522.68 ✓
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,522.68
GST @7%:	316.59
Grand Total :	4,839.27

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No: 197401559W GST Reg. No M2-0020081-X



383, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438160
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/830 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

03 DEC 2018

Estimate No. : b1 49322
Date Estimated : 03/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
See Seow Peng (Xu Xiaoping)
42 Pavilion Place

Singapore 658378

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJS7172Y	J721244	26/09/2013	316iA/4	0

DESCRIPTION

To replace rear bumper panel, & reinforcement, carrier & all attachments cause by accident.

850 2,550.00

Painting on rear bumper panel

795 882.00

To check electrical wiring systems at the rear section for proper function.

150 177.00

Sundries.

? 80.00

Total Labour 1: 3,689.00

DESCRIPTION

RR BUMPER BOTTOM REINFORCEMENT
REAR BUMPER CENTRE GUIDE
REAR BUMPER CARRIER (ECE)
REAR DECORATIVE STRIP (SPORT LINE)
REAR BUMPER PANEL PRIMED BASIS
RR BUMPER FLAP TOWING EYE PRIMED
REAR PDC HOLDER SET
REAR BUMPER LH SIDE GUIDE
REAR BUMPER RH SIDE GUIDE
REAR SILENCER HEAT SHIELD
DECOUPLING RING PDC TORQUE CONVERTE
(DG/SL) ADHESIVE SET K6

QTY	PRIC	VALUE
1	67.75	? 67.75
1	32.90	? 32.90
1	443.70	? 443.70
1	57.00	? 57.00
1	1,127.80	de 1,127.80
1	43.25	X 43.25
1	23.70	? 23.70
1	58.50	? 58.50
1	58.50	? 58.50
1	34.10	? 34.10
4	5.05	un 20.20
1	53.05	? 53.05

Total Parts : 2,020.45



383, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

180, Kangkong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64798601 (AfterSales)
64798624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49322
Date Estimated : 03/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJS7172Y	J721244	26/09/2013	316iA/4	0

Closest GDT / Sime Darby / Uninsured / Insured / Direct Settlement

Regn No. 12/12/18 21130 GDT No.

Date & Time 12/12/18 21130 Excess \$

Surveyor's Name Tanpin Sign [Signature]

Surveyor's Tel 9746 5749 Authorized Yes / No

Authorized Date Time

REPAIR PARTS PRICED BY SURVEYOR Yes / No Price Yes / No

Surveyor's Email tanpin@lkkauto.com

No. of Working Days Required 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Date:

Labour 1	:	3,689.00
Parts	:	2,020.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	399.66
Grand Total	:	6,109.11

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

<< Re:RE: MANDATE IA - SJS 7172Y - PERFORMANCE

Type

🔔 Question

Message

Hi, TP vehicle is manuf in year 2013. Kindly advise LS COR application. Thanks

[Reply](#)

 **Re:<MANDATE IA> - S8M0158Y {ACCIDENT INVOLVING
SJN 3141P (OI) & SJS 7172Y (TP) ON 01/12/2018}**

Type

 Question

Message

Hi, we have maintained to use the NIMA benchmark at \$60/day and did not agree with the benchmark meant for writs filed. Kindly maintain. Thanks

[Reply](#)

<< **Re:<MANDATE IA> - S8M0158Y {ACCIDENT INVOLVING
SJN 3141P (OI) & SJS 7172Y (TP) ON 01/12/2018}**

Type

🔗 Question

Message

Hi, Proceed. Thanks

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 25/7/2019

Survey Details:

Date of loss	1-Dec-18
Date of appointment	4-Dec-18
Date of survey	17-Dec-18
Location of survey	PERFORMANCE MOTORS LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SJS7172Y
Make and Model	B.M.W. 316I 1.6 AT D/AB 4DR ABS
Date of registration	26-Sep-13
Parf Rebate	
Market Value	\$ 68,000.00
Parf Rebate	\$ 58,083.00
Nett Loss	\$ 9,917.00

Repair details:

Initial Estimate	5,709.45
------------------	----------

Proposed/Revised repair cost:

Parts	\$ 2,366.38
Check items (estimate)	\$ -
Labour	\$ 2,156.30
Total	\$ 4,522.68
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>3 days</u>
---------------------------	---------------



Remarks:

3 RECOMMENDED REPAIR DAYS + 1PRS = 4DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 4,839.27	W/GST
Loss of use	\$ 240.00	4days x \$60.00
Loss of rental	\$ -	
Loss of income	\$ -	
LTA search fees	\$ 2.00	
Others	-	
Proposed Total	5081.27	



<MANDATE IA> - S8M0158Y {ACCIDENT INVOLVING SJN 3141P (OI) & SJS 7172Y (TP) ON 01/12/2018}

Type

Question

Message

LIABILITY: 100% INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE
SEEK YOUR MANDATE AT \$5081.27 (CLAIMING LOU). MANDATE IA UPLOADED IN SMARTCLAIM.
KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

Reply

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Thursday, 7 November 2019 5:01 PM
To: PBSP
Subject: RE: LOD REMINDER - SJS7172Y & SJN3141P ON 01/12/2018

WITHOUT PREJUDICE

Dear Caroline,

We are pleased to re-offer total amount of \$5,161.27 (all-in) as per your proposal.

Dv has received

Thus, we shall proceed to submit and close off the case.

Thanks

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Thursday, 7 November 2019 4:58 PM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Subject: Re: LOD REMINDER - SJS7172Y & SJN3141P ON 01/12/2018

Dear Cecilia

As spoken moments ago, we reject and mandate to settle at \$80/day.

Please let us have your confirmation if you are agreeable to settle as per LOD.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601



Service Request Details

Claim

S8M0158Y

Reference

None

Loss Date

December 1, 2018

Request Date

December 4, 2018

Due Date

December 11, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

04/12/2018 @ 1039am
Caroline veh not in.

Actions

Next Step

Agree to perform service

Decline WorkAccept Work

Vehicle Information

Incident Vehicle Registration #

SJS7172Y

Make

TPVD BMW

Model

316I-1.6 (A)

Service Address

...

Primary Contact/Insured

OH WEI LING

20 PAVILION CIRCLE, 658490, Singapore

98590784

WEILINGZ@GMAIL.COM

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Monday, 3 December, 2018 5:49 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: REQ FOR DIRECT SETTLEMENT - SJ57172Y & SJN3141P ON 1.12.2018
Attachments: SKM_558e18120317450.pdf

Categories: Pragati

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

 **Re:<MANDATE IA> - S8M0158Y {ACCIDENT INVOLVING
SJN 3141P (OI) & SJS 7172Y (TP) ON 01/12/2018}**

Type

 Question

Message

Hi CCL, only for PML cases, may allow to use Pre-writ benchmark on LOU & LOR. TPV is of around 5yrs at point of accident, though there is no correlation to no. of years against benchmark, negotiate if we may close at \$70/day, up to \$80/day. Thanks

[Reply](#)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJN 3141P (Insd veh)	Model:	B.M.W. 316I
	SJS 7172Y (TP veh)		
Date of Accident:	01/12/2018		

Global Sum Settlement	: [] Yes	[X] No
Repair Estimate	: \$	7,314.84
Final Repair Cost	: \$	4,839.27
Loss of Use	: \$	320.00
Rental (if any)	: \$	4days at \$80.00 per day
LTA / GIA Search Fee	: \$	2.00

Others:	: \$	0.00
---------	------	------

	: \$	
Final Settlement Sum	: \$	5,161.27

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No- BOLA Scenario No: _____
 BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	PERFORMANCE MOTORS LIMITED	: \$	5,161.27

 JOANNE LEE KHANG MIN
 LKK Auto Consultants Pte Ltd

 13/11/2019
 Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave. 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18021861/T1ga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:PETER

Date : 13-11-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJN 3141P	Veh. Inspected	SJS 7172Y
Policy No.	VA1/GA162906	Coverage (\$)	0.00
Claim No.	S8M0158Y	Excess (\$)	0.00
Assign From		Assign Date	04/12/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 316I	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WBA3A12090J721244	Colour	RED
Odometer	55955	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	MICHELIN	6 mm
L/H Front Tyre	205/60 R16	MICHELIN	6 mm
R/H Rear Tyre	205/60 R16	MICHELIN	6 mm
L/H Rear Tyre	205/60 R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/12/2018	Inspection Date	17/12/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 7172Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	80.00	80.00
1	RR BUMPER BOTTOM REINFORCEMENT (SN) (CONSISTENT)	DEFORMED	67.75	65.72
1	REAR BUMPER CENTRE GUIDE (SN) (CONSISTENT)	NOT NECESSARY	32.90	-
1	REAR BUMPER CARRIER (ECE) (SN) (CONSISTENT)	BENT	443.70	430.39
1	REAR DECORATIVE STRIP (SPORT LINE) (SN) (CONSISTENT)	NOT NECESSARY	57.00	-
1	REAR BUMPER PANEL PRIMED BASIS (SN) (CONSISTENT)	DEFORMED	1,127.80	1,093.97
1	RR BUMPER FLAP TOWING EYE PRIMED (SN) (CONSISTENT)	NOT NECESSARY	43.25	-
1	SET REAR PDC HOLDER (SN) (CONSISTENT)	NECESSARY	23.70	22.99
1	REAR BUMPER LH SIDE GUIDE (SN) (CONSISTENT)	NOT NECESSARY	58.50	-
1	REAR BUMPER RH SIDE GUIDE (SN) (CONSISTENT)	NOT NECESSARY	58.50	-
1	REAR SILENCER HEAT SHIELD (SN) (CONSISTENT)	NOT NECESSARY	34.10	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN) (CONSISTENT)	NOT NECESSARY	20.20	-
1	(DG/SL) ADHESIVE SET K6 (SN) (CONSISTENT)	NECESSARY	53.05	51.48
1	TRUNK LID LOCK (SN) (CONSISTENT)(ADDITIONAL)	DISTORTED	210.64	210.64
6	PLUG BLACK D=5MM (SN) (CONSISTENT)(ADDITIONAL)	NECESSARY	5.24	5.24
1	CONTROL UNIT REM (SN) (CONSISTENT) (ADDITIONAL)	SHORTED	485.97	485.97
			2,802.30	2,446.38
LABOUR				
TO DIAGNOSE AND REPLACE REAR ELECTRONIC MODULE (REM) CONTROL UNIT INCLUDE PROGRAMMING AND CONDUCTING TESTS FOR PROPER FUNCTION .(ADDITIONAL)			425.00	382.50
TO REPLACE REAR BUMPER PANEL & REINFORCEMENT ,CARRIER & ALL ATTACHMENTS CAUSE BY ACCIDENT.			2,550.00	765.00
PAINTING ON REAR BUMPER PANEL.			882.00	793.80
TO CHECK ELECTRICAL WIRING SYSTEMS AT THE REAR SECTION FOR PROPER FUNCTION.			177.00	135.00
			4,034.00	2,076.30

Report Ref No. CC4/ASM18021861/T1ga3q2



GRAND TOTAL		6,836.30	4,522.68
RECOMMENDED COST OF REPAIRS			4,522.68

Report Ref No. CC4/ASM18021861/T1ga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	58MG15JY
Reference	CC4/ASM18021861/71ga3a2
Loss Date	1 December 2018
Report Date	3 Dec 2018 4:41:00 PM
Request Date	30 May 2019
Due Date	

Actions

Next Step

Wait for: Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SJ57172Y
Make	TPWD BMW
Model	316i-1.6 (A)
Service Address	

...

Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Primary Contact/Insured
OH WEI LING
20 PAVILION CIRCLE, 658490, Singapore
98590784
WEILINGZ@GMAIL.COM

Claim Handler
KHONG Lynn
68804892
lynn.khong@axa.com.sg

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKXInvoice1 (6).pdf	Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	20 November 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 WORKSHOP INVOICE.pdf	Invoice	Regular	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 PAYMENT BREAKDOWN_LKK.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 LOO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 CIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 LETTER TO OL.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 MANDATE IA - SJS 7172V - PERFORMANCE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 June 2019
 RE-SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 June 2019
 TP ESTIMATE - MARKED .pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 June 2019
 SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 June 2019
 PRI EMAIL RECEIVED FROM WORKSHOP WITH TP CIA REPORT.mug	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	4 December 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 SJN3141P INSD GIA.PDF	Reports & Statement	GIA Report	RATAN BHOSALE Pragati	4 December 2018