

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

03 DEC 2018

Estimate No. : b1 49322
Date Estimated : 03/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
See Seow Peng (Xu Xiaoping)
42 Pavilion Place

Singapore 658378

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJS7172Y	J721244	26/09/2013	316iA/4	0

DESCRIPTION

To replace rear bumper panel, & reinforcement, carrier & all attachments cause by accident.

Painting on rear bumper panel

To check electrical wiring systems at the rear section for proper function.

Sundries.

VALUE

850 2,550.00

793 882.00

150 177.00

? 80.00

Total Labour 1: **3,689.00**DESCRIPTIONRR BUMPER BOTTOM REINFORCEMENT
REAR BUMPER CENTRE GUIDE
REAR BUMPER CARRIER (ECE)
REAR DECORATIVE STRIP (SPORT LINE)
REAR BUMPER PANEL PRIMED BASIS
RR BUMPER FLAP TOWING EYE PRIMED
REAR PDC HOLDER SET
REAR BUMPER LH SIDE GUIDE
REAR BUMPER RH SIDE GUIDE
REAR SILENCER HEAT SHIELD
DECOUPLING RING PDC TORQUE CONVERTER
(DG/SL) ADHESIVE SET K6QTY PRIC

1	67.75
1	32.90
1	443.70
1	57.00
1	1,127.80
1	43.25
1	23.70
1	58.50
1	58.50
1	34.10
4	5.05
1	53.05

VALUE

? 67.75

? 32.90

? 443.70

? 57.00

de 1,127.80

X 43.25

? 23.70

? 58.50

? 58.50

? 34.10

4x 20.20

? 53.05

Total Parts : **2,020.45**

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49322
Date Estimated : 03/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJS7172Y	J721244	26/09/2013	316iA/4	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 12/12/18 21130 Claim No. _____

Date & Time 12/12/18 21130 Excess S\$ _____

Surveyor's Name Tanfer Sign [Signature]

Surveyor's Tel 9246 5749 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tanfer@lkk.com

No. of Working Days Recommend 3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	3,689.00
Parts	:	2,020.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	399.66
Grand Total	:	6,109.11

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **