

Policy No : VPA/P1777559
Date of Accident : 01 December 2018

Claims Department
AXA Insurance (S) Pte Ltd
8 Shenton Way
#27-01
Singapore 068811


陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD
51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Date : 04 December 2018

Estimate To Repair SKT8087L - Infiniti Q50 2.0T Premium A/T
Chassis No : JN1BCAV37Z0480214

S/No	Quantity	Description	Amount
		Cost	
01	1 pc	front bumper <i>Dee7C47</i>	\$ 620.00
02	1 pc	front bumper side retainer right <i>Bent</i>	\$ 35.00
03	8 ps	front bumper clips @ \$2.00 <i>ner</i>	\$ 16.00
04	1 pc	headlamp right	\$ 1,950.00
05	1 pc	right front fender <i>Bod500</i>	\$ 420.00
06	1 pc	right front fender inner cowling	\$ 85.00
07	6 ps	right front fender inner cowling clips @ \$2.00 <i>11</i>	\$ 12.00
08	1 pc	right front fender 2.0t badge <i>scr</i>	\$ 25.00
09	1 pc	right front shock absorber <i>11</i>	\$ 250.00
10	1 pc	right front lower arm <i>11</i>	\$ 300.00
11	1 pc	right front knuckle arm	\$ 350.00
12	1 pc	right front wheel bearing	\$ 150.00
13	1 pc	right front wheel bearing hub	\$ 380.00
14	1 pc	right front stabilizer link	\$ 65.00
15	1 pc	right front wishbone upper right	\$ 250.00
16	1 pc	right front door <i>100/111</i>	\$ 980.00
17	1 pc	right front door outer chrome moulding right <i>11</i>	\$ 60.00
18	1 pc	right front door hinge top <i>11</i>	\$ 40.00
19	1 pc	right front door hinge bottom <i>11</i>	\$ 40.00
20	1 pc	right front door checker/arrestor <i>11</i>	\$ 25.00
21	1 pc	right rear door <i>50/347</i>	\$ 980.00
22	1 pc	right rear knuckle arm <i>11</i>	\$ 400.00
23	1 pc	right rear wheel bearing <i>11</i>	\$ 150.00
24	1 pc	right rear wheel bearing hub <i>11</i>	\$ 380.00
25	1 pc	right rear fender <i>11</i>	\$ 880.00
		Add 15% 10%	\$ 8,843.00
			\$ 1,326.45
			\$ 10,169.45
		Cost	
26	1 pc	right front wheel tyre <i>50</i>	\$ 500.00
27	1 pc	right front wheel rim <i>C47 950</i>	\$ 1,753.40
28	1 pc	right rear wheel rim <i>C47 950</i>	\$ 1,753.40
29	1 pc	right rear wheel tyre <i>50</i>	\$ 500.00
30	1 pc	rear windscreen sealant <i>11</i>	\$ 60.00



Policy No : VPA/P1777559
Date of Accident : 01 December 2018

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department
AXA Insurance (S) Pte Ltd
8 Shenton Way
#27-01
Singapore 068811

Date : 04 December 2018

Estimate To Repair SKT8087L - Infiniti Q50 2.0T Premium A/T
Chassis No : JN1BCAV37Z0480214

S/No	Quantity	Description	Amount
31	1 pc	<u>Cost</u> rear windscreen inner sponge seal 11	\$ 40.00
		Add 15 %	\$ 4,606.80
			\$ 691.02
			\$ 5,297.82
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 50.00
02		To transfer of front and rear tyre, rim and on wheel balancing.	\$ 11 100.00
03		To check steering geometry and computer wheel alignment.	\$ 80.00
04		To transfer of both right door fittings and perform water seepage test.	\$ 160.00
05		To remove and refit rear windscreen glass.	\$ 11 120.00
06		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 80.00
07		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ 180.00
08		To drop rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	\$ 11 180.00
09		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,400.00
10		Putty and spray painting of the affected portion.	\$ 1,800.00
			\$ 3,950.00
		Total	\$ 19,417.27

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: