

INS. CASE OWNER:

ANDA

CC 3, III 180

H872, T. ha39/

LKK
IDAC

Surveyor:

TAUPIKH

DOI:

ASSIGNMENT

17/12/18

Date / Time:

5/1/18

Registered in Merimen:

8/12/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 3341 K

Claim No.:

HOT 18110953

Name of Insured:

CTOL

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

30/11/2018

Place of Accident:

Km Seng Rd

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L) (YES / NO)

Insured Liability: %

Final ? Yes / No

SEA 5676 B



INSRS:

WSP:

Tel:

Liability:

RMKS:

pml



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

11/12
26

SEA 5676 B - X.

SHC 3341 K. call/mtg 8/05/2018/11/03/18 ; 20/12/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

02/12/18

FILE REVIEWED. OLD REPAIR-BUILDING TP.

SHC 3341 K. call/mtg 8/05/2018/11/03/18 ; 20/12/18

12/12/18

U APPROVED B/L

B/L LIABILITY CLERK

PENDING COR MINISTRATION

PENDING:

TP LOD IN.

22/02/19

TYPE REPORT FOR WARRANT APPROVAL

REPORT DONE

09/08/19

986K WARRANT TO II BY WERIMEN.

II APPROVED WARRANT

15/08/19

ALL DOC IN ORDER. CONFIRMED

AMOUNT PAID AS LOD.

TO CLOS.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS 9,853.70 (3 days) Reduction: 40 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

% 100 (Assessed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS 4,123.46

(LOD REPAIR-BUILDING TP)

Loss of Rental (LOR):

SS (days)

Loss of Use (LOU):

SS 500.00 (510 x 3 days)

OUG. TP LOD at III

Loss of Income (LOI):

SS (5 x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS

Medical:

SS

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

SS

3) Survey fee:

4500.00

Total:

SS 4,983.46

Global Sum SS: —

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 4,983.46

Name 1:

PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N/A)

SS

Name 2:

Payee 3: (Strike if N/A)

SS

Name 3:

16/3/19

Tamplin

III. 787-2 716

From:	Date:
Estimated Cost:	
<u>OD / TP / WS / TP RES / OD RES / EVA / INV / MY</u>	
To Inspect Vehicle No:	
at Workshop n/s	
of	
Insured	
Policy No.	
Claims No.	
Sum Insured:	Excess:
(Client's Record)	
Make of Veh:	

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:				843K.
IDAC Accident Rpt:			Consistent?	Yes or No
GIA / PR Seen:			Consistent?	Yes or No
Est. Repairs:	2	days	Res.:	Yes or No
Lum Sum:	-	%	3 Val:	Yes or No

CA / REV / REP / 24 HRS

Date:	Person Contacted:
-------	-------------------

Vehicle: IN / OUT

Kevin

Veh No: SKA5265 Yr Regn: 2011 New

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 320 CC: 1995

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 117924 T/Radio: Insured / Std / NI / NA

Eng/No:

C/Nr: WBAPG5600UNM26298

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17 R: 1 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Continental*

Front		Rear
R/Bal.	6 mm	R/Bal.
L/Bal.	6 mm	L/Bal.
D.O.I.		D.O.I.

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rekord 36,365

Date / Time	Action / Instruction
-------------	----------------------

[CloseTune], Film Page 633

III.

Date/Time: File Return to?

32

Report Format :

Lump Sum / I.B.E. (\$)

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Free

Therapeutics

54 RS 54

Phonics

Citizens

TOTAL

Add Fee: ☐ Site Insp (\$
☐ Interview (\$
☐ Tech Invs (\$
☐ Weekend (\$

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747775

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

05 DEC 2018

ESTIMATE

Estimate No. : b1 49349
Date Estimated : 04/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Emery Justin Michael Anthony
51 Chai Chee Street
#07-310
Singapore 460051

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA5626B	NM26298	14/03/2011	320i/4 (A)	0

DESCRIPTION

To replace rear bumper & all attachments cause by accident.

VALUE
850 2,550.00

Painting on rear bumper panel

934 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries. *me*

? 80.00

Total Labour 1: 3,845.00

DESCRIPTION

RR BUMPER CARRIER
RR BUMPER CTR GUIDE
RR BUMPER TAILLAMP RH GUIDE
RR BUMPER CTR BOTTOM GUIDE
RR BUMPER RH GUIDE
RR BUMPER TOW HOOK COVER
RR BUMPER (PDC)
SET MOUNTS PDC SENSOR RR
RR RH FENDER TAIL LAMP
RR BUMPER BREATHER COVERING
DECOUPLING RING PDC TORQUE CONVERTE
PDC sensor

QTY	PRIC	VALUE
1	434.80	434.80
1	32.40	32.40
1	31.10	31.10
1	61.20	61.20
1	58.50	58.50
1	38.95	38.95
1	1,136.80	1,136.80
1	56.85	56.85
1	387.35	387.35
1	39.35	39.35
4	5.05	20.20
1	368.80	368.80

Total Parts : 2,666.30

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401519W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

389, Rempang Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49349
Date Estimated : 04/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA5626B	NM26298	14/03/2011	320i/4 (A)	0

Call to 111 for more information or visit our website
12/12/18 @ 4:15pm
Tangha
9749 8141
wp
to the members in
03 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	3,845.00
Parts	:	2,666.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	455.79
Grand Total	:	6,967.09

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

4,511.30

Print Received Message

This mail is associated with :

***SKA5626B (MCT18110953)**
[SHC3341K]

TP
JUSTIN EMERY
Nov 30 2018 7:00AM

[-]
Performance Motors Limited

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 07/03/2019 17:20 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4483.46) - SKA5626B - Claim Handler: Zuhaidah Bte Samsuri

Approved:4483.46.

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

SIME DARBY INSURANCE BROKERS (SINGAPORE) PTE. LTD.
300 Beach Road
#12-01/02 The Concourse
Singapore 199597
Tel: 6222 2244 Fax: 6294 8810

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

SIME MOTOR PRIVATE
Comprehensive

Certificate No. B 27072194 SMP

Excess: SGD1,000

1. **Index Mark and Registration Number of Vehicle**
SKA5626B

2. **Name of Policyholder**
Emery Justin Michael Anthony

3. **Effective Date of the Commencement of Insurance for the purposes of the Act**
14/03/2018

4. **Date of Expiry of Insurance**
13/03/2019

5. **Persons or Classes of Persons entitled to drive***

Emery Justin Michael Anthony

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. **Limitations as to use***

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT PERFORMANCE MOTORS LTD OR AT ANY WORKSHOP OF YOUR CHOICE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers


for Chief Executive Officer


 Libration Number: S2685167Z
 Name: EMERY JUSTIN MICHAEL ANTHONY
 Birth Date: 19 Apr 1967
 Issue Date: 26 May 2003


REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2685167Z



EMERY JUSTIN MICHAEL ANTHONY

Race: CAUCASIAN
 Date of Birth: 19-04-1967 Sex: M
 Country of Birth: ENGLAND




 S2685167Z

Nationality: BRITISH
 Blood Group: B- Date of issue: 24-05-1998

70 LENTOR LOOP
 13-03
 SINGAPORE 789099



India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
Attention: Motor Claims



MCT/18110953
Ade
2/219
"Without Prejudice"

Your Ref :

Our Ref :

Date :

24 January 2019

Subject :

ACCIDENT INVOLVING VEHICLES SKA5626B & SHC3341K ON 30.11.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	: S\$	4123.46
Loss of use	: S\$	360.00 (S\$120.00 x 3 days)
Total	: S\$	4483.46

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Performance Motors
Limited
1800-Call-BMW
(1800-2255-269)
www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel AfterSales:
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales:
6319 0527
Fax 6479 6624

280
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel AfterSales:
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401559W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SKA 5626B & SHC 3341K ON 30/11/18

I, Emery Justin Michael Anthony owner of Vehicle Registration No. SKA 5626B
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all
documents whatsoever in relation to this matter and to accept and receive any payment
due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement
amount in respect of such claim shall constitute the full discharge of my claim in respect of
such loss and damage.

Signed by:

Name: JUSTIN MICHAEL ANTHONY EMERY

(Date)

30/11/18

NRIC No.: S26851672

In the presence of:

KEVIN LEONG WAI KIT
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Name :

(Date)

30/11/18

NRIC No.:



INDIA
INTERNATIONAL
INSURANCE
PTE LTD
Singapore 159941

INDIA INTERNATIONAL INSURANCE PTE LTD

Co Reg No: 1907037NCR | GST Reg No: M20070000X
#11 Cecil Street | #04-01 | #05-01 | #06-02 | Raffles Building | Singapore 048711
Mobile: 9651 6347 & 100 | Email: claims@ii.com.sg
Fax: 6543 62244174 | Website: www.ii.com.sg

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: U0518110933
Claimant Ref: 9KA 56763

We/I, PERFORMANCE MOTORS LIMITED ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 4,123.46 (repair cost), S\$ 360.00 (loss of use/rental), S\$ — (search fee), vehicle no. 9KAS6763 that was damaged pursuant to the accident which occurred on 20/11/2018 (date) at KIM SENG ROAD (location) involving vehicle no. 9KCS341K (insured vehicle). This is pursuant to the inspection conducted on 17/12/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner EMERY JUSTIN MICHAEL ANTHONY ("the third party claimant") of vehicle no. 9KAS6763 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to 9KAS6763 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4,483.46 to PERFORMANCE MOTORS LIMITED.

Dated this 15 day of 03 20 19

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

Wong Yit Loong
Performance Motors Limited
303 Alexandra Road
Singapore 159941
Signed by: [Signature] (With chop)

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



UTF

Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933

Performance Motors Limited

A member of the Sime Darby Group
CO. Reg. No. 197401559W GUT Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kangong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1323759

Date IN : 17/12/2018

Cust. Svc. Advisor: Kevin Leong Wai Kit

Page No. : 1 of 2

Invoice Number : 2058009 / WSB

Invoice Date : 23/01/2019

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Emery Justin Michael Anthony
51 Chai Chee Street
#07-310

Singapore 460051

- INVOICE TO - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.
SKA5626B

CHASSIS NO.
NM26298

REGN. DATE
14/03/2011

MODEL
320I/4 (A)

MILEAGE
117974

- - - - LABOUR 1 - - - -

To replace right tail lamp, rear bumper and attachments
including to remove and install body parts in order
to carry out painting job.

To respray rear bumper.

To check electrical wiring systems and lightings at the
rear section for proper function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 30.11.2018. 3RD PARTY CAR : SHC3341K.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO
CONSULTANTS PTE LTD ON 17.12.2018 AT 4.15 PM.
AUTHORISED REPAIR BY MR VIC ALPEH FROM LKK AUTO
CONSULTANTS PTE LTD ON 12.12.2018 VIA E-MAIL.

PROPOSE LOSS OF USE = \$120X3. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

Total Labour 1: 2,014.00

- - - - PARTS - - - -

RR BUMPER (PDC)
DECOUPLING RING PDC TORQUE CONVERTE
RR BUMPER RH GUIDE
RR RH FENDER TAIL LAMP
BUMPER PDC SENSOR (SCHWARZ)- ELBOW

Qty	Retail Price	NETT
1	1,136.80	1,136.80
4	5.05	20.20
1	58.50	58.50
1	387.35	387.35
1	236.85	236.85

Total Parts : 1,839.70

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No M2-0020001-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159943
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1323759	Page No. : 2 of 2
Date IN : 17/12/2018	Invoice Number : 2058009 / WSB
Cust. Svc. Advisor: Kevin Leong Wai Kit	Invoice Date : 23/01/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

Labour Charges :	1,934.00	Total Labour & Parts Charges :	S\$ 3,853.70
Parts Charges :	1,839.70	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	80.00	Invoice Total Amount Exclude GST :	S\$ 3,853.70
		GST @ 7% :	S\$ 269.76
		Invoice Total Amount Include GST :	S\$ 4,123.46

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 4,123.46**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Dec 2018 Edit Reg		17 Dec 2018 00:00 Edit Adj Rpt	S\$3,853.70 Edit Estimates	S\$3,853.70 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	EMERY JUSTIN MICHAEL ANTHONY, ID: 526851672								
Vehicle Reg. No.:	SKA5626B	Date of Loss:	30/11/2018 07:00 - :59 [92 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18110953	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC3341K	Policy No. (Claimant):	B27072194SMP						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/12/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (07/03/2019): Alert - Adj Mandate Approved (S\$4483.46) - SKA5626B - Claim Handler: Zuhaidah Bt... - III_SG (07/12/2018): Alert - Adj Mandate Approved (S\$0.00) - SKA5626B - Claim Handler: Zuhaidah Bte S...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKA5626B (MCT18110953)
[SHC3341K]
TP
EMERY JUSTIN MICHAEL ANTHONY
Nov 30 2018 7:00AM
[COMFORT TRANSPORTATION PTE LTD]
Performance Motors Limited

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/02/19 10:56	Odometer Reading	1	Load JPG	☒
2	22/02/19 10:56	Chassis Number	1	Load JPG	☒
3	22/02/19 10:56	General View	1	Load JPG	☒
4	22/02/19 10:56	General View	1	Load JPG	☒
5	22/02/19 10:56	General View	1	Load JPG	☒
6	22/02/19 10:56	General View	1	Load JPG	☒
7	22/02/19 10:56	General View	1	Load JPG	☒
8	22/02/19 10:56	General View	1	Load JPG	☒
9	22/02/19 10:56	General View	1	Load JPG	☒
10	22/02/19 10:56	General View	1	Load JPG	☒
11	22/02/19 10:56	General View	1	Load JPG	☒
12	22/02/19 10:56	General View	1	Load JPG	☒
13	22/02/19 10:56	General View	1	Load JPG	☒
14	22/02/19 10:56	General View	1	Load JPG	☒
15	22/02/19 10:56	General View	1	Load JPG	☒
16	22/02/19 10:56	General View	1	Load JPG	☒
17	22/02/19 10:56	Reinspection Photo	1	Load JPG	☒
18	22/02/19 10:56	Reinspection Photo	1	Load JPG	☒
19	22/02/19 10:56	Reinspection Photo	1	Load JPG	☒

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/12/18 09:46	TP ESTIMATE	1	Load PDF	
2	05/12/18 09:46	TP GIA REPORT	1	Load PDF	
3	23/12/18 17:40	TP ESTIMATE - MARKED	1	Load PDF	
4	25/02/19 15:06	WORKSHOP INVOICE	1	Load PDF	
5	25/02/19 15:06	LOD	1	Load PDF	
6	14/03/19 16:27	AUTHORISATION TO ACT FORM	1	Load PDF	
7	14/03/19 16:27	DISCHARGE VOUCHER	1	Load PDF	

No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	06/12/18 08:57	Singapore Accident Statement	1	Load PDF	
2	21/02/19 16:14	Letter of Demand from Third Party TPD LOD FROM PERFORMANCE MOTORS LTD (SKA5626B)	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LXX Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHC3341K (Insd veh)	Model:	BMW 320i 2.0 (A)
	SKA5626B (TP veh)		
Date of Accident:	30/11/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	6,967.09
Final Repair Cost	:	\$	4,123.46
Loss of Use	:	\$	360.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,483.46

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: 27

BOLA Liability: 100 (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 4,483.46
2)		:	\$

JOANNE LEE KHANG MIN

14 Mar
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18021872/T1HA3Q2

Date: 14/03/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No : SKA5626B

Insured Vehicle No : SHC3341K

Date of Loss: 30/11/2018

Nature of Claim: TP

Claim No: MCT18110953

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKA5626B

Make & Model: BMW 320i, 2.0 (A)

Reg. Date: 14/03/2011 (Man. Year: 2010)

Colour: Beige

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: A333I787N46B20BD

Chassis No: WBAPG56000NM26298

Odometer: 117974 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,746.30	1,919.70	826.60	30.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,765.00	1,934.00	1,831.00	48.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,511.30	3,853.70	2,657.60	40.82
+ GST 7.00/7.00% (S\$)	455.79	269.76	186.03	40.81
Nett Amount (S\$)	6,967.09	4,123.46	2,843.63	40.82
+ Loss of Use (3.0 x S\$120.00/day) (S\$)		360.00		
Nett Liability (S\$)		4,483.46		

INSPECTION

Date of Assignment: 17/12/2018

Date Inspected: 17/12/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Feb 2019)	
Parts:	N/A	BMW 320I 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA5626B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*RR BUMPER CARRIER	Not Necessary	434.80 FS	*- FS
3	1		*RR BUMPER CTR GUIDE	Not Necessary	32.40 FS	*- FS
4	1		*RR BUMPER TAILLAMP RH GUIDE	Not Necessary	31.10 FS	*- FS
5	1		*RR BUMPER CTR BOTTOM GUIDE	Not Necessary	61.20 FS	*- FS
6	1		*RR BUMPER RH GUIDE	Necessary	58.50 FS	*58.50 FS
7	1		*RR BUMPER TOW HOOK COVER	Not Necessary	38.95 FS	*- FS
8	1		*RR BUMPER (PDC)	Deformed	1,136.80 FS	*1,136.80 FS
9	1		*SET MOUNTS PDC SENSOR RR	Not Necessary	56.85 FS	*- FS
10	1		*RR RH FENDER TAIL LAMP	Cracked	387.35 FS	*387.35 FS
11	1		*RR BUMPER BREATHER COVERING	Not Necessary	39.35 FS	*- FS
12	4		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	20.20 FS	*20.20 FS
13	1		*PDC SENSOR	Distorted	368.80 FS	*236.85 FS
Total Parts (\$\$)					2,746.30	1,919.70

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER & ALL ATTACHMENTS CAUSE BY ACCIDENT	New	2,550.00	850.00
2	PAINTING ON REAR BUMPER PANEL	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			3,765.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >