

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

05 DEC 2018

E S T I M A T E

Estimate No. : b1 49349 Page No. : 1 of 5
Date Estimated : 04/12/2018
Prepared By : Kevin Leong Wai Kit

- ESTIMATE REPAIR FOR -
Emery Justin Michael Anthony
51 Chai Chee Street
#07-310

Singapore 460051

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA5626B	NM26298	14/03/2011	320i/4 (A)	0

DESCRIPTION

To replace rear bumper & all attachments cause by accident.

VALUE

850 2,550.00

Painting on rear bumper panel

934 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150. 177.00

Sundries.

? 80.00

Total Labour 1: **3,845.00**DESCRIPTIONQTYPRICVALUE

RR BUMPER CARRIER

1 434.80

? 434.80

RR BUMPER CTR GUIDE

1 32.40

? 32.40

RR BUMPER TAILLAMP RH GUIDE

1 31.10

? 31.10

RR BUMPER CTR BOTTOM GUIDE

1 61.20

? 61.20

RR BUMPER RH GUIDE

1 58.50

nei 58.50

RR BUMPER TOW HOOK COVER

1 38.95

mis 38.95

RR BUMPER (PDC)

1 1,136.80

de 1,136.80

SET MOUNTS PDC SENSOR RR

1 56.85

? 56.85

RR RH FENDER TAIL LAMP

1 387.35

an 387.35

RR BUMPER BREATHER COVERING

1 39.35

? 39.35

DECOUPLING RING PDC TORQUE CONVERTE

4 5.05

an 20.20

PDC sensor

1 368.80

dis 368.80

Total Parts : **2,666.30**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49349
Date Estimated : 04/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA5626B	NM26298	14/03/2011	320i/4 (A)	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 17/12/18 04:50pm Excess S\$ _____

Surveyor's Name Tayfun Sign _____

Surveyor's Tel 9249 8249 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's Email tayfun@lkkambro.com

Days Recommended 03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Labour 1	:	3,845.00
Parts	:	2,666.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	455.79
Grand Total	:	6,967.09

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **