LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building

51 Ubi Ave 1 #01-25 78 Shenton Way #08-16 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Attn: Mohd Zawaye, Norsazani Date: 02 Jan 2019

Preliminary Advice

Vehicle No : SLS1885P Accident Date : 02/12/2018 Make : AUDI A3 Policy No. : 1700050003 **Assignment Date** : 05/12/2018 **Excess** : S\$0.00 Date of Inspection : 04/12/2018 Est. Duration of Repair : 15 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	59,706.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	42,865.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	8,626.00

Total :S\$ 51,491.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	136,000.00
Pre-Accident Value	:S\$	95,000.00
COE / PARF Rebate	:S\$	40,995.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	95,005.00
Margin for Repair		54,005.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: SUPPLEMENTARY AMOUNT IS \$ 939.00.