

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 05 Dec 2018

Preliminary Advice

Vehicle No	: SLS1885P	Accident Date	: 02/12/2018
Make	: AUDI A3	Policy No.	: 1700050003-01
Assignment Date	: 05/12/2018	Excess	: S\$0.00
Date of Inspection	: 04/12/2018	Est. Duration of Repair	: 15 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	58,767.00
Revised Amount	:S\$	41,926.00
Check Items (Estimated)	:S\$	8,626.00
Total	:S\$	50,552.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	136,000.00
Pre-Accident Value	:S\$	95,000.00
COE / PARF Rebate	:S\$	40,995.00
Salvage Value	:S\$	
Margin for Repair (New For Old Value)	:S\$	95,005.00
Margin for Repair		54,005.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : WE ARE PENDING REPAIR COST FROM REPAIRER.