



Quotation For FBC3737Z

No	Parts	Price
/ 1	Exhaust Pipe / BT	\$1,700.00
/ 2	Signal (2 Set) / B.S.	\$80.00
/ 3	Crash Bar Repair x / BT	\$80.00
/ 4	Footrest Bracket / BR.	\$220.00
5	Handlebars / BT.	\$120.00
6	Front Fork Alignment /	\$120.00
/ 7	Clutch Lever (left) / cut .	\$40.00
/ 8	Mirror (left) / cut .	\$60.00
9	Paintwork for Tank Bike .	\$550.00
10	Labour	\$320.00
11	Towing	\$80.00
	Total	\$3,370.00

\$1200

—

~~1~~ 2

258

✗

— labour

1

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

350

180

~~50~~ 50

11/4/19

8799 c940

John.

Surveyor

Mohd Rasol (LKK Auto Consultants) 67418434

3 Days. (4)

part by part.

After repair photos.

Gino Qiang - 82880262

05/12/18.

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: