

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NGO SAU WEI SHAWN

Date: 07 Dec 2018

Preliminary Advice

Insured Vehicle No : FW2782X

TP Vehicle No : FBC3737Z

Make : HONDA CB400A8J M

Date of Inspection : 05/12/2018

Inspection At : O.m. Motor Services (HQ)
10 KAKI BUKIT ROAD 2, #01-36
Singapore 417868

Accident Date : 29/11/2018

Assignment Date : 04/12/2018

Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s & n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,370.00
Revised Amount	:S\$	1,030.00
Check Items (Estimated)	:S\$	1,920.00
Total	:S\$	2,950.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP