

ASS. REC. BY:

REF:

CS/FCL18021888 / Kvb2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

WS Serena Lee

of

FCL

Date/Time: 04-12-2018 5:28 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMA 3528R

Insured:

SHC 7009U

at Workshop m/s:

Hui Yang Motor

Tel:

6451 5752

of

Blk 176 Sin Ming Drive #04-02

Policy No:

Claim No:

D18U08560MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 01-12-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

05-12-2018 9:11am

Person Contacted:

Marcus

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SMA 3528R - X

SHC 7009U - NS / INC 1003743 / FN

DUA: 28102610

12/12/18

Email preli revised to FCI

19/12

L1/Lp 8365a email & confirm (Red 2797.9, 4370)

REF: FCL

ASSIGNMENT

From:

Date: 11/12/2018

Estimated Cost:

OD ☒ / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMA 3528R

at Workshop m/s

Hui Yang

of

176 Sin Ming Dr #04-02

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

88dc

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SMA 3528R Yr Regn: 06 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle Wagon 1496

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 58888 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GP7 1210712

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dayton

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 1/12/18

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 11/12/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 19 DEC 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2) 19/12 - typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Report Format:

CWS

Lump Sum / I.B.I. (\$

3650/-

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

145

50

50

19

264



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18008560MFSH

Our ref: CS/FCI18021888/Kvb

Date : 12/12/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SMA 3528R


We thank for your instruction on 4/12/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/12/2018 at the premises of M/s HUI YANG MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$6,447.92
Revised Estimate Amount	: S\$4,583.92
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	04-12-2018	Our Ref No. D18008560MFSH
Accident Date	01-12-2018	Claim Type. Third Party
Insured Vehicle	SHC7009U	Third Party Vehicle. SMA3528R
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	MARCUS LOH	
Contact No.	6451 5752/ 0	Fax No. 6451 4658
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 12 December 2018 1:23 PM
To: 'CWS Motor Claims'
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008560MFSH/1, SMA 3528R
Attachments: SMA 3528R PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SMA 3528R
Date of survey: 11/12/2018
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 5 December 2018 9:13 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Serener@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008560MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 4 December, 2018 5:28 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Serener@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008560MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

30/11/2018

Owner: MKM CAR LEASING PTE LTD

ESTIMATE TO REPAIR HONDA SHUTTLE - SMA3528R

1pc	rear tailgate
1pc	rear tailgate "H" logo
1pc	rear tailgate "SHUTTLE" emblem
1pc	rear tailgate "HYBRID" emblem
1pc	rear tailgate inner lock
1pc	rear tailgate inner rubber
1pc	rear tailgate inner garnish
1pc	rear bumper
2pcs	rear bumper side retainer @\$26.50
2pcs	rear bumper reflector @\$75.00
2pcs	rear bumper reflector garnish @\$85.50
1pc	rear bumper towing cover
1pc	rear end panel
1pc	rear end panel outer sensor
1pc	rear end panel inner sensor
1pc	rear end panel inner garnish

Bt	\$ 1,193.70	✓
Ln	\$ 32.30	—
Ln	\$ 55.00	—
Ln	\$ 78.90	—
Net	\$ 189.40	✓
Net/11	\$ 168.50	—
Ln	\$ 320.00	X
Bu	\$ 1,150.60	—
Ln	\$ 53.00	X
Ln	\$ 150.00	X
Ln	\$ 171.00	X
Net	\$ 85.00	✓
Bt	\$ 601.50	✓
Ln	\$ 90.50	X
Ln	\$ 85.00	X
Ln	\$ 285.50	X

less 20%

\$ 4,709.90
\$ 941.98
\$ 3,767.92

1set	rear parking sensor
1set	rear windscreen glass moulding
1set	rear number plate & casing

Net s.nett	\$ 280.00	20052
Ln s.nett	\$ 100.00	—
Ln s.nett	\$ 50.00	X

remove & refit rear windscreen glass

sealant

wiring

tuffkote

spray painting

labour charges

Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Any supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 150.00 1201
\$ 80.00 4052
\$ 120.00 201
\$ 100.00 601
\$ 900.00 600
\$ 900.00 600
\$ 6,447.92





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18021888/Kvbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-12-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7009U	Veh. Inspected	SMA 3528R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008560MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	04/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GP71210712	Colour	METALLIC GREY	
Odometer	58888	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	DAYTON	8 mm	
L/H Front Tyre	185/60 R15	DAYTON	8 mm	
R/H Rear Tyre	185/60 R15	DAYTON	8 mm	
L/H Rear Tyre	185/60 R15	DAYTON	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/12/2018	Inspection Date	11/12/2018	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 3528R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BENT	1,193.70	1,193.70
1	REAR TAILGATE "H" LOGO	NECESSARY	32.30	32.30
1	REAR TAILGATE "SHUTTLE" EMBLEM	NECESSARY	55.00	55.00
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	78.90	78.90
1	REAR TAILGATE INNER LOCK	DENTED	189.40	189.40
1	REAR TAILGATE INNER RUBBER	DENTED / DISTORTED	168.50	168.50
1	REAR TAILGATE INNER GARNISH	SERVICEABLE	320.00	-
1	REAR BUMPER	BUCKLED	1,150.60	1,150.60
2	REAR BUMPER SIDE RETAINER @\$26.50	SERVICEABLE	53.00	-
2	REAR BUMPER REFECTOR @\$75.00	SERVICEABLE	150.00	-
2	REAR BUMPER REFECTOR GARNISH @\$85.50	SERVICEABLE	171.00	-
1	REAR BUMPER TOWING COVER	DENTED	85.00	85.00
1	REAR END PANEL	BENT	601.50	601.50
1	REAR END PANEL OUTER SENSOR	SERVICEABLE	90.50	-
1	REAR END PANEL INNER SENSOR	SERVICEABLE	85.00	-
1	REAR END PANEL INNER GARNISH	SERVICEABLE	285.50	-
	LESS 20% DISCOUNT		-941.98	-710.98
			3,767.92	2,843.92
SPECIAL NETT ITEMS				
1	SET REAR PARKING SENSOR (SN)	DENTED	280.00	200.00
1	SET REAR WINDSCREEN GLASS MOULDING (SN)	NECESSARY	100.00	100.00
1	SET REAR NUMBER PLATE & CASING (SN)	SERVICEABLE	50.00	-
1	SEALANT (SN)	NECESSARY	80.00	40.00
			510.00	340.00
LABOUR				
	REMOVE & REFIT REAR WINDSCREEN GLASS.		150.00	120.00
	WIRING.		120.00	20.00
	TUFFKOTE.		100.00	60.00
	SPRAY PAINTING.		900.00	600.00

Report Ref No. CS/FCI18021888/Kvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES.		900.00	600.00
			2,170.00	1,400.00
	GRAND TOTAL		6,447.92	4,583.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,650.00

Report Ref No. CS/FC118021888/Kvbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.