



SMRT AUTOMOTIVE SERVICES PTE LTD
60 Woodlands Industrial Park E4, SINGAPORE 757705

To: PUB

Vehicle No: YN5532D

Model: ISUZU NJR85

Date: 30/11/2018

Quotation

S/No.	Description	Qty	Price
1	Front Wind Screen	1	\$ <i>new</i> 1,587.00
2	Front Wind Screen Rubber Top	1	\$ <i>new</i> 121.00
3	Front Wind Screen Rubber Bottom	1	\$ <i>new</i> 90.00
4	Front Wiper Linkage Assy	1	\$ <i>?</i> 163.00
5	Front Wiper Arm RH	1	\$ <i>bf</i> 55.00
6	Front Wiper x 1 set	1	\$ <i>ant</i> 45.00
7	Front Wiper Motor	1	\$ <i>?</i> 388.00
8	Front Wiper Noisse RH	1	\$ <i>?</i> 35.00
9	Front Big Panel	1	\$ <i>bf</i> 634.00
10	Front Big Panel Logo (ELF)	1	\$ <i>new</i> 30.00
11	Front Big Panel Logo (ISUZU)	1	\$ <i>new</i> 128.00
12	Floor Panel	1	\$ <i>Ry</i> 2,507.00
13	Front Giller	1	\$ <i>new</i> 346.00
14	Front Giller Clip x 8 clip (\$8 per pc)	1	\$ <i>new</i> 64.00
15	Front Side Panel RH	1	\$ <i>new</i> 211.00
16	Front Head Lamp RH	1	\$ <i>new</i> 347.00
17	Front Head Lamp LH	1	\$ <i>X</i> 347.00
18	Front Side Lamp RH	1	\$ <i>?</i> 105.00
19	Front Mounting RH	1	\$ <i>?</i> 96.00
20	Front Mounting LH	1	\$ <i>?</i> 96.00
21	Front Bumper	1	\$ <i>Ry</i> 382.00
22	Front Door Pallar Outer RH	1	\$ <i>Ry</i> 205.00
23	Front Door Pallar 2nd Layer RH	1	\$ <i>Ry</i> 475.00
24	Front Door Pallar 3rd Layer RH	1	\$ <i>Ry</i> 265.00
25	Front Step Panel RH	1	\$ <i>X</i> 152.00
26	Front Dash Board Assy	1	\$ <i>?</i> 1,023.00

photo

27	Front Steering Column	1	\$?	1,302.00
28	Front Steering Box	1	\$?	2,200.00
29	Front Steering Key	1	\$?	480.00
30	Air Con Blower Assy	1	\$?	496.00
31	Air Con Discharge Pipe	1	\$?	315.00
32	Air Con Suction Pipe	1	\$?	403.00
33	Front Brake Air Booster	1	\$?	438.00
34	Brake Master Pump	1	\$?	404.00
35	IU Bracket	1	\$ <i>rev</i>	40.00
To supply labour cost				
1	Front Door RH PUB Logo And Front Panel Sticker	-	\$ <i>x</i>	120.00
2	To Top Up Brake Fluid - 4L	-	\$?	30.00
3	Towing Fee	-	\$ <i>80</i>	150.00
4	To Check Wiring System	-	\$ <i>30</i>	80.00
5	To Remove And Refix Front Wind Screen	-	\$ <i>120</i>	200.00
6	To Remove And Refix Dash Board Box <i>photo</i>	-	\$ <i>200?</i>	500.00
7	To Remove And Refix Steering Column And Steering Box	-	\$ <i>120 ?</i>	350.00
8	To Remove And Refix Air Con Blower Assy <i>photo</i>	-	\$ <i>100</i>	300.00
9	To Top Up Air Con Gas	-	\$ <i>?</i>	80.00
10	To Remove & Refix Brake Booster And Master Pump <i>photo</i>	-	\$ <i>100?</i>	250.00
11	To Remove & Refix Front Mounting RH & LH <i>photo</i>	-	\$ <i>120?</i>	200.00
12	To Remove And Refix Wiper Linkage And Motor <i>photo</i>	-	\$ <i>80?</i>	150.00
13	To Replace And knocking, welding front accident, portion front panel, floor panel Front Pallar Outer, 2nd layer, 3 layer, Bumper, Door RH and centre pallar RH	-	\$ <i>800</i>	3,000.00
14	To Respary, Front Portion, Front Panel, Door RH, Pallar Outer, Pallar Outer, 2nd, 3rd Layer, Side Panel RH, Giller, Bumper & Center Pallar RH	-	\$ <i>800</i>	2,000.00
Remarks: Any additional parts or pricing will be informed after dismantle parts for further check (if needed)			Total Charges:	\$ 23,385.00
			GST	\$ 1,636.95
			Amount Payable:	\$ 25,021.95

SMRT Automotive Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749

5/12/18.

- WP

Resurvey after repair

sure@lkkauto.com

taufik@lkkauto.com

8 days