

**Best regards,**

**Justin Ee**

**Workshop Executive**

**BW Workshop Services Pte Ltd - [www.bw.com.sg](http://www.bw.com.sg)**

**Venture Cars Pte Ltd - [www.venturecars.com.sg](http://www.venturecars.com.sg)**

**30 Ubi Road 4 Singapore 408615**

**Main: 6289 8800 / Direct Line : 6692 0139 /**

**Fax: 6858 2120 / HP : 9731 8883 Email [justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)**

On Wed, 24 Apr 2019 at 15:54, Justin Ee <[justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)> wrote:

Hi Guo Qiang,

Any news from your side?

Please kindly advise.

Thank you.

**Best regards,**

**Justin Ee**

**Workshop Executive**

**BW Workshop Services Pte Ltd - [www.bw.com.sg](http://www.bw.com.sg)**

**Venture Cars Pte Ltd - [www.venturecars.com.sg](http://www.venturecars.com.sg)**

**30 Ubi Road 4 Singapore 408615**

**Main: 6289 8800 / Direct Line : 6692 0139 /**

**Fax: 6858 2120 / HP : 9731 8883 Email [justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)**

On Wed, 10 Apr 2019 at 15:42, Justin Ee <[justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)> wrote:

Hi Guo Qiang,

Good day,

As we spoken few days ago,

Please kindly update us when we can close the case, as this case is still pending for Mr Guo Qiang to resurvey - hybrid battery.

Please kindly advice.

Thank you.

**Best regards,**

**Justin Ee**

**Workshop Executive**

**BW Workshop Services Pte Ltd - [www.bw.com.sg](http://www.bw.com.sg)**

**Venture Cars Pte Ltd - [www.venturecars.com.sg](http://www.venturecars.com.sg)**

**30 Ubi Road 4 Singapore 408615**

**Main: 6289 8800 / Direct Line : 6692 0139 /**

**Fax: 6858 2120 / HP : 9731 8883 Email [justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)**

On Wed, 3 Apr 2019 at 12:26, Justin Ee <[justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)> wrote:

Hi Mr Guo Qiang,

Good day,

Any update of finalize states?

Please kindly assist,

Thank you.

**Best regards,**

**Justin Ee**

**BW Workshop Services Pte Ltd**

**30 Ubi Road 4 Singapore 408615**

**Main: 6289 8800 / Direct Line : 6692 0139 /**

**Fax: 6858 2120 / HP : 9731 8883 Email [justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)**

On Tue, 26 Mar 2019 at 09:49, Justin Ee <[justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)> wrote:

Hi Guo Qiang,

Good day,

Any update for finalize states?

Kindly assist.

Thank you.

**Best regards,  
Justin Ee  
BW Workshop Services Pte Ltd**

**30 Ubi Road 4 Singapore 408615**

**Main: 6289 8800 / Direct Line : 6692 0139 /**

**Fax: 6858 2120 / HP : 9731 8883 Email [justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)**

On Thu, 21 Mar 2019 at 19:20, Justin Ee <[justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)> wrote:

Hi Guo Qiang,

Good day,

Any update of finalize states?

Kindly assist.

Thank you. =)

**Best regards,  
Justin Ee  
BW Workshop Services Pte Ltd**

**30 Ubi Road 4 Singapore 408615**

**Main: 6289 8800 / Direct Line : 6692 0139 /**

**Fax: 6858 2120 / HP : 9731 8883 Email [justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)**

On Wed, 13 Mar 2019 at 10:56, Justin Ee <[justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)> wrote:

Hi Guo Qiang,

Noted with thanks a lot, hope to hear you soon.

Thank you.

**Best regards,  
Justin Ee  
BW Workshop Services Pte Ltd**

**30 Ubi Road 4 Singapore 408615**

**Main: 6289 8800 / Direct Line : 6692 0139 /**

**Fax: 6858 2120 / HP : 9731 8883 Email [justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)**

On Wed, 13 Mar 2019 at 10:55, Guo Qiang (LKKAuto) <[GuoQiang@lkkauto.com](mailto:GuoQiang@lkkauto.com)> wrote:

Hi Justin,

I will finalize with you asap.

Regards,

Guo Qiang

**From:** Justin Ee [mailto:[justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)]

**Sent:** Tuesday, 12 March, 2019 1:23 PM

**To:** Guo Qiang (LKKAuto)

**Cc:** Admin A; assignments; Vic (LKKAuto); Derek Low

**Subject:** Re: (TP) Claim- Accident Involving SMF4507T & SCU8992M LKK REF  
CC4/EQI18021899/Ghb3

Hi Guo Qing,

Good day,

Any update and the amount is same with you?

Please kindly assist it, this case is under 2018 we need to close file as soon as possible.

Thank you.

**Best regards,  
Justin Ee  
BW Workshop Services Pte Ltd**

**30 Ubi Road 4 Singapore 408615**

**Main: 6289 8800 / Direct Line : 6692 0139 /**

**Fax: 6858 2120 / HP : 9731 8883 Email [justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)**

On Sat, 9 Mar 2019 at 10:33, Justin Ee <[justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)> wrote:

Hi Guo Qiang,

Good day,

Please kindly finalize of vehicle SMF 4507 T.

This case is under 2018 - December. Please kindly refer to our attach file and below we had courted.

Parts : \$16,684.16 - After -20%

Labour : \$4,350.00

-----  
**Total : \$21,034.16 - 14 Days (Before GST)**  
-----

Please kindly assist and get back to us as soon as possible.

Thank you.

**Best regards,  
Justin Ee  
BW Workshop Services Pte Ltd**

**30 Ubi Road 4 Singapore 408615**

**Main: 6289 8800 / Direct Line : 6692 0139 /**

**Fax: 6858 2120 / HP : 9731 8883 Email [justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)**

From: **Vic (LKKAuto)** <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>

Date: Tue, 11 Dec 2018 at 11:50

Subject: RE: (TP) Claim- Accident Involving SMF4507T & SCU8992M LKK REF  
CC4/EQI18021899/Ghb3

To: [syafirah@bw.com.sg](mailto:syafirah@bw.com.sg) <[syafirah@bw.com.sg](mailto:syafirah@bw.com.sg)>

Cc: Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>, Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>

Without Prejudice

Dear Sir/Madam,

Please find attached estimate as requested.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Error! Filename not specified.** *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Nur Syafirah [<mailto:syafirah@bw.com.sg>]  
**Sent:** Wednesday, December 5, 2018 9:51 AM  
**To:** Janet Tan <[janet.tan@eginsurance.com.sg](mailto:janet.tan@eginsurance.com.sg)>  
**Subject:** Re: (TP) Claim- Accident Involving SMF4507T & SCU8992M

Hi Janet,

Noted of the email for future PRS.

Kindly engage **LKK Auto Consultants** for the PRS.

Thank you.

Best regards,  
Nur Syafirah

BW Workshop Services Pte Ltd

30 Ubi Road 4 Singapore 408615

Main: 6289 8800 Fax 6858 2120 Email [syafirah@bw.com.sg](mailto:syafirah@bw.com.sg)

On Wed, 5 Dec 2018 at 09:03, Janet Tan <[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)> wrote:

***Without Prejudice***

***Save As To Costs***

Dear Syafirah,

For pre repair survey request, please email to [eqiprs@eqinsurance.com.sg](mailto:eqiprs@eqinsurance.com.sg)

Our insured has reported. Liability is cleared. We can agree on direct settlement.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please **revert within 2 working days** if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

<b>1) AJAX Inspection Services Pte Ltd</b>  Tel: 6255 0808  Fax: 6849 9155	<b>2) Automobile Inspection Services Pte Ltd</b>  Tel: 6286 0155  Fax: 6284 1539  Contact Person: Sophia
<b>3) LBS Automotive Appraisal Pte Ltd</b> <b>L.B.S. Auto Consultants Pte Ltd</b>  Tel: 6281 6690 / 62832866  Fax: 6281 8748  Contact Person: Amy/ Grace	<b>4) Priority Services</b>  Tel: 62934822  Fax: 62963283  Contact Person: Sharon

<p><b>5) RT Appraisal Pte Ltd</b></p> <p>Tel: 67486076  Fax: 67480361  Contact Person: Elson/Elgene</p>	<p><b>6) LKK Auto Consultants Pte Ltd</b></p> <p>Tel: 6256-3561  Fax: 6741-4108</p>
<p><b>7) Kelvin Automotive Appraising Services</b></p> <p>Tel: 81825263  Fax: 67461148  Contact Person: Kelvin</p>	<p><b>8) Automotive Appraiser &amp; Surveying Services</b></p> <p>Tel: 96623655  Fax: 67655662  Contact Person: Mr Chee</p>
<p><b>9) JP Knights Pte Ltd</b></p> <p>Tel: 63450068  Fax: 63445328</p>	<p><b>10) Appraisals Associates Pte Ltd</b></p> <p>Tel : 67472822  Fax: 67470070</p>
<p><b>11) Infiniti Appraisal Service</b></p> <p>Tel : 96684818/90099001  Fax: 64587432</p>	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

**Janet Tan**  
Senior Executive | Claims

**Error! Filename not specified.**

**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

**Error! Filename not specified.**

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient*

---

**From:** Nur Syafirah [mailto:[syafirah@bw.com.sg](mailto:syafirah@bw.com.sg)]  
**Sent:** Tuesday, December 4, 2018 5:24 PM  
**To:** Janet Tan <[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)>  
**Subject:** (TP) Claim- Accident Involving SMF4507T & SCU8992M

Dear Janet,

We're writing in to let you know that our client (**SMF4507T**) had an accident with your insured (**SCU8992M**).

We're authorized by our client to proceed with the TP claim process.

Attached is the GIA Report for your reference.

Please arrange for a surveyor for the PRS at our workshop.

Address:

**BW Workshop Services Pte Ltd**

**30 Ubi Road 4**

**Singapore 408615**

The vehicle is already in our workshop.

Please do contact us at **66920125** or email at [syafirah@bw.com.sg](mailto:syafirah@bw.com.sg) for any enquiries. Thank you.



Best regards,  
Nur Syafirah

BW Workshop Services Pte Ltd

30 Ubi Road 4 Singapore 408615

Main: 6289 8800 Fax 6858 2120 Email [syafirah@bw.com.sg](mailto:syafirah@bw.com.sg)

# LITHIUM BATTERY TEST REPORT



**HYBRID**  
AUTOMOTIVE  
(SINGAPORE)

**APPLICANT:** BW WORKSHOP SERVICES PTE LTD  
**TEST PRODUCT:** HONDA FIT HYBRID BATTERY PACK



**1. SAMPLES DESCRIPTION**

APPLICANT	BW WORKSHOP SERVICES		DATE REQUEST	27 <sup>TH</sup> , THURSDAY, JUNE 2019	
HEV MAKE	HONDA		TEST COMPLETED	28 <sup>TH</sup> FRIDAY, JUNE 2019	
HEV MODEL	FIT		CELL TESTED	FULL HEV BATTERY PACK	
CELL DESCRIPTION	LITHIUM-ION		CHEMICAL COMPONENTS	(N) AMORPHOUS CARBON	
CELL MODEL	EH5			(P) LITHIUM NICKEL-COBALT-MANGANESE COMPOSITE OXIDE	
NOMINAL VOLTAGE	3.6 (V)	RATED CAPACITY	5.0 Ah	END CHARGE CURRENT	300 (A)
CAPACITY AT CHARGING	4.2 (V)	CHARGE CURRENT	300 (A)	MAXIMUM DIS-CHARGE CURRENT	300 (A)
CUT-OFF VOLTAGE	3.0 (V)	MAXIMUM CURRENT	300 (A)		

**II REFERENCE METHOD**

- United Nations Recommendations On The Transport Of Dangerous Goods, Manual of Tests And Criteria (ST/SG/AC.10/11/Rev.5/Amend.1 & ST/SG/AC.10/11/Rev.5/Amend.2)
- American Society for Testing and Materials (ASTM E1359 – 17 / ASTM E543 – 15)

**III TEST ITEM (tick the box for samples to be tested)**

- |                           |                                     |                 |                                     |
|---------------------------|-------------------------------------|-----------------|-------------------------------------|
| 1. Altitude Simulation    | <input type="checkbox"/>            | 2. Thermal Test | <input type="checkbox"/>            |
| 3. Vibration Test         | <input type="checkbox"/>            | 4. Shock Test   | <input type="checkbox"/>            |
| 5. External Short Circuit | <input checked="" type="checkbox"/> | 6. Crush Test   | <input type="checkbox"/>            |
| 7. Forced Discharge Test  | <input checked="" type="checkbox"/> | 8. NDT Testing  | <input checked="" type="checkbox"/> |

**2. CONCLUSION**

TEST ITEM	SAMPLE NUMBER	STANDARD	CONCLUSION
Altitude Simulation	NIL	ASTM E543 – 15 / E1359 – 17 / UN38.3	FAIL
Thermal Test			
Vibration Test			
Shock Test			
External Short Circuit			
Crush Test			
Forced Discharge Test			
NDT Testing			




The submitted battery and component cell were complied with the UN Manual of tests and criteria, part III, sub-section 38.3 and ASTM Manual of tests and criteria, E1359 – 17 / E543 – 15.

Issued Date: 28/06/2019


Prepared by:

Checked by:


Approved by:




ABOVE ALL RED IN CIRCLE ARE THE RESIDUES OF THE BATTERY PACK THAT HAD LEAKIED AND DRIED OFF FOR SOME PERIOD OF TIME.



ABOVE PICTURE SHOWS THE RESIDUE THAT LEAKS OUT AFTER THE IMPACT OF CRUSH, SO THE WHOLE PACK OF BATTERY IS NOT REQUIRED FOR THE TEST AS ACCORDING TO THE MANUFACTURER A FULL NEW BATTERY OF REPLACEMENT IS REQUIRED.



SIGNS OF CRACK BEEN OBSERVED



AIR INTAKE CASING BEING OBSERVED BROKEN



BATTERY COVER LID BEEN OBSERVED OPEN DUE TO A HIT IMPACT

**TEST END**  
**RESULT - NULL**

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Wednesday, 2 October 2019 8:10 AM  
**To:** 'Justin Ee'  
**Cc:** Vic (LKKAuto); Admin A; Guo Qiang (LKKAuto); Derek Low; Ebell Lee; Xu Hai  
**Subject:** RE: (TP) Claim- Accident Involving SMF4507T & SCU8992M LKK REF CC4/EQ118021899/Gpb3

### Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement at \$18,022.34(all-in).

We will proceed to close file.

*\*Note: EQ case, no DV is needed for settlement < \$20K.*

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Justin Ee <[justin\\_ee@bw.com.sg](mailto:justin_ee@bw.com.sg)>  
**Sent:** Monday, 30 September 2019 5:55 PM  
**To:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Cc:** Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Guo Qiang (LKKAuto) <[GuoQiang@lkkauto.com](mailto:GuoQiang@lkkauto.com)>; Derek Low <[derek@bw.com.sg](mailto:derek@bw.com.sg)>; Ebell Lee <[ebell@bw.com.sg](mailto:ebell@bw.com.sg)>; Xu Hai <[xu\\_hai@bw.com.sg](mailto:xu_hai@bw.com.sg)>  
**Subject:** Re: (TP) Claim- Accident Involving SMF4507T & SCU8992M LKK REF CC4/EQ118021899/Gpb3

Hi Hsiao Tong,

Good afternoon to you,



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ18021899/Gpb3s2

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEXSINGAPORE 069110

Date : 07-10-2019



Code : EQI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SCU 8992M	Veh. Inspected	SMF 4507T
Policy No.	DMPPHQ18-003767	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JANET TAN	Assign Date	05/12/2018

## 2. Vehicle Particulars & Condition

Make & Model	HONDA FIT HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP51329849	Colour	SILVER
Odometer	001709	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	BRIDGESTONE	9 mm
L/H Front Tyre	185/60 R15	BRIDGESTONE	9 mm
R/H Rear Tyre	185/60 R15	BRIDGESTONE	9 mm
L/H Rear Tyre	185/60 R15	BRIDGESTONE	9 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	03/12/2018	Inspection Date	06/12/2018
Survey held at	BW WORKSHOP SERVICES PTE LTD 30 UBI ROAD 4 SINGAPORE 408615		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **14 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 4507T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRT BUMPER	DEFORMED	1,300.00	540.00
1	FRT BUMPER SEAL	NOT NECESSARY	65.00	-
1	FRT BUMPER FOG LAMP GARNISH LH	CUT	48.30	48.30
2	FRT BUMPER SIDE HOLDER @ \$38.00	N/S DEFORMED / O/S NOT NECESSARY	76.00	20.00
1	REINFORCEMENT	NOT NECESSARY	318.20	-
1	BUMPER LOWER GRILLE	NOT NECESSARY	191.80	-
1	BONNET	NOT NECESSARY	811.70	-
1	LOCK	NOT NECESSARY	90.50	-
1	HEAD LAMP LH	CRACKED	1,036.70	810.00
1	BUMPER GRILLE	NOT NECESSARY	352.90	-
1	BUMPER SPONGE	NOT NECESSARY	301.20	-
1	BUMPER EMBLEM	NOT NECESSARY	27.40	-
1	BUMPER TOP MOULDING	NOT NECESSARY	271.20	-
2	RADIATOR SIDE GUIDE LH & RH @ \$25.20	N/S BENT	50.40	25.20
1	GRILLE TOP GARNISH	NOT NECESSARY	30.10	-
1	GRILLE TOP BRACKET	NOT NECESSARY	26.40	-
1	REAR TAILGATE	BUCKLED	950.90	860.00
1	REAR TAILGATE CHROME GARNISH	BROKEN	251.90	140.00
1	REAR TAILGATE LOCK	BENT	195.90	195.90
1	REAR LOCK STRIKER	BENT	95.30	95.30
1	REAR TAILGATE SWITCH HANDLE	NOT NECESSARY	175.50	-
1	REAR TAILGATE POCKET PULLER	DEFORMED	80.60	80.60
1	REAR TAILGATE INNER TRIM	BROKEN	159.20	159.20
10	REAR TAILGATE INNER TRIM CLIP @ \$4.50	NECESSARY	45.00	45.00
1	REAR TAILGATE WEATHER STRIP	TWISTED	92.30	92.30
2	REAR TAILGATE HINGE RH & LH @ \$50.20	NOT NECESSARY	100.40	-
2	REAR TAILGATE DAMPER @ \$131.90	NOT NECESSARY	263.80	-
1	REAR TAILGATE REVERSE CAMERA	NOT NECESSARY	350.00	-
2	REAR TAILGATE BRAKE LAMP LH & RH @ \$481.50	CRACKED	963.00	577.80

Report Ref No. CC4/EQ118021899/Gpb3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WINDSCREEN SPONGE TAPE	NECESSARY	60.00	60.00
1	REAR TAILGATE WINDSCREEN SEAL	NECESSARY	120.00	120.00
2	REAR TAILGATE WINDSCREEN MOULDING @ \$151.80	NECESSARY	303.60	95.00
1	REAR TAILGATE HYBRID EMBLEM	NECESSARY	85.60	75.00
1	REAR TAILGATE FIT EMBLEM	NECESSARY	60.20	60.20
2	REAR BOOT LAMP LH & RH @ \$392.50	NOT NECESSARY	785.00	-
1	REAR END PANEL	BUCKLED	820.90	420.00
1	REAR END PANEL TOP GARNISH	DEFORMED	189.80	65.00
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,518.30	-
1	REAR TOP BOARD	NOT NECESSARY	258.30	-
2	REAR INNER TRIM LH & RH @\$258.40	DEFORMED	516.80	516.80
1	REAR HYBRID BATTERY	DAMAGED	11,120.80	8,000.00
1	REAR HYBRID BATTERY AIR GARNISH OUT	DEFORMED	126.30	63.15
1	REAR HYBRID BATTERY AIR GARNISH IN	DEFORMED	259.30	129.65
1	REAR HYBRID BATTERY COVER	CRACKED	254.50	127.25
1	REAR BUMPER	DEFORMED	851.90	520.00
1	REAR BUMPER GARNISH CENTER	DEFORMED	130.60	130.60
2	REAR BUMPER REFLECTOR LH & RH @ \$80.50	NOT NECESSARY	161.00	-
2	REAR BUMPER REFLECTOR GARNISH LH & RH @ \$95.60	CUT	191.20	50.00
2	REAR BUMPER RETAINER	DEFORMED	50.20	40.00
2	REAR BUMPER INNER BRACKET	BENT	121.00	60.00
1	REAR ANTENNA SENSOR	DAMAGED	58.10	58.10
1	REAR BUZZER	DAMAGED	80.50	80.50
1	REAR PANEL UNDER COVER	NOT NECESSARY	258.60	-
1	REAR EX SILENCER	NOT NECESSARY	651.80	-
1	REAR AIR GUIDE FENDER	NOT NECESSARY	60.30	-
	LESS 20% DISCOUNT		-	-2,872.17
			27,816.20	11,488.68
	<b>SPECIAL NETT ITEMS</b>			
10	FRT BUMPER CLIP @ \$4.50 (SN)	NECESSARY	45.00	30.00
20	REAR INNER TRIM CLIP @ \$4.50 (SN)	NECESSARY	90.00	40.00
10	REAR BUMPER CLIP (SN)	NECESSARY	45.00	30.00

Report Ref No. CC4/EQ118021899/Gpb3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR PARKING SENSOR (SN)	DAMAGED	250.00	150.00
			430.00	250.00
	<b>LABOUR</b>			
	TO CUT & WELD REAR PANEL, FLOOR PANEL. PULLING REAR CHASSIS MEMBER AND REPLACE ACCIDENT PORTION. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL.		3,800.00	1,600.00
	TO RESPRAY PAINT ON ACCIDENT PORTION (REAR BUMPER, END PANEL, FLOOR PANEL, TAILGATE, HINGEX2, LH FENDER, RH FENDER, FRT BUMPER, SUPPORT PANEL, FRT FENDER LH, BONNET)		3,000.00	1,800.00
	TO TUFF-KOTE.		350.00	80.00
	TO REMOVE RADIATOR, AIR CONDENSER REPAIR SUPPORT PANEL.	NOT NECESSARY	250.00	-
	TO TOP UP AIR COND GAS.	NOT NECESSARY	80.00	-
	TO CHECK & REAR WIRING.		250.00	30.00
	TO REMOVE & REFIX REAR TOP GARNISH, FENDER INNER TRIM AND ROOF LINING.		200.00	60.00
	TO REMOVE & REFIX REAR WINDSCREEN GLASS.		150.00	100.00
	TO REMOVE & REPLACE REAR PARKING SENSOR.		120.00	40.00
	TO TRANSFER & INSTALLATION REAR BOOT WIRING, BRAKE LAMP, WIPER MOTOR.		280.00	60.00
	TO REMOVE & REFIX REAR EXHAUST.		180.00	60.00
	TO DIAGNOSTIC REPROGRAM ANTISAFETY SYSTEM.		800.00	250.00
	TO REMOVE REAR SEAT.		180.00	40.00
	TO REMOVE & REFIX REAR AXEL.		250.00	100.00
	TO REMOVE & REFIX ABS SENSOR.	NOT NECESSARY	50.00	-
	TO REMOVE & REFIX LH & RH WHEEL BEARING.	NOT NECESSARY	80.00	-
	TO REMOVE & REFIX REAR HYBRID BATTERY.		380.00	80.00
	TO EMANCIPATION HYBRID POWER SYSTEM BEFORE REMOVER.		250.00	50.00
	WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
			10,730.00	4,350.00
<b>GRAND TOTAL</b>			<b>38,976.20</b>	<b>16,088.68</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>16,088.68</b>

Report Ref No. CC4/EQ18021899/Gpb3s2



Report Ref No. CC4/EQ118021899/Gpb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.