

BW WORKSHOP SERVICES PTE LTD

30 UBI ROAD 4 SINGAPORE 408615

TEL: 62898800 FAX: 68582120

GST REG NO. 201504834E

QUOTATION

EQ Insurance Company Limited
 THIRD PARTY CLAIM: SCU8992M
 DATE OF ACCIDENT: 03.12.2018

NO. : 18120002
 CURRENCY : \$
 PAGE :
 DATE : 5/12/2018

QTY	DESCRIPTION	VEH NO.	
		SMF4507T HONDA FIT HYBRID	
		Unit Price	AMOUNT
1PC	FRT BUMPER <i>DE</i>		\$ 1,300.00
10PCS	FRT BUMPER CLIP <i>ALL</i>	\$ 4.50	\$ 45.00
1PC	FRT BUMPER SEAL <i>X NN</i>		\$ 65.00
1PC	FRT BUMPER FOG LAMP GARNISH LH <i>X CUT</i>		\$ 48.30
2PCS	FRT BUMPER SIDE HOLDER <i>LH - DE, RH X NN</i>	\$ 38.00	\$ 76.00
1PC	REINFORCEMENT <i>X</i>		\$ 318.20
1PC	BUMPER LOWER GRILLE <i>X</i>		\$ 191.80
1PC	BONNET <i>X</i>		\$ 811.70
1PC	LOCK <i>X</i>		\$ 90.50
1PC	HEAD LAMP LH <i>X CRA</i>		\$ 1,036.70
1PC	BUMPER GRILLE <i>X</i>		\$ 352.90
1PC	BUMPER CHROME <i>X</i>		\$ 301.20
1PC	BUMPER EMBLEM <i>X</i>		\$ 27.40
1PC	BUMPER TOP MOULDING <i>X</i>		\$ 271.20
2PCS	RADIATOR SIDE GUIDE LH & RH <i>X / BR LH</i>	\$ 25.20	\$ 50.40
1PC	GRILLE TOP GARNISH <i>X</i>		\$ 30.10
1PC	GRILLE TOP BRACKET <i>X NN</i>		\$ 26.40
1PC	REAR TAILGATE <i>bul</i>		\$ 950.90
1PC	REAR TAILGATE CHROME GARNISH <i>X / BR</i>		\$ 251.90
1PC	REAR TAILGATE LOCK <i>- LST</i>		\$ 195.90
1PC	REAR LOCK STICKER <i>-</i>		\$ 95.30
1PC	REAR TAILGATE SWITCH HANDLE <i>X NN</i>		\$ 175.50
1PC	REAR TALGATE POCKET PULLER <i>- DE</i>		\$ 80.60
1PC	REAR TAILGATE INNER TRIM <i>- BR</i>		\$ 159.20
10PCS	REAR TAILGATE INNER TRIM CLIP <i>- ALL</i>	\$ 4.50	\$ 45.00
1PC	REAR TAILGATE WEATHER STRIP <i>- TMS</i>		\$ 92.30
2PCS	REAR TAILGATE HINGE RH & LH <i>X NN</i>	\$ 50.20	\$ 100.40



2PCS	REAR TAILGATE DAMPER	X NN		\$ 131.90	\$ 263.80
1PC	REAR TAILGATE REVERSE CAMERA	X NN			\$ 350.00
2PCS	REAR TALGATE BRAKE LAMP LH & RH	9 / CRA		\$ 481.50	\$ 963.00
1PC	WINDSCREEN SPONGE TAPE	/			\$ 60.00
1PC	REAR TAILGATE WINDSCREEN SEAL	/			\$ 120.00
2PCS	REAR TAILGATE WINSCREEN MOULDING	/		\$ 151.80	\$ 303.60
1PC	REAR TALGATE HYBRID EMBLEM	/			\$ 85.60
1PC	REAR TAILGATE FIT EMBLEM	/			\$ 60.20
2PCS	REAR BOOT LAMP LH& RH	X NN		\$ 392.50	\$ 785.00
1PC	REAR END PANEL	/			\$ 820.90
1PC	REAR END PANEL TOP GARNISH	/			\$ 189.80
1PC	REAR SPARE TYRE PANEL	X Repair.			\$ 1,518.30
1PC	REAR TOP BOARD	X NN			\$ 258.30
2PCS	REAR INNER TRIM LH & RH	/		\$ 258.40	\$ 516.80
20PCS	REAR INNER TRIM CLIP	/		\$ 4.50	\$ 90.00
1PC	REAR HYBRID BATTERY	?			\$ 11,120.80
1PC	REAR HYBRID BATTERY AIR GARNISH OUT	/			\$ 126.30
1PC	REAR HYBRID BATTERY AIR GARNISH IN	/			\$ 259.30
1PC	REAR HYBRID BATTERY COVER	X CRA			\$ 254.50
1PC	REAR BUMPER	/			\$ 851.90
10PCS	REAR BUMPER CLIP	/		\$ 4.50	\$ 45.00
1PC	REAR BUMPER GARNISH CENTER	/			\$ 130.60
2PCS	REAR BUMPER REFLECTOR LH & RH	X NN		\$ 80.50	\$ 161.00
2PCS	REAR BUMPER REFLECTOR GARNISH LH & RH	/		\$ 95.60	\$ 191.20
2PCS	REAR BUMPER RETAINER	/		\$ 25.10	\$ 50.20
2PCS	REAR BUMPER INNER BRACKET	/		\$ 60.50	\$ 121.00
1PC	REAR ANTENNE SENSOR	/			\$ 58.10
1PC	REAR BUZZER	X			\$ 80.50
1PC	REAR PANEL UNDER COVER	X NN			\$ 258.60
1PC	REAR EX SILENCER	?			\$ 651.80
1PC	REAR PARKING SENSOR	/			\$ 250.00
1PC	REAR AIR GUIDE FENDER	X NN			\$ 60.30

Rear Bumper Spenge LH & RH - CRA.
 Rear Exhaust Heat Shield - BT
 Headlamp Bracket LH - BR.

TOTAL	28,246.20
LABOUR CHARGE	10,730.00
DISCOUNT (only Parts)	0%
TOTAL:	38,976.20
GST 7%	2,728.33
TOTAL	41,704.54

LABOUR :

- 1 TO CUT & WELD REAR PANEL, FLOOR PANEL, PULLING REAR CHASSIS MEMBER AND REPLACE ACCIDENT PORTION -\$3800 1600
- 2 TO RESPRAY PAINT ON ACCIDENT PORTION (REAR BUMPER, END PANEL, FLOOR PANEL, TAILGATE, HINGE X2, LH FENDER, RH FENDER, FRT BUMPER, SUPPORT PANEL, FRT FENDER LH, BONNET) -\$ 3000.00 1800
- 3 TO TUFF-KOTE -\$350.00 80
- 4 TO REMOVE RADIATOR, AIR CONDENDER REPAIR SUSPORT PANEL -\$250.00 ?
- 5 TOP UP AIR COND GAS -\$ 80 ?
- 6 TO CHECK & REAR WIRING -\$250 30
- 7 TO REMOVE & REFIX REAR TOP GARNISH, FENDER INNER TRIM AND ROOF LINING -\$200.00 60
- 8 TO REMOVE & REFIX REAR WINDSCREEN GLASS -\$150.00 100
- 9 TO REMOVE & REPLACE REAR PARKING SENSOR -\$120.00 40
- 10 TO TRANSFER & INSTALLATION REAR BOOT WIRING, BRAKE LAMP, WIPR MOTOR- \$280 60
- 11 TO REMOVE & REFIX REAR EXHOUST -\$180 60
- 12 TO DIAGNOSTIC REPROGRAM ANTISAFETY SYSTEM - \$800.00 250
- 13 TO REMOVE REAR SEAT -\$180.00 40
- 14 TO REMOVE & REFIX REAR AXEL -\$250 100
- 15 TO REMOVE & REFIX ABS SENSOR -\$50 X
- 16 TO REMOVE & REFIX LH& RH WHEEL BEARING -\$80 X 500
- 17 TO REMOVE & REFIX REAR HYBRID BATTERY-\$380 80
- 18 TO EMANCIPATION HYBRID POWER SYSTEM BEFORE REMOVER -\$250 50
- 19 WHEEL ALIGNMENT-\$80 X ~~80~~ NN

14 Days.

part by part.

before part photos

Guo Qian

06/12/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: