

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 5383L

MAKE :

MODEL : HYUNDAI SONATA

DATE 4/12/2018 9:09

*LKK/kawin*  
*Like*

*H/Sum*  
**CHINA**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Clip ✓			\$ 22.00
	Rear Bumper Protector (LH) x rear			\$ 38.00
	<i>Rear Fender (RH) x repair</i>			
	<i>Rear Trillday (LH) ✓</i>			
	<b>SUB TOTAL</b>			<b>\$ 638.40</b>
	<b>LESS 20%</b>			<b>\$ 127.68</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 510.72</b>
	Rear Bumper Rubber Mat ✓			\$ 50.00 <b>Nett</b>
	Rear Bumper Advertisement Logo ✓			\$ 50.00 <b>Nett</b>
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00 <b>Nett</b>
				<b>\$ 300.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>400.00</del> <i>300</i>
	Spray Painting Charge-Fender/Bumper			\$ <del>600.00</del> <i>400</i>
	Wiring Charge			\$ <del>30.00</del> <i>20</i>
	Tuff Kote			\$ <del>50.00</del> <i>X</i>
	Remove/Refix Reverse Sensor			\$ <del>120.00</del> <i>30</i>
	<b>TOTAL LABOUR</b>			<b>\$ 1,200.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,010.72</b>

*Ka Lun (LKK)*  
*4/12/18 1040hrs.*  
*3 Pys*  
*4/5*  
*After Repair photo*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.