



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SLS 4013 U

*Not Authorized*  
*Repair By Paint*

Parts (a) Cost / List Price Items	\$	2,075.50
Plus/Less 25%	\$	518.88
Total of Cost / List	\$	1,556.63
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$	200.00
Total Parts Cost	\$	1,756.63
Labour	\$	1,690.00
Total	\$	3,446.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
Company : LKK  
Survey conducted on : 10/12/18 at \_\_\_\_\_

#### Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 2-3 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Sc Date: 10/12/18



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SLS 4013 U**  
Make & Model : **TOYOTA PRIUS**  
Chassis No : **JTDKB3FU103570604**

Submit By : **Serence Chee**  
Year Manufacture : **2017**  
Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>SL</i>	1	\$200.00	S.N	X
2	Rear bumper <i>Bul/SL</i>	1	\$497.50		✓
3	Rear bumper clip <i>SL</i>	10	\$40.00		✓
4	Rear bumper side retainer LH <i>SL</i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>SL</i>	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		?
7	Rear bumper lower garnish centre <i>Red/SL</i>	1	\$582.60		✓
8	Rear bumper lower garnish LH <i>SL</i>	1	\$149.70		X
9	Rear bumper lower garnish RH <i>SL</i>	1	\$149.70		X
10	Rear bumper tow cover <i>SL</i>	1	\$31.70		✓
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SLS 4013 U** Submit By : **Serence Chee**  
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL)	\$600.00	2001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL)	\$600.00	2201
3	To check wiring	\$50.00	151
4	To remove & refit reverse sensor	\$120.00	501
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	X
6	To tuff coat. <i>nn</i>	\$50.00	X
7	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.