

REPAIR ESTIMATE*

VEHICLE NO : SHB 6393X

DATE 5/12/2018 8:38

MAKE :

MODEL : MERCEDES

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt <i>x repair</i>			\$ 1,890.50
	Fender Splashshield , Frt/LH (Front) <i>x</i>			\$ 257.00
	SUB TOTAL			\$ 2,147.50
	LESS 20%			\$ 429.50
	DISCOUNTED TOTAL			\$ 1,718.00
	Labour Charge			
	Panel Beating			\$ 400.00 ²⁰⁰
	Spray Painting Charge			\$ 600.00 ²⁰⁰
	<i>Young Fee</i>			\$ 60.00 [✓]
	TOTAL LABOUR			\$ 1,000.00
	ESTIMATE TOTAL			\$ -500.00
				2,118.00

Kahin Uday
5/12/18 1015 hrs
2 hrs.
U/s
After Repair photo

LKK Auto C
 the Repairer
 • To resurvey the vehicle
 • To display damaged parts and accessories
 • Parts prices are subject to change
 • Third party surveyor must be present
 • No illegal modification
 • Supplementary repair must be approved
 is subject to final approval from insurance company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.