

3 MOTORWERKZ ^{Sheet 1} CONCEPT PTE LTD

Block 25 Kaki Bukit Road 4, #01-40/42 Synergy @ KB Singapore 417800
HP: 96583371

HSU SI YANG
Bk 25 Kaki Bukit Rd 4
01-40/42 SYNERGY @KB
Singapore 417800

TPA-A

Acilin

05th December 2018

KLIA 69E SCIC616258

Accident date: 03rd December 2018

Estimated repair cost for vehicle no: SKD5819X CHEVROLET CRUZE '11

S/n	Qty	Items	U/price	Amount
1	1	Rear boot lid emble logo		\$48.00 ✓
2	1	Rear boot lid CRUZE logo		\$45.00 ✓
3	1	Rear boot lid chevrolet logo		\$38.00 ✓
4	1	Rear Boot Lid number plate		\$50.00 ✓
5	1	Rear boot lid inner lock		\$385.00 ✓
6	1	Rear boot lid inner rubber		\$188.00 ✓
7	1	raer boot lid side reflector -LH		\$420.00 ✓
8	1	Rear tail lamp -LH		\$320.00 ✓
9	4	Rear tail lamp clips	\$5.00	\$20.00 10
10	1	Rear bumper		\$1,450.00 1151
11	2	Rear Bumper Side Bracket	\$67.00	\$134.00 ✓
12	10	Rear bumper clips	\$5.00	\$50.00 30
13	1	Rear bumper reverse sensor		\$360.00 2w
14	1	Rear Bumper reinforcement		\$780.00 689
15	2	Rear Bumper reinforcement bracket	\$145.00	\$290.00 ✓
16	1	Rear end panel		\$968.00 ✓
17	1	Rear End Panel Top Garnish		\$283.00 ✓

Subtotal :- \$5,819.00

2665

2398.50

Labour charges

To remove & re-fix rear windscreen	\$120.00 +
Gum	\$50.00 +
To remove & re-fix cushion	\$120.00 +
To remove & re-fix reverse sensor	\$100.00 50
To Check Wiring System	\$60.00 30
Tuff kote	\$120.00 40
Panel beating	\$800.00 300
Spray painting	\$800.00 500

Subtotal :- \$2,170.00

Total:- \$7,989.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 3318.5

h/s 2650

04 days