

ASSIGNMENT

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess See II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

I.T.A / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed /

Assessed)

BOLA S/N No.:

If NO or B 28, Ass. Lin:

Repair Cost: (w/ GST)

S\$ 5350.00

Loss of Rental (LOR):

S\$ 720.00

(

6

days) x

\$120

Loss of Use (LOU):

S\$ -

(\$

x

days)

Loss of Income (LOI):

S\$ -

(\$

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

CHA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$500

Total:

S\$ 6077.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 6077.45

Name 1:

N-SI Automotive Pte Ltd

Payee 2: (Sole if N.A.)

S\$

Name 2:

Payee 3: (Sole if N.A.)

S\$

Name 3:

REF:

SUBSIDIARY

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

TP III

LIS \$ 5000 CR201 \$ 5799.07 / 5471

Vali No: 6863194T. Yr Regn: 2017 July.
 Type: ☒ M.Veh / ☒ M.Cycle / ☒ Bus / ☒ Van / ☒ Lorry / ☒ Taxi / ☒ Prime Mover /
 Truck / Trailer or

Make: Toyota Hiace C.C. 2982

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 58294 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFHT02P000217057

Gen. Cond: ☒ Good / ☒ Fair / ☒ Poor / ☒ BurntSteering: ☒ In order / ☒ Jammed / ☒ Leaked / ☒ Burnt orBrake: ☒ In order / ☒ Jammed / ☒ Leaked / ☒ Burnt orModi: ☒ Nil / ☒ S/Rim / ☒ STD A/Rim or

Tyre Size: F: 195R15C

R: 195R15C

☒ BS / ☒ DUN / ☒ EXNOVA / ☒ GY / ☒ FS / ☒ LIZA / ☒ MIC / ☒ OHTSU / ☒ PIR / ☒ SUMI /
 TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. D.O.I. 06/12/18

Survey held at: NSI

Des. of Damages: Frt / ☒ Rear / ☒ O/S / ☒ N/S / ☒ U/C / ☒ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to:

☐ : Preli. Report

Days Of Repair:

11

☐ : Final Report

Resurvey No. of Trip:

Date/Time: File Return to:

Survey Fee:

21

Transportation:

Add Fee: ☐ Site Insp (\$

1 - S - P - S

☐ Interview (\$

1 - P - S - S

☐ Tech. Insp (\$

1 - O - S - S

☐ Weighing (\$

1 - O - S - S

Report Format:

Lump Sum / I.B.I. (\$

Total

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

8823 5151

RICHLAND LOGISTICS SERVICES PTE LTD
300 TAMPINES AVE 5 #05-02
SINGAPORE 529653

Contact : 69348411 87157915

TP III
Xiao Tony

ESTIMATE

Repair Code : CLM14934

Date in : 29/11/2018

Vehicle Num. : GBG3194T

Model : TOYOTA HIACE VAN TURBO 5 DR MANUAL

Chassis/Eng# : JTFHT02P000217057/1KD2688883

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehmb</i>	1	706.00	706.00 538
REAR BUMPER LOWER BRACKET <i>267 new Bent</i>	3	25.00	75.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	66.10	✓ 132.20
REAR END PANEL 'INNER' <i>Repair</i>	1	1144.00	+ 1,144.00
REAR END PANEL 'OUTER' <i>Dented</i>	1	581.80	✓ 581.80
REAR EXHAUST PIPE <i>Repair</i>	1	871.20	+ 871.20
REAR SPARE TYRE CARRIAGE <i>Bent</i>	1	237.97	✓ 237.97
REAR SPARE TYRE CARRIAGE BRACKET <i>Bent</i>	1	243.10	✓ <u>243.10</u>
REAR SPARE TYRE CARRIAGE SCREW <i>new</i>	1	68.30	+ 68.30
REAR TAILGATE <i>Dented</i>	1	2205.30	2,205.30 1855
REAR TAILGATE 'HIACE' STICKER <i>new</i>	1	71.60	✓ 71.60
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	71.60	✓ 71.60
REAR TAILGATE 'TOYOTA' STICKER <i>new</i>	1	67.15	✓ 67.15
REAR TAILGATE CENTER LOCK CONTROL <i>new</i>	1	267.30	+ 267.30
REAR TAILGATE DAMPER L/R <i>new</i>	2	287.90	+ 575.80
REAR TAILGATE HINGES L/R <i>new</i>	2	68.90	+ 137.80
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>new</i>	2	28.50	+ 57.00
REAR TAILGATE LOCK STRIKER <i>new</i>	1	70.20	+ 70.20

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

RICHLAND LOGISTICS SERVICES PTE LTD
 300 TAMPINES AVE 5 #05-02
 SINGAPORE 529653

Contact : 69348411 87157915

ESTIMATE

Repair Code : CLM14934

Date in : 29/11/2018

Vehicle Num. : GBG3194T

Model : TOYOTA HIACE VAN TURBO 5 DR MANUAL

Chassis/Eng# : JTFHT02P000217057/1KD2688883

REAR TAILGATE MECHANISM LOCK <i>Pangd</i>	1	263.00	✓	263.00
REAR TAILGATE WEATHER STRIP <i>Cut</i>	1	387.60	✓	387.60
REAR TAILLAMP L/R <i>Rt cancelled</i>	2	354.80	<i>5037.72</i>	<i>354.80</i> 209.60
REAR TAILLAMP LOWER GARNISH L/R <i>Del</i>	2	78.95	✓	157.90
REAR TAILLAMP LOWER GARNISH SIDE RETAINER L/R <i>per car</i>	2	22.00	+	44.00
Subtotal before discount				9,145.42
Percentage discount 25%				2,286.36
Sub-total 1				6,859.07
COMPANY 3D STICKER - SET <i>N/A</i>	1	450.00	<i>180</i>	450.00
REAR BUMPER CLIPS - SET <i>N/A</i>	1	80.00	<i>30</i>	80.00
REAR BUMPER REVERSE SENSOR - SET <i>Pangd</i>	1	350.00	<i>200</i>	350.00
REAR TAILGATE '70KM/H' STICKER <i>N/A</i>	1	25.00	<i>15</i>	25.00
REAR TAILGATE NUMBER PLATE <i>N/A</i>	1	25.00	<i>X</i>	25.00
REAR TAILGATE WINDSCREEN SEAL <i>3 N/A</i>	1	100.00	<i>40</i>	100.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	<i>40</i>	80.00
REAR TAILLAMP CLIPS L/R - SET <i>N/A</i>	2	30.00	<i>20</i>	60.00
REAR TAILLAMP LOWER GARNISH CLIPS L/R - SET <i>N/A</i>	2	30.00	<i>10</i>	60.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

RICHLAND LOGISTICS SERVICES PTE LTD
300 TAMPINES AVE 5 #05-02
SINGAPORE 529653

Contact : 69348411 87157915

ESTIMATE

Repair Code : CLM14934

Date in : 29/11/2018

Vehicle Num. : GBG3194T

Model : TOYOTA HIACE VAN TURBO 5 DR MANUAL

Chassis/Eng# : JTFHT02P000217057/1KD2688883

Subtotal before discount	1,230.00
Percentage discount 0%	0.00
Sub-total 2	1,230.00
Parts-total	8,089.07

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To transfer rear tailgate inner trim board, wiper motor, mechanism lock outer handle.

Labour Total

2,710.00

Parts & Labour Total

10,799.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "No Fault" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

*** This is a computer-generated document which requires no signature.***

page 3

Adrian L/S 06/12/18
06 days

total: 6263.29
L/S: SK

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, 15 December 2018 8:16 AM
To: Sabrina A
Subject: Your Ref: GBG 3194T *Our Ref: CC4/III18021915/Apa3 [ACCIDENT INVOLVING SHD 3182Y(III) AND GBG 3194T ON 29/11/2018]

Your Ref: **GBG 3194T** **Without Prejudice**
Our Ref: CC4/III18021915/Apa3

Dear Sirs/ Mdm,

ACCIDENT INVOLVING SHD 3182Y(III) AND GBG 3194T ON 29/11/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***GBG3194T (MCT18110924)
[SHD3182Y]**

TP

RICHLAND LOGISTICS SERVICES PTE LTD

Nov 29 2018 10:00AM

[-]

N-51 Automotive Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 03/05/2019 12:10 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6077.45) - GBG3194T - Claim Handler: Sherini Pillai

Approved:6077.45.

DOCUMENTS SUMMARY

There are no documents.

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	05 Dec 2018 16:03	Cim Veh Model Changed	(205832) TOYOTA HIACE 3.0 D (M).	[A] HOW MEI KWAN
2	05 Dec 2018 16:03	Cim Created	Reg No: GBG3194T, Acct Date: 2018/11/29. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ). Workshop: N-51 Automotive Pte Ltd (HQ)	[A] HOW MEI KWAN
3	05 Dec 2018 16:03	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
4	05 Dec 2018 16:03	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/12/14	[A] HOW MEI KWAN
5	05 Dec 2018 16:03	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
6	05 Dec 2018 16:04	Label Added	(30651):Vehicle Not In,(30653):Direct Settlement.	[A] HOW MEI KWAN
7	05 Dec 2018 16:04	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] HOW MEI KWAN
8	07 Dec 2018 18:21	Label Removed	(30651):Vehicle Not In.	[A] HOW MEI KWAN
9	14 Dec 2018 07:39	Adj Mandate Request	Cur.Reg:0.00:PODS Liability: 100% Remarks: Insured driver rear-ended third party	[A] CHEW HSIAO TONG
10	14 Dec 2018 11:56	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/12/14	[I] Lalitha Krishnan
11	14 Dec 2018 11:56	Adj Mandate Set	Approved:0.00.	[I] Lalitha Krishnan
12	11 Feb 2019 09:35	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
13	11 Feb 2019 09:35	Cim Dtl Modified	Insured Name: -> -.	[A] JOANNE LEE KHANG MIN
14	11 Feb 2019 09:35	Cim Dtl Modified	Claimant's Name: -> -. Claimant's ID: -> -.	[A] JOANNE LEE KHANG MIN
15	11 Feb 2019 09:35	Cim Dtl Modified	JPJ Reg. Date: -> 2017/07/20.	[A] JOANNE LEE KHANG MIN
16	11 Feb 2019 09:35	Cim Details Notified		[A] JOANNE LEE KHANG MIN
17	29 Mar 2019 12:11	Adj Mandate Set	Approved:0.00.	[I] Stanley Lai
18	03 May 2019 09:23	Adj Mandate Request	Cur.Reg:6077.45:PODS Liability: 100% Quantum: (a)CORw/GST: \$5,350.00 + (b)LOR (6days x \$120.00): \$720.00 + (c)LTA/GIA search fee: \$7.45 = Total: \$6,077.45 Vehicle Model: Toyota Hiace (2982cc) 6 recommendation repair days For your approval please	[A] CHAN JIA LE

Date From



Date To



Audit Type

None

Go

ACTIVITY

Jia Le (LKK Auto)

From: Chin Hui Xin <huixin@n51.com.sg>
Sent: Thursday, 13 June 2019 4:02 PM
To: Jia Le (LKK Auto)
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: Re: LOD - Accident involving GBG3194T & SHD3182Y on 29/11/2018 *** LKK REF: CC4/III18021915/Apa3
Attachments: 3194.pdf

Dear Jia Le,

Refer to the above subject.

Attached signed DV for your kind action.

Original copy will post out soon.

Thank you

Regards,
Melody Chin
N-51 Automotive Pte Ltd
Office : 6842 0051
Fax : 6741 0510
www.n51.com.sg



On Thu, Jun 13, 2019 at 3:37 PM Jia Le (LKK Auto) <JiaLe@lkkauto.com> wrote:
Without Prejudice

Dear Melody,

For III's DV was sign by the workshop instead the owner.

Please resign the DV and return the original to us.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chin Hui Xin [mailto:huixin@n51.com.sg]

Sent: Thursday, 13 June 2019 3:30 PM

To: Jia Le (LKK Auto)

Cc: Hsiao Tong (LKKAuto); Admin A

Subject: Re: LOD - Accident involving GBG3194T & SHD3182Y on 29/11/2018 *** LKK REF: CC4/III18021915/Apa3

Dear Jia Le,

Refer to the above subject.

Attached signed DV for your kind action.

Your need original copy or not.

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



On Tue, May 21, 2019 at 4:17 PM Jia Le (LKK Auto) <JiaLe@lkkauto.com> wrote:

Without Prejudice

Dear Melody,

We refer to the above matter.

We confirm settlement as follows: -

1. Cost of Repair (w/GST)	\$ 5,350.00
2. Loss of Use (6days x \$120.00)	\$ 720.00
TOTAL	\$ 6,077.45

Please sign the DV and return to us.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Sunday, 17 March 2019 4:21 PM

To: Chin Hui Xin <huixin@n51.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Subject: RE: LOD - Accident involving GBG3194T & SHD3182Y on 29/11/2018 *** LKK REF: CC4/III18021915/Apa3

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CC4/III18021915/Apa3	Hsiao Tong - 6742 3197

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chin Hui Xin <huixin@n51.com.sg>

Sent: Friday, 15 March, 2019 10:18 AM

To: Admin A <admin-a@lkkauto.com>

Subject: LOD - Accident involving GBG3194T & SHD3182Y on 29/11/2018

Dear Sir / Madam,

We refer to the above reference.

Attached LOD for your kind perusal.

Original copy will post out to you soon.

Kindly acknowledge upon received our email and original copy of LOD.

Regards,

Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg





N-51 AUTOMOTIVE PTE LTD

(117)

Kaki Bukit Autohub,
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921
Tel No. : +65 6842 0051 / 6744 0510 Fax No. : +65 6741 0510
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

13 March 2019

Our Ref : CLM14934 / GBG3194T / DEC-06/2018

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
ATTN: MOTOR CLAIMS DEPARTMENT

Dear Sir @ Madam,

Re: Accident involving GBG3194T & SHD3182Y on 29/11/2018
Along Braddell Road towards CTE

We refer to the above accident which was caused due to the negligence of your insured driver of vehicle No: **SHD3182Y** whose vehicle was insured with you at the material date of the accident.

We are proposing for a direct settlement on the claims as following EXCLUDE personal injury in respect of claim arising out of the above mentioned accident.

Cost of repairs	\$	5,350.00	(Include 7% GST)
Loss of rental	\$	720.00	(\$120 X 6 Days)
LTA search fee	\$	7.45	
	S \$	<u>6,077.45</u>	

We enclosed herein the following documents for your necessary attention:

- 1) Our Final Bill No: CLM14934
- 2) Twincar Rental - Invoice no: 13-2440 , Vha no: 71894
- 3) LTA search fee
- 4) Letter of Authorisation
- 5) GIA report of GBG3194T
- 6) Accident video

We look forward to your prompt reply.

Yours faithfully,



N-51 AUTOMOTIVE PTE LTD

S.Y.NEO

Director



bizSAFE

P.I.C - Melody Chin
Reply to :huixin@n51.com.sg

LETTER OF AUTHORISATION

To: **M/s N-51 Automotive Pte Ltd**
Singapore

RE: ACCIDENT INVOLVING VEHICLE NOS: GBG 3194 T & SHD 3182 Y
ALONG BRADDELL ROAD TOWARDS CTE ON 29/11/2018 @ 10:45HRS

I/We RICHLAND LOGISTICS SERVICES PTE LTD NRIC/Passport No: 199500443 D
of 300 TAMPAKES AVE 5 #05-02 S(529653)
the owner of vehicle no. GBG 3194 T hereby authorise you to commence repair to the said
vehicle forthwith. In consideration of you repairing my/our vehicle at my/our request.

- a) I/We hereby irrevocably authorise you to demand claim settle receive whatever amount settled/payable by the insurance and/or third party or to commence legal proceeding, if necessary, in my name, for the costs of repair and loss of use, etc and to you appointing any Solicitor to act for me in respect of the accident' claim and all an any amount claimed, received and/or settled shall belong absolutely to you. I/We agree to assign the whole proceeds of my/our third party claim to you and my/our Solicitors (to be appointed by you on my/our behalf) shall accept this as my/our irrevocable authorisation to pay the amount compensated direct to you after deduction of their costs on a Solicitor & Client basis. I/We undertake to co-operate fully with you and my/our Solicitors to see the claim to a successful conclusion.
- b) If the third party claim is unsuccessful or in your discretion inappropriate for any reason, I/we hereby instruct and authorise you to claim direct from my/our insurance company on my/our behalf for all monies due to you. I undertake to pay you for the Excess applicable under my policy and to reimburse you all costs, fees and expenses incurred by you in pursuing the claim on my behalf.
- c) If the own insurers' claim is not applicable and/or the third party claim fails and/or either of the aforesaid is inadequate, I/we undertake to pay you for your expenses, costs and fees immediately.

I/We also irrevocably authorise you to sign all discharge vouchers/indemnity forms and all necessary papers in connection with the above claim in my/our absence. I/We irrevocable authorise you to appoint such a firm of Solicitors on my/our behalf as you shall deem fit for the purpose of the third party/own insurer's claim.

I/We undertake to inform you and/or the Solicitors appointed by you on my behalf in the event the third party's insurance company communicate with me/us directly, orally or in writing and I/we further undertake not to accept any monies or offer of settlement from the third party's insurers without first communicating with you and obtaining your consent.

Upon settlement of the third party claim and in case the settlement monies was sent to me/us by the third party's insurers, I/we undertake to pay you and my/our solicitor the cost of repairs settled and related expenses and disbursement incurred.

My/Our insurer is/are _____

Policy No. _____

Expiry Date: _____

Date: _____

Frankie Koh

Manager, Finance & HR

Richland Logistics Services Pte Ltd
Company Registration 190500143D

Excess: _____

Owner's Signature/Co's stamp (if applicable)

Witness Signature/Name

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: TP / MCT18110924
Claimant Ref: GBG 3194T

We/I, N-51 AUTOMOTIVE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 5,350.00 (repair cost), S\$ 720.00 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. GBG 3194T that was damaged pursuant to the accident which occurred on 29/11/2018 (date) at BRADDELL ROAD TOWARDS CTE (location) involving vehicle no. SHD 3182Y (insured vehicle). This is pursuant to the inspection conducted on 06/12/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner RICHLAND LOGISTICS SERVICES PTE LTD ("the third party claimant") of vehicle no. GBG 3194T to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to GBG 3194T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 6,077.45 to N-51 AUTOMOTIVE PTE LTD

Dated this 13 day of JUNE 20 19

CLAIMANT:

Signature:


Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

200616038 C
2 KAKI BUKIT ME 2 #01-7
KAKI BUKIT AUTOMOB
S (417921)

WITNESS:

Signature:


Signed by appointed Surveyor

Name:

NRIC:

Address:

Nationality:

Occupation:

LKK AUTO CONSULTANTS PTE LTD
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921
Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

RICHLAND LOGISTICS SERVICES PTE LTD
300 TAMPINES AVE 5 #05-02
SINGAPORE 529653

Contact : 69348411 87157915

TAX INVOICE

Date : 27/12/2018
Date in : 06/12/2018
Vehicle Num. : GBG3194T
Make/Model : TOYOTA HIACE VAN TURBO 5 DR MANUAL-2016
Chassis/Eng# : JTFHT02P000217057/1KD2688883
Accident Date : 29/11/2018
Claim No : CLM14934
Reference : DEC-06/2018
Policy No. : 5070270535-02 (31/12/2018)

LUMP SUM REPAIR BILL
REF : CLM14934-N51 DATED 06/12/2018
BY DIRECT

Amount S\$
5,000.00

E. & O.E.	Sub S\$:	5,000.00
	Add GST (7%) S\$:	350.00
	Total Amount S\$:	<u>5,350.00</u>

Hubby

for N-51 AUTOMOTIVE PTE LTD



TWINCAR RENTAL

Business Registration Number : 53092815M

Blk 2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 68420051 Fax : 67410510 email: sales@n51.com.sg

Invoice To :

RICHLAND LOGISTICS SERVICES PTE LTD
300 TAMPINES AVE 5
#05-02
SINGAPORE 529653

INVOICE

Invoice No. 13-2440

Date 12/12/2018

		Hirer's Car No.	VHA No.	Terms
		GBG3194T	71894	CASH
No. of Day	Description	Per Day	Amount (S\$)	
6	Car Rental from the period of 06/12/2018 to 12/12/2018. Vehicle no. GBG4478T Singapore Dollars Seven Hundred and Twenty Only	120.00	720.00	
		Total	\$720.00	

TWINCAR RENTAL



Authorised Signature



TWINCAR RENTAL

Kaki Bukit Autohub @ 2 Kaki Bukit Ave, 2 #01-18
Singapore 417921 Tel: 6744 0510 / 6842 0051

GBG 3194 T (NSI)

VHA No: 71894

ROC NO. 53092615M

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULAR Name: (as in I/C) <u>RICHLAND LOGISTICS SERVICES PTE LTD</u> NRIC/PASSPORT No: <u>1995004431D</u> Address (Res): <u>300 TAMPINES AVE 5</u> <u>#05-02 S (529653)</u> Name & Address of Employer: _____ Occupation: _____ Driving Exp: _____ Driving Licence No: _____ D/L Type: Local / International Pass Date: _____ Date of Birth: _____ Tel: (O) _____ (R) _____ HP _____		Vehicle No: <u>GBG 4478T</u> Replace Veh No: _____ Mileage Out: _____ Mileage Out: _____ Make & Model: _____ Auto / Manual Group: _____ OUT: Date <u>06/12/2018</u> Time: <u>11:30HRS</u> HIRE/PERIOD EXPIRY: _____ NON-WAIVER EXCESS: \$ _____																																																		
ADDITIONAL DRIVER'S PARTICULARS Name: (as in I/C) <u>QUAN CHEE MENG</u> NRIC/PASSPORT No: <u>S 790704011</u> Address (Res): <u>BUK 308 PUNGGOL WALK</u> <u>#17-564 S (822310)</u> Driving Licence No: <u>S 790704011</u> D/L Type: Local / International Pass Date: <u>06/12/1999</u> Date of Birth: <u>14/03/1979</u> Occupation: _____ Driving Exp: _____		<table border="1"> <thead> <tr> <th colspan="4">CHARGES</th> </tr> </thead> <tbody> <tr> <td>Daily</td> <td>@ \$</td> <td><u>120</u> per day</td> <td><u>6</u> \$720.00</td> </tr> <tr> <td>Weekly</td> <td>@ \$</td> <td>per week</td> <td></td> </tr> <tr> <td>Monthly</td> <td>@ \$</td> <td>per month</td> <td></td> </tr> <tr> <td>Hours</td> <td>@ \$</td> <td>per hour</td> <td></td> </tr> <tr> <td>Others</td> <td>@ \$</td> <td></td> <td></td> </tr> <tr> <td>CDW</td> <td>@ \$</td> <td>per day/month</td> <td></td> </tr> <tr> <td>PAI</td> <td>@ \$</td> <td>per day/month</td> <td></td> </tr> <tr> <td colspan="4">Delivery Service</td> </tr> <tr> <td colspan="4">SUB-TOTAL \$</td> </tr> </tbody> </table>		CHARGES				Daily	@ \$	<u>120</u> per day	<u>6</u> \$720.00	Weekly	@ \$	per week		Monthly	@ \$	per month		Hours	@ \$	per hour		Others	@ \$			CDW	@ \$	per day/month		PAI	@ \$	per day/month		Delivery Service				SUB-TOTAL \$												
CHARGES																																																				
Daily	@ \$	<u>120</u> per day	<u>6</u> \$720.00																																																	
Weekly	@ \$	per week																																																		
Monthly	@ \$	per month																																																		
Hours	@ \$	per hour																																																		
Others	@ \$																																																			
CDW	@ \$	per day/month																																																		
PAI	@ \$	per day/month																																																		
Delivery Service																																																				
SUB-TOTAL \$																																																				
VEHICLE CHECKLIST D - DENTS S - SCRATCHES A - ACCIDENTS 		<table border="1"> <thead> <tr> <th colspan="7">PETROL LEVEL</th> </tr> </thead> <tbody> <tr> <td>Out</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td>3/4</td> <td>F</td> <td></td> </tr> <tr> <td>In</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td>3/4</td> <td>F</td> <td></td> </tr> <tr> <td colspan="7">EXTENSION</td> </tr> <tr> <td colspan="7">Collection Service</td> </tr> <tr> <td colspan="7">Misc.</td> </tr> <tr> <td colspan="6">TOTAL CHARGE \$</td> <td><u>720.00</u></td> </tr> </tbody> </table>		PETROL LEVEL							Out	E	1/4	1/2	3/4	F		In	E	1/4	1/2	3/4	F		EXTENSION							Collection Service							Misc.							TOTAL CHARGE \$						<u>720.00</u>
PETROL LEVEL																																																				
Out	E	1/4	1/2	3/4	F																																															
In	E	1/4	1/2	3/4	F																																															
EXTENSION																																																				
Collection Service																																																				
Misc.																																																				
TOTAL CHARGE \$						<u>720.00</u>																																														
ACCESSORIES CHECK <input type="checkbox"/> Ashtray <input type="checkbox"/> Cig Lighter <input type="checkbox"/> S/Tyre <input type="checkbox"/> STD Tools <input type="checkbox"/> Jack <input type="checkbox"/> Hub Caps <input type="checkbox"/> Radio / Cass <input type="checkbox"/> CD <input type="checkbox"/> Cartridges		Rented out by: _____ Hirer's Signature: _____ Addition Driver's Signature: _____																																																		

I have read and agree to the terms & condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given TWINCAR RENTAL in connection with this Agreement is true.

* IMPORTANT

- ONLY PERSONS ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN, AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY TWINCAR RENTAL.

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO TWINCAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS
<u>12/12/2018</u>	<u>14:44HRS</u>			

SIGNATURE OF HIRER/DRIVER



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time : 04 Dec 2018 / 12:18:11

Receipt Date/Time : 04 Dec 2018 / 12:18:11

Tax Invoice/Receipt

Receipt No. : ITNET-00000-181204-001307

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHD3182Y As at 29 Nov 2018/10:45:00 Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SHD3182Y Enquiry Fee 20181204121731589655	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx2392	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Feb 2019 Edit Reg		04 Dec 2018 00:00 Edit Adj Rpt	\$55,000.00 Edit Estimates	\$55,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	RICHLAND LOGISTICS SERVICES PTE LTD , Co. Reg. No.: 199500443D								
Vehicle Reg. No.:	GBG3194T	Date of Loss:	29/11/2018 10:00 - :59 [16 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18110924	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHD3182Y	Policy No. (Claimant):	5070270535-02						
		Excess:							
Repairer:	N-S1 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/12/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (03/05/2019): Alert - Adj Mandate Approved (\$6077.45) - GBG3194T - Claim Handler: Sherini Pillai III_SG (29/03/2019): Alert - Adj Mandate Approved (\$0.00) - GBG3194T - Claim Handler: Sherini Pillai III_SG (14/12/2018): Alert - Adj Mandate Approved (\$0.00) - GBG3194T - Claim Handler: Sherini Pillai 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBG3194T (MCT18110924)
[SHD3182Y]

TP


















































RICHLAND LOGISTICS SERVICES PTE LTD


Nov 29 2018 10:00AM

[COMFORT TRANSPORTATION PTE LTD]

N-51 Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
2	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
3	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
4	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
5	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
6	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
7	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
8	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
9	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
10	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
11	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
12	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
13	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
14	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
15	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
16	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
17	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
18	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
19	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
20	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
21	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
22	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
23	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
24	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
25	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
26	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
27	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
28	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
29	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
30	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
31	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
32	14/12/18 07:40	General View		Load JPG	<input checked="" type="checkbox"/>
33	19/12/18 16:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
34	19/12/18 16:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	19/12/18 16:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
36	19/12/18 16:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
37	19/12/18 16:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	19/12/18 16:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	19/12/18 17:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	19/12/18 17:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	19/12/18 17:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	19/12/18 17:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	19/12/18 17:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	19/12/18 17:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	19/12/18 17:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	19/12/18 17:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	19/12/18 17:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	19/12/18 17:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	19/12/18 17:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	19/12/18 17:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	19/12/18 17:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/18 16:04	NOTIFICATION FROM WORKSHOP + TP GIA REPORT	 Load PDF	
2	05/12/18 16:04	ACKNOWLEDGEMENT EMAIL TO III DD 04.12.2018	 Load PDF	
3	03/05/19 09:14	LETTER OF DEMAND	 Load PDF	
4	03/05/19 09:14	LTA SEARCH FEE	 Load PDF	
5	03/05/19 09:14	RENTAL RECEIPT	 Load PDF	
6	03/05/19 09:14	TAX INVOICE	 Load PDF	
7	20/06/19 09:27	AUTHORISATION TO ACT FORM	 Load PDF	
8	20/06/19 09:27	DISCHARGE VOUCHER	 Load PDF	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	06/12/18 08:41	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18021915/APA3Q2

Date: 20/06/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No: MCOM0015
Claimant Vehicle No : GBG3194T	Insured Vehicle No : SHD3182Y
Date of Loss: 29/11/2018	Nature of Claim: TP Claim No: MCT18110924

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG3194T	Engine No:	1KD2688883
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	JTFHT02P000217057
Reg. Date:	20/07/2017 (Man. Year: 2016)	Odometer:	58294 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,089.06	4,313.29	3,775.77	46.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,710.00	1,950.00	760.00	28.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,799.06	6,263.29	4,535.77	42.00
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	10,799.06	5,000.00	5,799.06	53.70
+ GST 7.00/7.00% (S\$)	755.93	350.00	405.93	53.70
Nett Amount (S\$)	11,554.99	5,350.00	6,204.99	53.70
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,077.45		

INSPECTION

Date of Assignment:	04/12/2018	
Date Inspected:	06/12/2018 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI

BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 Feb 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG3194T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	706.00 FL	*539.00 FL
2	3		*REAR BUMPER LOWER BRACKET	Bent	75.00 FL	*75.00 FL
3	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	132.20 FL	*132.20 FL
4	1		*REAR END PANEL INNER	Repair	1,144.00 FL	*- FL
5	1		*REAR END PANEL OUTER	Dented	581.80 FL	*581.80 FL
6	1		*REAR EXHAUST PIPE	Repair	871.20 FL	*- FL
7	1		*REAR SPARE TYRE CARRIAGE	Bent	237.97 FL	*237.97 FL
8	1		*REAR SPARE TYRE CARRIAGE BRACKET	Bent	243.10 FL	*243.10 FL
9	1		*REAR SPARE TYRE CARRIAGE SCREW	Not Necessary	68.30 FL	*- FL
10	1		*REAR TAILGATE	Dented	2,205.30 FL	*1,855.00 FL
11	1		*REAR TAILGATE HIACE STICKER	Necessary	71.60 FL	*71.60 FL
12	1		*REAR TAILGATE LOGO STICKER	Necessary	71.60 FL	*71.60 FL
13	1		*REAR TAILGATE TOYOTA STICKER	Necessary	67.15 FL	*67.15 FL
14	1		*REAR TAILGATE CENTER LOCK CONTROL	Not Necessary	267.30 FL	*- FL
15	2		*REAR TAILGATE DAMPER L/R	Not Necessary	575.80 FL	*- FL
16	2		*REAR TAILGATE HINGES L/R	Not Necessary	137.80 FL	*- FL
17	2		*REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R	Not Necessary	57.00 FL	*- FL
18	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	70.20 FL	*- FL
19	1		*REAR TAILGATE MECHANISM LOCK	Damaged	263.00 FL	*263.00 FL
20	1		*REAR TAILGATE WEATHER STRIP	Cut	387.60 FL	*387.60 FL
21	1		*REAR TAILLAMP L/R	O/S Cracked	709.60 FL	*354.80 FL
22	2		*REAR TAILLAMP LOWER GARNISH L/R	Deformed	157.90 FL	*157.90 FL
23	2		*REAR TAILLAMP LOWER GARNISH SIDE RETAINER L/R	Not Necessary	44.00 FL	*- FL
24	1		*SET COMPANY 3D STICKER	Necessary	450.00 FS	*180.00 FS
25	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
26	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
27	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*15.00 FS
28	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
29	1		*REAR TAILGATE WINDSCREEN SEAL	Necessary	100.00 FS	*40.00 FS
30	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
31	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	60.00 FS	*20.00 FS
32	2		*SET REAR TAILLAMP LOWER GARNISH CLIPS L/R	Necessary	60.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part, S=SpcNett, L=ListItemDisc.						
Sub Total (S\$)					10,375.42	5,572.72
- List Item Discount on L Items 25.00/25.00% (S\$)					2,286.36	1,259.43
Total Parts (S\$)					8,089.06	4,313.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING ,AND REWIRE FOR PARKING SENSOR	New	120.00	30.00
2	TO REMOVE,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT, TRIM GARNISH ,TRIM LINER CARPER (TO FR)	New	140.00	0.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
5	TO REMOVE AND CHARGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	100.00	80.00
6	TO PROVIDE LABOUR,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR,RE-CONSTRUCT AND REALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	40.00
8	TO TRANSFER REAR TAILGATE INNER TRIM BOARD ,WIPER MOTOR ,MECHANISM LOCK OUTER HANDLE	New	80.00	80.00
Gross Labour Cost (S\$)			2,710.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >