



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SLJ1326J

Date of Accident : 03 December 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Global Advance Leasing

Date : 04 December 2018

Estimate To Repair GBE4131D - NISSAN NV200 1.5L MT ABS AIRBAG 2WD 6

Chassis No : VSKYBAM20Z0115398

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	left rear cargo door <i>3.500</i>	\$ 1,281.10
02	1 pc	left rear cargo door Nissan badge <i>ner</i>	\$ 66.40
03	1 pc	left rear cargo door NV200 badge <i>ner</i>	\$ 110.20
04	6 ps	left rear cargo door inner trimboard clips @ \$5.50 <i>17</i>	\$ 33.00
05	1 pc	left rear cargo door bottom lock <i>7m/3m</i>	\$ 101.50
06	1 pc	left rear cargo door bottom lock stricker <i>17</i>	\$ 97.10
07	1 pc	left rear cargo door checker/arrestor <i>17</i>	\$ 105.20
08	1 pc	left rear cargo door hinge bottom <i>17</i>	\$ 99.10
09	1 pc	left rear cargo door hinge top <i>17</i>	\$ 99.10
10	1 pc	left rear cargo door outer garnish <i>17</i>	\$ 336.00
11	1 pc	left rear cargo door back off camera <i>17</i>	\$ 606.00
12	1 pc	rear licence plate lamp <i>17</i>	\$ 67.50
13	1 pc	right rear cargo door <i>3.500</i>	\$ 960.90
14	1 pc	right rear cargo door weatherstrip <i>70.1</i>	\$ 96.40
15	1 pc	right rear cargo door DCI badge <i>ner</i>	\$ 56.20
16	1 pc	right rear cargo door lock bottom <i>7m/3m</i>	\$ 101.50
17	1 pc	right rear cargo door lock stricker bottom <i>17</i>	\$ 105.20
18	1 pc	rear bumper <i>10/12</i>	\$ 624.80
19	2 ps	rear bumper reflectors @ \$66.60 <i>17</i>	\$ 133.20
20	6 ps	rear bumper clips @ \$3.50 <i>ner</i>	\$ 21.00
21	1 pc	rear bumper energy absorber foam <i>70.1</i>	\$ 133.80
22	2 ps	rear bumper side retainers @ \$35.20 <i>17</i>	\$ 70.40
23	2 ps	rear bumper side holders @ \$53.10 <i>17</i>	\$ 106.20
24	2 ps	rear bumper brackets @ \$91.70 <i>17</i>	\$ 183.40
25	2 ps	rear lamps @ \$258.70 <i>17</i>	\$ 517.40
26	1 pc	rear end panel <i>R</i>	\$ 246.20
Less 10%			\$ 6,358.80
			\$ 1
			\$
<u>SPECIAL NETT ITEMS</u>			
27	1 pc	left rear cargo door 70 KM/H sticker <i>ner</i>	\$ 15.00
28	1 pc	left rear cargo door window glass sealant <i>ner</i>	\$ 100.00
29	1 pc	left rear cargo door window glass inner sponge seal <i>ner</i>	\$ 40.00
30	1 pc	rear licence plate <i>17</i>	\$ 80.00
31	1 pc	right rear cargo door window glass sealant <i>ner</i>	\$ 80.00
32	1 pc	right rear cargo door window glass inner sponge seal <i>ner</i>	\$ 40.00

*not authorized
Lal
5/12/18
2/5 4400/c
Hohy.
To the ph. After repair*

*5/12 - confirmed with
marcum.*

*1778
10%
3364.2
10
40
40
40*



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SLJ1326J
Date of Accident : 03 December 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Global Advance Leasing

Date : 04 December 2018

Estimate To Repair GBE4131D - NISSAN NV200 1.5L MT ABS AIRBAG 2WD 6
Chassis No : VSKYBAM20Z0115398

S/No	Quantity	Description	Amount
33	1 pc self	<u>SPECIAL NETT ITEMS</u> rear bumper parking sensor <i>shhh</i>	\$ 400.00
			\$ 755.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To remove and refit both rear cargo door window glass.	\$ 250.00
02		To rust-proofing of the affected areas.	\$ 180.00
03		To reinstall of rear bumper parking sensor.	\$ 120.00
04		To check electrical lighting concerned.	\$ 60.00
05		remove and renew back off camera settings.	\$ 120.00
06		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00
07		To transfer of both cargo door fittings and perform water seepage test.	\$ 200.00
08		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 850.00
09		Putty and spray painting of the affected portion.	\$ 950.00
			\$ 2,880.00
		Total	\$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

200

200

80

50

20

2

120

600

700

5504.2