

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD 734A

AAD1812-009

Not Authorized
Resurvey B4 paint
 @ 2789.93

| | |
|-----------------------|-------------------|
| Vehicle No.: | SHD 734A |
| Chassis No.: | VF1ABL15AUC283289 |
| Vehicle Make: | RENAULT |
| Vehicle Model: | LATITUDE |
| Date of Accident : | 01.12.2018 |
| Third Party Insurer : | AIG |

| PART | | LIST |
|--------------|---------------------------|-------------------------|
| 1 | BUMPER COVER FRT | \$ <i>Bu</i> 1,259.42 ✓ |
| 1 | BUMPER SPOILER FRT | \$ <i>Sn</i> 181.75 |
| 1 | BUMPER ABSORBER FRT | \$ <i>Sn</i> 394.68 |
| 1 | BUMPER RETAINER FRT LH | \$ <i>DI</i> 151.41 |
| 1 | BUMPER SUPPORT FRT | \$ <i>Sn</i> 123.88 |
| 1 | BUMPER RETAINER FRT RH | \$ <i>Sn</i> 150.77 |
| 1 | BUMPER SUPPORT FRT | \$ <i>Sn</i> 123.88 |
| 1 | BUMPER UNDERTRAY FRT | \$ <i>Sn</i> 472.83 |
| 1 | BUMPER GRILLE LOWER FRT | \$ <i>Sn</i> 266.80 |
| 1 | BUMPER FOG LAMP GRILLE LH | \$ <i>Sn</i> 207.21 |
| 1 | BUMPER BEAM FRT | \$ <i>R</i> 914.08 |
| 1 | HEADLAMP LH | \$ <i>Sn</i> 1,184.43 |
| 1 | HEADLAMP PANEL FRT LH | \$ <i>R</i> 152.15 |
| 1 | FENDER PANEL FRT LH | \$ <i>B1</i> 783.83 ✓ |
| 1 | WHEELARCH FRT LH | \$ <i>Sn</i> 278.84 X |
| 1 | FENDER BRACKET LOWER LH | \$ <i>Sn</i> 15.79 X |
| 1 | FENDER INSULATOR LH | \$ <i>Sn</i> 130.84 X |
| TOTAL | | \$ 6,792.61 |
| 10% | | \$ 679.26 |
| | | \$ 6,113.35 |

Special Nett

| | | |
|------|-------------------------------|----------------------|
| 1SET | BUMPER CLIP FRT | \$ <i>Ne</i> 66.00 ✓ |
| 1 | BUMPER BRACKET CLIP FRT LH | \$ <i>nn</i> 12.00 X |
| 1 | BUMPER SUPPORT CLIP FRT LH | \$ <i>nn</i> 10.50 X |
| 1SET | BUMPER GRILLE LOWER CLIP | \$ <i>nn</i> 69.00 X |
| 1SET | FRAME FULL SUPPORT PANEL CLIP | \$ <i>nn</i> 70.00 X |

Trans-cab Auto Services Pte Ltd

AAD1812-009

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 734A

| | | | |
|------|-------------------------------|----|-------------------|
| 2 | FRAME FULL SUPPORT PANEL NUT | \$ | <i>na</i> 20.00 X |
| 2 | FRAME FULL SUPPORT PANEL STUD | \$ | <i>na</i> 30.00 X |
| 1SET | WHEELARCH CLIP FRT RH | \$ | <i>na</i> 30.50 X |

| | |
|----|---------------|
| \$ | 308.00 |
|----|---------------|

| | | |
|--------------------|----|-----------------|
| TOTAL PARTS | \$ | 6,421.35 |
|--------------------|----|-----------------|

LABOUR

| | | |
|---|----|----------------------|
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 3,500.00 <i>400l</i> |
| Putty and spray painting of the affected portion. | \$ | 3,500.00 <i>440l</i> |
| To rust-proofing of the affected areas. | \$ | 170.00 <i>30l</i> |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | <i>na</i> 380.00 X |
| To check steering geometry and computer wheel alignment | \$ | <i>na</i> 220.00 X |
| To transfer of tire, rim and on wheel balancing. | \$ | <i>na</i> 170.00 X |
| To Check Electrical Lighting Concerned. | \$ | 170.00 <i>15l</i> |
| To transfer of front fender fittings, attachment and perform water seepage test. | \$ | <i>na</i> 380.00 X |
| To vacuum, replace, refix and recharge air condenser | \$ | <i>na</i> 380.00 X |
| To replace, refix and top up coolant for radiator | \$ | <i>na</i> 170.00 X |
| To vacuum, replace, refix and recharge Air Intercooler | \$ | <i>na</i> 170.00 X |

Trans-cab Auto Services Pte Ltd

AAD1812-009

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 734A

TOTAL \$ 9,210.00

Over All Total \$ 15,631.35

LUMP SUM (REPAIR DAY)

~~10 DAYS~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: