* INS. CASE OWNER	TAN, BONNIE	CC 3/ A1 6180	21924, K	chas gil	EKK: IDAC:
11.10g Int 1100 In 2003 In	140	ASSIGN	MENT	/	41.12
GOLDANDE.	1050	DOI:	17/10	Date / 1 me :	1.1.0
Pre-assign / CCU	FTE Charle	0010		Registered in Merin	nen: SIVIO
Insured Vehicle No	266 A	dollar	Claim No.	55756	113079G
101	102 H	405-1	Dodford Win		
Name of Insured		J -	Policy No.		
Insured Tel No.	i	HP:	Make / Model		
Excess Sec II :S\$	0	DOV: 30-11-18.	Place of Accide	nt s	
Is driver the owner	(VES / NO)	Nature of Accident :			
If NO, Driver Nar	ne / Age :		OI GIA REPOR	ET PES / NO : TP	GIA REPORT: YES / NO
Driver Tel	No. :	(V/L: YES// NO)	Insured Liability	y: %	Final? Yes/No
548 9836	16 <u> </u>				·
INSRS:	INSRS		INSRS:		INSRS:
WSP: O	WSP.		WSP:		WSP:
Tel: V I/V	Tel:	H	Tel: Liability:	H H	Tel: Liability:
RMKS:	RMKS	(M4/)	RMKS:		RMKS:
Date/ Time			. Troite Co.		
Tila.	SN091714 X	OK G MARIANA	10	STAGE	DATE/PIC
c. lin	21/2 1926 9 . 12	the Laws	300	Non-Reporting ltr (1)	
No				Non-Reporting ltr (2: Non-Reporting ltr (Fi	
1714 10 = 330 pm		to confirmed the mi		Notification ltr (if no	n-pickup):
-KINDUCINES		righerd in with a		Call OL	solostia - gassans
	- MNYCLERO	e official it applicat	-14	After call lir to Ol: /	
	- OKUGANAL TP L	NI CLO		Notification ltr (if no	the state of the s
				After call ltr to OI:	
			44171	Authorisation To Act	
30/07/19	- GAND ACCEDE		CP	Release Voucher:	
	- by 110. Au bo	00 IN OFFICE		Final Repair Bill:	
	- TO CLOSE.			Car Rental Invoice: Towing Invoice	
				LTA/ GIA:	
				Medical Bill	
				PTR:	
				Mandate/Reject Ins	truction:
				LOD	
				Payment Breakdow	
PRELIMINARY ADVICE	Date/Time:	Sent By:		Post-Repair Photos	
FINALIZATION	Date/Time:	Confirm with:		Others: Confirm by:	
Repair Cost: US	SS 21700.00 (5		%	Commin by.	Email Call
FINAL SETTLEMENT	Date/Time: 31107119	A STATE OF THE STA	H YIN	Email Call	
Final Liability:	56 60 (A) (A)	/ Assessed) BOLA S/N No.:	1	If NO or B 28, Ass	Lin
Repair Cost: (w/667)	55 2,889.00				MILLS AKOM
Loss of Rental (LOR):		5 days) X 15.25		MINORT	oup posso)
Loss of Use (LOU):	SS 750.00(S 50 X	5 days)		(2)(2)	BIK SPNC
LOS of Income (LOI): LOR only LOU only	The second secon	OR + LOI Tick only on	ė1	100	-1M
GLA/LTA Search	SS 7.19	The unit un		(9)	1819
Medical:	ss –				ml/Reject/Private Settle
Dishursement:	ss —	(e.g. Tow/ Independe	nt)	2) Report Format:	400-
Legal Cost	55 -	Clobal Sam CS. —		3) Survey fee:	4520.00
Total: FINAL PAYMENT	SS 3.512.44	Global Sum SS: — Confirm with:		Email Call	_
	SS 3,511.74	Name 1: TRANS - CA	M AUKO O	PERVICES	PTE UTD
Payee 1:	55 91944.44	Name 1: 10000000000000000000000000000000000		.,	, TO OLD
Payre 2: (Strike if N.A.) Prote 2: (Strike if N.A.)	55 -	Jame 3.	_		

1 11	
enneth	ASSIGNMENT
From: Date:	Veh No: SHB 9636B Yr Regn: 05, 13
Estimated Cost:	Type: M.Car / M. Cycle / Rus / Ven / Land
OD ITP JWS / TP RES / OD RES / EVA / INV / MV	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / Truck / Traller or
To inspect Vehicle No:	
at Workshop m/s Trans Cab	- CHESTORY CP129 CC 1799
of	The state of the s
Insured	Sp.Reading 787059 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	CNO: KLILAG9RJBB. 121888
Sum Insured: Excess:	Gen. Cond: Good / Fair / Poor / Burnt
(Client's Record)	Steering: Inprder / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: NII S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F: 195/65R15
Pomert: The yeb had	R:
repair at the time of inspection.	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
·Ų	TOYO / YOKO or GTT1
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 9 mm R/Bal. 9 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bai. 5° mm L/Bai. 2 mm
Est. Repairs: 05 days Res.: Yes or No	D.O.A. 30/11/18 D.O.I. 4/12/19
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / C	OUT NIS Are bods
- Controlled	The U/C / Chassis frame / Body Structure affected due to collision.
THE COUNTY HIS COUNTY	- Committee of the comm
21 hap 827 od	
CRUPD: \$ 11,002.77	locil 2
7 11,002.22	80 (0)
1	
do/Time, File Pass to?	
Freii. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
	Transportation:
Add Fe	99: : Site Insp (\$) _ s - RS _ SI
	: Interview (\$) Favors
	: Interview (3); Paotos
port Format :	Tech Invs (\$) Pacros
pport Format : mp Sum / I.B.I: (S	Toch In a 18

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHB 9636B

AAD1812-021

Not Nothern

Vehicle No.:	SHB 9636B
Chassis No.:	KL1LA69RJBB121888
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	30.11.2018
Third Party Insurer :	AIG
PART	LIST

1	1	Rear Fender LH	\$ By 1,145.00
2	1	Rear Fender Inner Trim LH	\$ Jh 418.44 x
3	1	Front Side Rocker Panel Garnish LH	\$ 54 236.40 X
4	1	Front Side Rocker Panel Outer LH	\$ M 600.00 ⊀
5	1	Front Side Rocker Panel Inner LH	\$ ₹ 519.30 X
6	1	Rear Bumper	\$ Bu 1,202.00 -
7	1	Rear Bumper Beam	\$ 7 239.94 /
8	1	Rear Bumper Centre Absorber	\$ 14 260.00 X
9	1	Rear Bumper Side Retainer RH	\$ 54 68.76 x
10	1	Rear Bumper Side Retainer LH	\$ 011 68.76
11	1	Rear Bumper Reflectors RH	\$ JL 119.74 X
12	1	Rear Bumper Reflectors LH	\$ /m 119.74×
13	1	Rear Bumper Tow Hook Cover	\$ ∫∟ 93.00 X

TOTAL	\$ 5,091.08	
10%	\$ 509.11	
	\$ 4,581.97	

Specical Nett

1	Rear Wheel Rim Hub Cap LH	\$ √5 166.30 X
1	Rear Tyre LH	\$ 180.00 ⊀
1	Rear Tyre Rim LH	\$ 330.00 ⊀
1	Rear rear door sticker '6555-3333'	\$ ~~ 80.00 ×
1Set	Rear Bumper Parking Sensor	\$ 54 300.00 X
1Set	Rear Bumper Fastener Clip	\$ Ma 44.00
1Set	Rear Fender Inner Trim Clip LH	\$ an 30.00 X

Trans-cab Auto Services Pte Ltd

AAD1812-021

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9636B

1Set	Rear Bumper End Dust Cover Clip	\$ 12 30.00 X
	TOTAL	\$ 1,160.30
	TOTAL PARTS	\$ 5,742.27
	LABOUR	
	To Check Electrical Lighting Concerned.	\$ 170.00 201
	Panel beating, knocking and straightening the necessary portion, remove and renewal of parts,	
	adjust and realign the same	\$ 3,000.00 6001
	Putty and spray painting of the affected portion.	\$ 3,000.00 400
	Towing Fees.	\$ ~~ 120.00 X
	To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$ ~~ 380.00 X
	To check steering geometry and computer wheel alignment	\$ ~~ 220.00 X
	To transfer of tire, rim and on wheel balancing.	\$ NA 170.00 X
	To rust-proofing of the affected areas.	\$ 170.00 3oL
	To check steering geometry and computer wheel alignment	\$ 220.00 X
	To transfer of tire, rim and on wheel balancing.	\$ ~~ 170.00 X
	To transfer of door fittings, attachment and perform water seepage test.	\$ ペル 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1812-021

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666

Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHB 9636B

To transfer of fender fittings, attachment and perform water seepage test.

\$

170.00 1001

TOTAL \$ 7,960.00

Over All Total \$

13,702.27

Repair Days (Lump Sum)

10 DAYS

5days

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis.
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID:	3878K	
Vehicle Details		
Vehicle No.:	SHB9636B	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	03 Dec 2018	
Vehicle Make:	CHEVROLET	
Vehicle Model:	EPICA 2.0D5L AT ABS D/AB 2WD 4DR TURBO	
Primary Colour:	Red	
Manufacturing Year:	2012	
Engine No.:	Z2051458413K	
Chassis No.:	KL1LA69RJBB121888	
Maximum Power Output:	110.0 kW (147 bhp)	
Open Market Value:	\$14.195.00	
Original Registration Date:	02 May 2013	
First Registration Date:	02 May 2013	
Transfer Count:	0	
Actual ARF Paid:	514.195.00	
Intended PARF Rebate Details		
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	01 May 2021	
PARF Rebate Amount:	\$9.936.00	
Intended COE Rebate Details		
COE Expiry Date:	01 May 2021	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	8	
PQP Paid:	\$57.045.00	
COE Rebate Amount:	\$17.192.00	
Total Rebate Amount:	\$27,128.00	
Maccana		

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Dec 2018

OK

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref

: AAD1812-021

Your Ref

: SKE499M

Date

: 12.February 2019

AIG ASIA PACIFIC INSURANCE

Dear Sir/Madam,

ACCIDENT INVOLVING SHB9636B AND SKE499M ON 30/11/18 04:10 PM ALONG TAMPINES AVENUE 1

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below:-

1.	Cost of Repair (inclusive of 7% GST)	S	2,889.00
2.	Loss of Rental for days @ \$_75.25 per day	\$	376.25
3,	Loss of Income for 5 days @ \$ 50 per day	5	250.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	5	0.00
	Total	S	3,522.74

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

Tel No.: 6603 1250 (DID)

Note: Please email any further correspondence to claims@transcab.com.sg (6603 1259)



51 UBI AYE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

30 JULY 2019

LEE HYOSIL BLOCK 760 BEDOK RESERVOIR ROAD #04-06 WATERFRONT WAVES SINGAPORE 479245

Dear Sir/Madam,

OUR REF

: CC3/AIG18021924/Kha3

YOUR REF : SKE 499M

ACCIDENT INVOLVING SKE 499M AND SHB 9636B ALONG TAMPINES AVENUE 8 ON 30.11.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SHB 9636B against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SHB 9636B. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD - if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter if not provided at AIG's reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)



51 UBLAVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Video footage of accident (if any)

Statement and/or police report from independent witness(es) (if any)

 If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2096 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh Case Handler DID: 6841 2096 FAX: 6741 4108

Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd (Motor Claims Dept)

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Authorization To Act

We, Trans-cab Services Pte Ltd of Company Registration No. 200303878K hereby authorize Trans-cab Auto Services Pte Ltd to act on behalf to claim for all losses incurred for the accident involving SHB9636B and SKE499M along TAMPINES AVENUE 1 on 30/11/18 04:10 PM.

In addition, we also hereby authorize the above payment to be made in favour of Trans-cab. Auto Services Pte Ltd upon settlement.

Dated this 12 (day) of February 2019

Yours Faithfully Trans-Cab Services Pte Ltd

Jasmine Tan General Manager

RELEASE VOUCHER (AIG Asia Pacific - Express Third Party Claim)

"We/I, TRANS-CAB AUTO SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$2,889.00 (Repair Cost), S\$626.25 (Loss of Rental/Use), S\$7.49 (Disbursement) for vehicle no. SHB 9636B that was damaged pursuant to the accident which occurred on 30/11/2018 (date) along TAMPINES AVENUE 1 (location) involving vehicle no/s SKE 499M. This is pursuant to the inspection conducted on 04/12/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner <u>TRANS-CAB SERVICES PTE LTD</u> ("the third party claimant") of vehicle no. <u>SHB 9636B</u> make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHB (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this <a> (day) of <a> Jusy (month) <a> 2019 (year)

Signed by appointed surveyor

Signed by "the workshop" (with chop)

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666 Fax: 6287 7764

Co. Reg. No.: 201019626G GST Reg. No.: 201019626G

Tax Invoice / Debit Note

TO:

AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way

#07-16 CHARTIS Building

079120 Singapore

ATTENTION:

DATE

: INV1901-036

: 2. January 2019 REFERENCE NO : AAD1812-021

TERMS DUE DATE

INVOICE NO.

: Net 30 Days

: 1. February 2019

PAGE

: 1

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1.	6050101	REPAIR-SHB9636B;DOA 30.11.18(PART-BY-PART-19)	1	2,889.00	2,889.00

Total SGD Excl. GST:

2,700.00

7% GST:

189.00

**** TWO THOUSAND EIGHT HUNDRED EIGHTY NINE SGD ONLY ****

Total SGD Incl. GST:

2,889.00

- 1) All cheques should be crossed and made payable to Trans-Cab Auto Services Pte Ltd*
- 2) Please quote our Invoice Number during payment.
- 3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.
- 4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

No. 2 Ang Mo Kio Street 63 Tel No.: 6287 6666 Fax No. 6281 1400 Co./GST Reg. No. 200303878K

12 February, 2019

To Whom It May Concern

Dear Sir / Madam,

Accident on 30/11/18 04:10 PM at TAMPINES AVENUE 1

- We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is the
 registered owner of the taxi bearing vehicle registration no. SHB9636B. The taxi was hired to NGO ENG
 HOCK a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of occurrence of the
 aforementioned accident at a rental rate \$75.25 per day (inclusive of GST).
- Please be advised that the Taxi is insured with AXA INSURANCE PTE LTD on a third party basis at the material time of the accident.
- 3. Please liaise with us directly for any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan General Manager

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

30-11-2018

Dear Sir/Madam,

Please be informed that the taxi was undergo accident repair in the workshop as follow:

Date In	Date Out	Vehicle No.		
Accident No.	AAD1812-021		Accident Date	30-11-2018
12/3/2018 15:40	12/7/2018 15:20	SHB9636B		

Yours Faithfully,

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

> Back to OneMotoring

Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name	
PA9320Y	01 Dec 2018 / 20:45:00	SOMPO INSURANCE SINGAPORE PTE. LTD.	
SLR2651X	02 Dec 2018 / 10:40:00	MSIG INSURANCE (SINGAPORE) PTE LTD	
SMA874K	01 Dec 2018 / 14:00:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.	
SKE499M	30 Nov 2018 / 16:10:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.	

OK Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING								
Case	Notified	Est Submitted	Adj Assigned	Ad) Rpt	Adj Submitted	Ins Authled	Status			
Main	03 Dec 2018 Edit Reg		04 Dec 2018 00:00 Edit Adj Rpt	S\$2,700.00 Edit Estimates	5\$2,700.00 View Rpt		Pending for Report Cancel Case	Survey		
	Main	R	eference	Claim De	tails	Documents		Show All		
CLAIM SU	BFOLDER DE	TAILS			[Created	by adjuster]				
Insured:	LEE HYOS	SIL, ID: G58420	77N							
Main Claimant:	TRANS-C	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg No.:	SHB963	6B		Date of		18 16:00 - :59 hs and 28 Days Fro	m LTA Reg Date (Man Yr)]		
Claim Type	TP / 537	5611307SG		Policy/C Note No		2100455115 (Comprehensive)				
Vehicle Reg No. (Insured):		5KE499M			vPX/P168	VPX/P1680520				
				Excess:	8					
Repairer	Trans-cat	Auto Services I	Pte Ltd () No 2 Ang	Mo Kio Street 63, 5	69111 Ang Mo Ki	o - Tel:				
Handling Insurer:	AIG Asia WZ.Tan@a		e Pte. Ltd. (Expres	s) - Tel: 65-6419-3	1000 [Handled	by Tan, Bennie-W	Z - 6419 1718] E	lennie-		
Claimant's Insurer:	AXA Insu	rance Pte Ltd (H	IQ) - Tel: 6338 7288							
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Handle	d by KENNETH K	ONG) [Final F	Rpt due 14/12/	2018]		
ASSOCIAT	ED MAIL RE	CEIVED				Vie	w All Composi	e Case Mail		
			FOR OI DETAILS> oad TP GIA Report							
ALL ASSO	CIATED TAS	ks⊟			View All	Search Tasks C	reate New Task	Complete		
Due Date	e Priority	Type Task	Group Subject	Handler	Assigned By	Completed On	Created On	Done?		

Claim Documents

*SHB9636B (5375611307SG)

[SKE499M]

TP

TRANS-CAB SERVICES PTE LTD

Nov 30 2018 4:00PM

[LEE HYOSIL]

Trans-cab Auto Services Pte Ltd

Let	ers/Corresponder	nces	1 per	page 🔻	4
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	
Pho	tos/Images		3 per	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Print
1	30/07/19 14:34	Odometer Reading	0	Load JPG	W
2	30/07/19 14:34	Chassis Number	0	Load JPG	V
3	30/07/19 14:34	General View	0	Load JPG	V
4	30/07/19 14:34	General View	0	Load JPG	V
5	30/07/19 14:34	General View	0	Load JPG	V
6	30/07/19 14:34	General View	0	Load 3PG	V
7	30/07/19 14:34	General View	0	Load JPG	V
В	30/07/19 14:34	General View	0	Load JPG	W
9	30/07/19 14:34	General View	0	Load JPG	V
10	30/07/19 14:34	General View	0	Load JPG	V
11	30/07/19 14:34	General View	0	Load JPG	2
12	30/07/19 14:34	General View	0	Load JPG	V
13	30/07/19 14:34	General View	0	Load 3PG	V
14	30/07/19 14:34	General View	0	Load JPG	V
15	30/07/19 14:34	General View	0	Load JPG	₩
-	1300007130	Technical From	-	6-00-01-0	CES
Doc	umentation		1 per	page 🗸	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/12/18 11:23	TP ESTIMATE - MARKED	0	Load PDF	
2	06/12/18 11:23	TP GIA REPORT	0	Load PDF	
3	31/07/19 06:50	LETTER TO 01	0	Load PDF	
4	16/08/19 08:43	WORKSHOP INVOICE	Ð	Load PDF	
5	16/08/19 08:43	AUTHORISATION TO ACT FORM	0	Load PDF	
6	16/08/19 08:43	Release Voucher	0	Load PDF	
7	16/08/19 08:43	RENTAL RECEIPT	0	Load PDF	
В	16/08/19 08:43	RENTAL MILEAGE	0	Load PDF	
9	16/08/19 08:43	LTA SEARCH	0	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	06/12/18 09:41	OI GIA REPORT	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

NOTE:	TO BE	COMPL	ETED	RY	SHRY	/FYO	R
NOIE	IU BE	COMPL		D 1	2017	10	n

TEAM		

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

	ricle No:	SKE499M (Insd veh)			M	Model:		CHEVROLET EPICA 2.0		
		SHB9636B (TP veh)						2.0DSL AT ABS D/AB 2		AT ABS D/AB 2WD
		30/11/2	2018						4DR TUR (A)	
_						_	_	-		
Glo	bal Sum Settlem	nent :	1 1	Yes	[X]	No				
Rep	pair Estimate			: \$		14,66	1.43			
Fin	al Repair Cost			: \$		2,889	.00			
Los	s of Use			: \$		250		_		ys at \$50.00 per day
Rei	ntal (if any)			: \$		376	.25	5	da	ys
LT/	I GIA Search F	ee		: \$		7	.49			
Oth	ers:			: \$		0	.00			
				: \$						
Fin	al Settlement Su	ım		: \$		3,522				
ls 1	hird Party Wor	kshop G	IA Regist	tered?	[]	YES	1	х]	NO	(Kindly indicate
411.11.11	For Non GIA R	legistere	d Works	hop:	Ag	reed Liab	ility		100	(%)
		tered w	orkshop:				-			BOLA Scenario No:
Rei	BOLA Liability:		(%)	nly for chair	As	sessed L	labil	ity (*):		(%) IOLA does not apply.
	BOLA Liability: * Assessed Lia marks	bility to b	(%) ne filled on		As	sessed L	labil	ity (*):		(%)
Pay	BOLA Liability: * Assessed Lia	bility to b	(%) ne filled on	kdown	As	sessed L	labil	ity (*):		(%)
Pay	BOLA Liability: * Assessed Liamarks marks ment Instruction	bility to b	(%) ne filled on	kdown	As	sessed Li	labil	ity (*):		(%) IOLA does not apply.
Pay 1) 2)	BOLA Liability: * Assessed Liamarks marks ment Instruction	bility to b	(%) ne filled on	kdown	As	sessed L ons and f	labil	ity (*):		(%) IOLA does not apply.
Pay 1) 2)	BOLA Liability: * Assessed Liamarks marks ment Instruction	bility to b	(%) ne filled on	kdown	As	sessed Lons and f	labil	ity (*):		(%) IOLA does not apply.
	BOLA Liability: * Assessed Liamarks marks ment Instruction	bility to b	(%) ne filled on	kdown	As	sessed L ons and f	labil	ity (*):		(%) IOLA does not apply.

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG18021924/KHA3Q2

Date:

16/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

2100455115

Claimant Vehicle SHB9636B

Insured Vehicle No:

SKE499M

No: Date of Loss:

30/11/2018

Nature of Claim:

TP

Claim No: 5375611307SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHB9636B

Make & Model:

CHEVROLET EPICA, 2.0 2.0DSL AT ABS D/AB

Engine No:

Z20S1458413K

Reg. Date:

02/05/2013 (Man. Year: 2012)

2WD 4DR TUR (A)

Chassis No:

KL1LA69RJBB121888

Colour:

Red/White

Odometer: 787069 km

Engine Capacity:

1991 oc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195/65 R15 Giti 9 mm

Rear Tyre Size: Rear Left Side:

195/65 R15 Giti 9 mm

Front Left Side: Front Right Side:

Giti 9 mm

Rear Right Side:

Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,742.27	2,218.18	3,524.09	61.37
Miscellaneous Items		0.00	0.00	0.00	
Labour		7,960.00	1,150.00	6,810.00	85.55
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	3,524.09 0.00 6,810.00	
	Calculated Gross Total (S\$)	13,702.27	3,368.18	10,334.09	75.42
	Approved Total (Overridden) (S\$)		2,700.00		
	(S\$)	13,702.27	2,700.00	11,002.27	80.30
	+ GST 7.00/7.00% (S\$)	959.16	189.00	770.16	80.30
	Nett Amount (S\$)	14,661.43	2,889.00	11,772.43	80.30
	+ Loss of Use (5.0 x S\$	250.00			
	+ Car Rental (5.0 x S\$	376.25			
	+ Doc/Search Fee (S\$)		7.49		
	Ne	tt Liability (S\$)	3,522.74		

INSPECTION

Date of Assignment:

04/12/2018

Date Inspected:

04/12/2018 Inspected At:

Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair:

5.0 days

Adjuster: KENNETH KONG Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER LH	Bent	1,145.00 FL	*1,145.00 FL
2	1		*REAR FENDER INNER TRIM LH	Serviceable	418.44 FL	*-FL
3	1		*FRONT SIDE ROCKER PANEL GARNISH LH	Serviceable	236.40 FL	*-FL
4	1		*FRONT SIDE ROCKER PANEL OUTER LH	Repair	600.00 FL	*-FL
5	1		*FRONT SIDE ROCKER PANEL INNER LH	Repair	519.30 FL	*-FL
6	1		*REAR BUMPER	Buckled	1,202.00 FL	*1,202.00 FL
7	1		*REAR BUMPER BEAM	Repair	239.94 FL	*-FL
8	1		*REAR BUMPER CENTRE ABSORBER	Serviceable	260.00 FL	*-FL
9	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	68.76 FL	*-FL
10	1		*REAR BUMPER SIDE RETAINER LH	Distorted	68.76 FL	*68.76 FL
11	1		*REAR BUMPER REFLECTOR RH	Serviceable	119.74FL	*-FL
12	1		*REAR BUMPER REFLECTOR LH	Serviceable	119.74FL	*-FL
13	1		*REAR BUMPER TOW HOOK COVER	Serviceable	93.00 FL	*-FL
14	1		*REAR WHEEL RIM HUB CAP LH	Serviceable	166.30 FS	*-FS
15	1		*REAR TYRE LH	Serviceable	180.00FS	*-FS
16	1		*REAR TYRE RIM LH	Serviceable	330.00 FS	*-FS
17	1		*REAR DOOR STICKER 6555-3333	Not Necessary	80.00FS	*-FS
18	1		*SET REAR BUMPER PARKING SENSOR	Serviceable	300.00FS	*-FS
19	1		*SET REAR BUMPER FASTENER CLIP	Necessary	44.00 FS	*44.00 FS
20	1		*SET REAR FENDER INNER TRIM CLIP LH	Not Necessary	30.00 FS	*-FS
21	1		*SET REAR BUMPER END DUST COVER CLIP	Not Necessary	30.00 FS	*-FS
F×Fm	inchise	part. S=SpcI	Nett. L=ListItemDisc.	Cub Tatal (CC)	0.054.00	2 450 75
			List Item Dissecut on Litem	Sub Total (S\$)	6,251.38	2,459.76
			- List Item Discount on L Item	5 10.00/10.00% (5\$)	509.11	241.58
				Total Parts (S\$)	5,742.27	2,218.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,000.00	600.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	400.00
4	TOWING FEES	New	120.00	0.00
5	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
12	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	100.00
	Gross Labou	r Cost (S\$)	7,960.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >