



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBK2125D PGO IME150 3 WHEELER REPAIR ESTIMATE 07/12/2018

ITEM	DESCRIPTION	AMOUNT SGD
1	REAR WHEEL ASSY	Sum \$320.00 X
2	REAR WHEEL AXLE & BUSHING	\$448.00 ?
3	REAR FENDER RH	Sum \$255.00 ✓
4	STAY. REAR FENDER	Sum \$45.00 ✓
5	FRONT FENDER	Sum \$165.00 ✓
6	FRONT FORK LH	\$492.08 ?
7	FRONT FORK RH	\$492.08 ?
8	STEM STEERING	\$245.00 ?
9	CONE BEARING SET	\$95.00 ?
10	FRONT WHEEL	11 \$280.00 X
11	FRONT WHEEL AXLE	Sum \$55.00 ✓
12	FRONT LOWER FAIRING RH	Sum \$95.00 ✓
13	BACK SHIELD	\$209.00 ?
14	LOWER SIDE PANEL RH	Sum \$85.00 ✓
15	HANDLEBAR	\$294.00 ?
16	WINDSHIELD	Sum \$300.00 X
17	BRAKE LEVER	Sum \$25.00 ✓
18	BALANCER	Sum \$26.15 ✓
19	HANDLE GRIP	Sum \$50.00 ✓
20	SIDE MIRROR	Sum \$35.00 ✓
21	TRANSPORTATION TP/ IDAC/ W-SHOP @\$100	\$200.00 100
22	WORKMANSHIP (REMOVE ,REPLACE & REPAIR DAMAGED AREAR)	\$350.00 300
23	TRANSPORTATION 2-WAY TO REPAIR CHASSIS @\$100	\$200.00 ?
24	BODY CHASSIS REPAIR	\$450.00 ?
25	SPRAY PAINTING (F-FENDER /REAR RENDER & CHASSIS)	\$300.00 ?
26	REAR TOP BOX	Sum \$250.00 X
TOTAL		\$5,761.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Accepted
L/s S
H. L.
Steph
13/12/18