

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE.

速良摩哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒杆噴漆
代理保險：車禍
賠償及買賣汽車

M/S YONG LEE SENG HOLDINGS PTE LTD

DATE : 29/11/2018

DOA : 23/11/2018

ESTIMATE REPAIR FOR VEHICLE NO. GBC 2760 L (NISSAN CABSTAR)

	Description	Nett Price
1 pc	Tailgate	\$ 1,450.70
1 pc	Rear end panel (floor)	\$ 1,550.40
1 pc	Tailgate side bracket(rh)	\$ 155.80
1 pc	Taillamp (rh)	\$ 168.40
1 pc	Taillamp bracket (rh)	\$ 170.70
1 pc	Nissan sticker	\$ 78.00
		\$ 3,574.00
	Less : 10%	\$ (357.40)
		\$ 3,216.60
		1451 102 1308.90
	<u>Special Nett Items</u>	
1 pc	70km/h sticker	\$ 10.00
1 pc	13 PAX sticker	\$ 10.00
	Labour charges for knocking & replacing parts	\$ 700.00
	Spraypainting	\$ 500.00
	TOTAL :	\$ 4,436.60
		600 480 2405.9

Not Authorized
after
L/S #1900/
Hony.
5/11/18
Wharhos Hony

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: