

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 7502 D .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>replaced</i>	\$ 1,907.00	✓ 1525.60
2	REAR BUMPER FIXING PARTS	\$ 63.00	x
3	REAR BUMPER SECURING PLATE	4 \$ 56.00	x
4	REAR BUMPER SEALING PLATE	4 \$ 9.00	x
5	REAR BUMPER SECURING STRIP	\$ 191.00	x
6	REAR BUMPER SPOILER	\$ 216.00	x
7	REAR LIGHT RELECTOR-LH/RH	2 \$ 70.00	x.
8	REAR BUMPER GUIDE SECTION-RH	\$ 38.00	x
9	REAR BUMPER UPPER GUIDE SECTION-RH	\$ 19.00	x.
10	REAR BUMPER SEAL RING	4 \$ 14.00	x.
11	REAR SECTIONAL PART-SIDE PANEL-RH <i>Replaced</i>	\$ 2,347.00	✓ 1877.60
12	REAR WINDSCREEN <i>new</i>	\$ 1,014.00	? 811.70 ✓
13	REAR SIDE WINDOW-RH <i>new</i>	\$ 541.00	? 437.40 ✓
14	PRIMER <i>new</i>	2 \$ 37.00	✓ 29.12
15	REAR SIDE WINDOW TRIM STRIP-RH	\$ 426.00	x
16	LED TAILLIGHT-RH	\$ 915.00	x
17	LED TAILLIGHT TRIM-RH	\$ 26.00	x
18	ACRYLIC SEALANT	S/N \$ 180.00	✓
19	CAVITY WAX	S/N \$ 140.00	✓
20	STONE CHIP	S/N \$ 180.00	✓
SUB TOTAL SPARE PARTS		\$ 8,389.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 7502 D .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	METAL FILLER POWDER	S/N \$ 280.00 ✓	
22	REAR WINDSCREEN SEALANT	S/N \$ 200.00 ✓	
23	1/4GLASS SEALNT	S/N \$ 100.00 ✓	
24	SUNDRIES	\$ 500.00 ?	(S, 18 ✓
TOTAL SPARE PARTS		: \$ 9,469.00	
TOTAL LABOUR CHARGES		: \$ 12,652.00	
GRAND TOTAL		: \$ 22,121.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian Lij
05/12/18.

Surveyed Date

:

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 12 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1372/2018/GW
Date : 28-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

11 days - ok - jb - 20 Feb 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Jayamohan S/O Jayabal @ Leonbard Jayamohan
Address : 7 Siglap Road
: #14-63
Singapore 448909
Telephone : HP +65 96330648
Type of Claim : Own Damage Claim
Policy No. : 2100479413-02
Vehicle No : **SLE 7502 D**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Jul-16
Engine No : CVN 014928
Chassis No : WAUZZZF45GA112063
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Nov-18
Place of Accident : Blk 86 Marine Parade Rd HDB Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLE 7502 D.

S/N	Nature of Jobs	Estimated Charges			
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N	\$	360.00	\$ 360.00
2	To renew rhs 1/4 glass and rear windscreen to facillitate fender renewal.	S/N	\$	600.00	\$ 600.00
3	To dislodge and reinstall rear wire harness for lights, battery manager , fuse and relay trays, electrical and audio equipment.	S/N	\$	1,400.00	\$ 1,400.00
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$	1,400.00	\$ 1,400.00
SUB TOTAL LABOUR CHARGES		:	\$	<u>3,760.00</u>	\$ <u>3,760.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLE 7502 D .

S/N	Nature of Jobs	Estimated Charges		
		<i>c/f</i>	\$	3,760.00
5	To dismantle rear bumper and rear lid. To cut out and reweld rhs rear fender. Inspect rhs wheel housing inner for further damages. To renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 4,800.00	\$	3,000.00
6	To respray rear bumper, rhs rear fender, rhs sill panel, door entrances, roof channel drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 3,900.00	\$	2,200.00
7	To carry out diagnostic check.	S/N \$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 12,652.00	\$ 9,152.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 7502 D .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,907.00	\$ 1,525.60
2	REAR BUMPER FIXING PARTS	\$ 63.00	
3	REAR BUMPER SECURING PLATE	4 \$ 56.00	
4	REAR BUMPER SEALING PLATE	4 \$ 9.00	
5	REAR BUMPER SECURING STRIP	\$ 191.00	
6	REAR BUMPER SPOILER	\$ 216.00	
7	REAR LIGHT RELECTOR-LH/RH	2 \$ 70.00	
8	REAR BUMPER GUIDE SECTION-RH	\$ 38.00	
9	REAR BUMPER UPPER GUIDE SECTION-RH	\$ 19.00	
10	REAR BUMPER SEAL RING	4 \$ 14.00	
11	REAR SECTIONAL PART-SIDE PANEL-RH	\$ 2,347.00	\$ 1,877.60
12	REAR WINDSCREEN	\$ 1,014.00	\$ 811.20
13	REAR SIDE WINDOW-RH	\$ 541.00	\$ 432.40
14	PRIMER	2 \$ 37.00	\$ 29.12
15	REAR SIDE WINDOW TRIM STRIP-RH	\$ 426.00	
16	LED TAILLIGHT-RH	\$ 915.00	
17	LED TAILLIGHT TRIM-RH	\$ 26.00	
18	ACRYLIC SEALANT	S/N \$ 180.00	\$ 180.00
19	CAVITY WAX	S/N \$ 140.00	\$ 140.00
20	STONE CHIP	S/N \$ 180.00	\$ 180.00
SUB TOTAL SPARE PARTS		\$ 8,389.00	\$ 5,175.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 7502 D .

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f	\$	5,175.92
21	METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
22	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
23	1/4GLASS SEALNT	S/N	\$ 100.00	\$ 100.00
24	SUNDRIES		\$ 500.00	\$ 18.08
	TOTAL SPARE PARTS	:	\$ 9,469.00	\$ 5,774.00
	TOTAL LABOUR CHARGES	:	\$ 12,652.00	\$ 9,152.00
	GRAND TOTAL	:	\$ 22,121.00	\$ 14,926.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLE 7502 D

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1372/2018/MAS

24 April 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLE 7502 D, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLE 7502 D**, claimant, **Mr. Jayamohan S/o Jayabal @Leonard Jayamohan**, please find the related document per attached.

1. A copy of the Original invoice no. 85013692 – S\$15,328.82
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLE 7502 D

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLE7502D

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1372/2018/JE
17 January 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 Sedan 1.4 TFSI
Vehicle Chassis No. : WAUZZZF45GA112063
Vehicle Regn No. : **SLE 7502 D**
Vehicle Mileage : **57252 KM**
Vehicle Owner : Mr. Jayamohan S/O Jayabal
Certificate No : 2100479413-02
Own Damage Excess : **SS 642.00 (Inclusive 7% GST)**
Accident Date : 27/11/2018
Place : Blk 86 Marine Parade Rd HDB Carpark
Repair Cost : \$ 15,328.82
WIP No. : 33637
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 11:05 AM
Date : 19 JAN 2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Dec 2018		05 Dec 2018 16:48 Edit Adj Rpt	\$S\$14,926.00 Edit Estimates	\$S\$14,926.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	JAYAMOHAN S/O JAYABAL @LEONARD JAYAMOHAN, ID: S2688005Z, Tel: +6596330648, Email: LEONARD_JAY@YAHOO.COM		
Vehicle Reg. No.:	SLE7502D	Date of Loss:	27/11/2018 12:00 - :59 [27 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 7944468787SG	Policy/Cover Note No.:	2100479413-02 (Comprehensive)
		Excess:	\$S\$600.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/12/2018]		
Driver/Custodian:	JAYAMOHAN S/O JAYABAL @LEONARD JAYAMOHAN (52 / Male), NRIC: S2688005Z, Tel: +6596330648 Email: LEONARD_JAY@YAHOO.COM		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (02/04/2019): Alert - Adj Mandate Approved (\$S\$14926.00) - SLE7502D - Claim Handler: Dally Amri...
- AIG_SG (06/12/2018): Alert - Adj Mandate Approved (\$S\$14523.00) - SLE7502D - Claim Handler: Dally Amri...
- AIG_SG (06/12/2018): SLE7502D / OD / 27/11/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLE7502D (7944468787SG)**

OD

Nov 27 2018 12:30PM

[JAYAMOHAN S/O JAYABAL @LEONARD JAYAMOHAN]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser ▾		
Video															1 per page ▾			☒		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)													Thumbnail			Print		
1	28/11/18 08:45	Video - Accident [Linked Accident Report Documents]													1 Load MP4					
Assessment Reports															1 per page ▾			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	06/12/18 14:25	Adjuster Immediate Advice													1 Load HTM					
2	26/02/19 14:47	Adjuster Immediate Advice													1 Load HTM					
Photos/Images															3 per page ▾			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	06/12/18 14:20	General View													1 Load JPG			☒		
2	06/12/18 14:20	Chassis Number													1 Load JPG			☒		
3	06/12/18 14:20	General View													1 Load JPG			☒		
4	06/12/18 14:20	General View													1 Load JPG			☒		
5	06/12/18 14:20	General View													1 Load JPG			☒		
6	06/12/18 14:20	General View													1 Load JPG			☒		
7	06/12/18 14:20	General View													1 Load JPG			☒		
8	06/12/18 14:20	General View													1 Load JPG			☒		
9	06/12/18 14:20	General View													1 Load JPG			☒		
10	06/12/18 14:20	General View													1 Load JPG			☒		
Documentation															1 per page ▾			☒		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail			Print		
1	06/12/18 10:33	Driver's Driving License													1 Load PDF					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	06/12/18 14:19	Singapore Accident Statement													1 Load PDF					
2	06/12/18 14:19	Certificate of Insurance													1 Load PDF					
3	06/12/18 14:19	Driver's Driving License													1 Load PDF					
4	06/12/18 14:19	ESTIMATE													1 Load PDF					
5	26/02/19 14:44	REVISED ESTIMATE													1 Load PDF					
6	13/05/19 09:49	DISCHARGE VOUCHER													1 Load PDF					
7	13/05/19 09:49	WORKSHOP INVOICE													1 Load PDF					

Linked Accident Report Documents

										View		View in Browser ▾	
Video										1 per page ▾		☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)							Thumbnail	Print			
1	28/11/18 08:45	Video - Accident							Load MP4				
Assessment Reports										1 per page ▾		☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)							Thumbnail	Print			

Video			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/11/18 08:58	Accident Statement	 Load HTM	☒

Photos/Images			3 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/11/18 08:51	Accident Photo	 Load JPG	☒
2	28/11/18 08:51	Accident Photo	 Load JPG	☒
3	28/11/18 08:51	Accident Photo	 Load JPG	☒
4	28/11/18 08:51	Accident Photo	 Load JPG	☒
5	28/11/18 08:51	Accident Photo	 Load JPG	☒
6	28/11/18 08:51	Accident Photo	 Load JPG	☒
7	28/11/18 08:51	Accident Photo	 Load JPG	☒
8	28/11/18 08:51	Accident Photo	 Load JPG	☒

Documentation			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/11/18 08:43	Sketch Plan	 Load JPG	☒
2	28/11/18 08:43	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18021927/AQBS2

Date: 13/05/2019

REFERENCE

Insured/Claimant: JAYAMOHAN S/O JAYABAL @LEONARD JAYAMOHAN Policy No: 2100479413-02
Date of Loss: 27/11/2018 Nature of Claim: OD Claim No: 7944468787SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE7502D	Engine No:	CVN014928
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF45GA112063
Reg. Date:	29/07/2016 (Man. Year: 2016)	Odometer:	56056 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$107,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,469.00	5,774.00	3,695.00	39.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,652.00	9,152.00	3,500.00	27.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,121.00	14,926.00	7,195.00	32.53
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	21,521.00	14,326.00	7,195.00	33.43
+ GST 7.00/7.00% (S\$)	1,506.47	1,002.82	503.65	33.43
Nett Amount (S\$)	23,027.47	15,328.82	7,698.65	33.43

INSPECTION

Date of Assignment:	05/12/2018		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	05/12/2018	Inspected At:	55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	11.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,907.00 FS	*1,525.60 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	63.00 FS	*- FS
3	4		*REAR BUMPER SECURING PLATE	Not Necessary	56.00 FS	*- FS
4	4		*REAR BUMPER SEALING PLATE	Not Necessary	9.00 FS	*- FS
5	1		*REAR BUMPER SECURING STRIP	Not Necessary	191.00 FS	*- FS
6	1		*REAR BUMPER SPOILER	Not Necessary	216.00 FS	*- FS
7	2		*REAR LIGHT RELECTOR - LH/RH	Not Necessary	70.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	38.00 FS	*- FS
9	1		*REAR BUMPER UPPER GUIDE SECTION - RH	Not Necessary	19.00 FS	*- FS
10	4		*REAR BUMPER SEAL RING	Not Necessary	14.00 FS	*- FS
11	1		*REAR SECTIONAL PART - SIDE PANEL - RH	Dented	2,347.00 FS	*1,877.60 FS
12	1		*REAR WINDSCREEN	Necessary	1,014.00 FS	*811.20 FS
13	1		*REAR SIDE WINDOW - RH	Necessary	541.00 FS	*432.40 FS
14	2		*PRIMER	Necessary	37.00 FS	*29.12 FS
15	1		*REAR SIDE WINDOW TRIM STRIP- RH	Not Necessary	426.00 FS	*- FS
16	1		*LED TAILLIGHT - RH	Not Necessary	915.00 FS	*- FS
17	1		*LED TAILLIGHT TRIM - RH	Not Necessary	26.00 FS	*- FS
18	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
19	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
20	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
21	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
23	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
24	1		*SUNDRIES	Necessary	500.00 FS	*18.08 FS

F=Franchise part, S=SpcNett.

Total Parts (\$\$)	9,469.00	5,774.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	New	360.00	360.00
2	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	New	600.00	600.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	New	1,400.00	1,400.00
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	New	1,400.00	1,400.00
5	TO DISMANTLE REAR BUMPER AND REAR LID. TO CUT OUT AND REWELD RHS REAR FENDER. INSPECT RHS WHEEL HOUSING INNER FOR FURTHER DAMAGES. TO RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	4,800.00	3,000.00
6	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	New	3,900.00	2,200.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			12,652.00	9,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >