



Case Details

Case Reference Number :

TAX/12/18/2002

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB1366H

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-4811-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 02/12/2018 09:25 AM

Vehicle Age(In Months) : 61

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95 <i>de</i>	Replace ▾	
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08 <i>un</i>	Replace ▾	
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0 ?	Check ▾	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0 ?	Check ▾	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0 ?	Check ▾	
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	25.00	118.05	Replace	0	0 X	Not Give ▾	
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00 <i>un</i>	Replace ▾	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00 <i>un</i>	Replace ▾	
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0 ?	Check ▾	
Total Spare Part Cost									2,903.68			Surveyor Total	798.23	
Lump Sum Discount (%)									20.00			Lump Sum Dis (%)	20	
Final Spare Part Cost									2,322.94			Final Sur Total	638.58	

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	? Check
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	? Check
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	X Not Give
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	1	0	Ry Repair
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0	X Not Give
Total Spare Part Cost									2,903.68		Surveyor Total	798.23	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									2,322.94		Final Sur Total	638.58	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	338.00	200	
Total:		338.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY BUMPER BEAM	180.00	0	
3	TO RESPRAY REAR SPOILER	180.00	100	
Total:		738.00	300.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
2	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
3	TO WASH AND VACUUM	60.00	0	
4	TOWING CHARGE	84.00	60	
Total:		344.00	120.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,322.94	638.58
Total Labour Cost	338.00	200.00
Total Spray Painting	738.00	300.00
Other	344.00	120.00
Overall Total	3,742.94	1,258.58
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	3,750.00	1,250.00
Surveyor Approved Amount		1,250.00
No of Repair Days*	3	2
Remarks	-	Resurvey after repair
Surveyor Name		Taufikh
Signature		
Survey Date	04/12/2018	

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: