



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLN6449J
Date of Accident : 24 November 2018

Mr Nayagam Anthony

Date : 30 November 2018

Estimate To Repair SJN1742T - NISSAN LATIO 1.5 4A/T SPORT BASE ABS
Chassis No : JN1FAAC11Z0010456

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	tailgate lid <i>74</i> ✓	\$ 1,314.70
02	1 pc	tailgate lid outer handle <i>repair</i>	\$ 88.90
03	1 pc	tailgate lid inner trimboard bottom X	\$ 256.00
04	1 pc	rear end panel <i>74</i> ✓	\$ 442.60
05	1 pc	rear bumper <i>DE</i> ✓	\$ 651.00
06	2 ps	rear bumper side retainer @ \$25.00 <i>NE</i> ✓	\$ 50.00
07	1 pc	rear bumper inner sponge <i>DE</i> ✓	\$ 38.60
08	1 pc	rear licence plate bracket <i>74</i> ✓	\$ 55.00
09	1 pc	rear licence plate lamp X	\$ 54.00
10	1 pc	tailgate lid rubber <i>NE</i> ✓	\$ 98.30
11	1 pc	rear exhaust box X	\$ 513.10
12	1 pc	rear exhaust box heat shield X	\$ 95.00
13	2 ps	rear exhaust box mounting @ \$65.00 X	\$ 130.00
14	1 pc	front bumper <i>DE</i> ✓	\$ 456.30
15	2 ps	front bumper side retainers @ \$33.00 <i>NE</i> ✓	\$ 66.00
16	1 pc	right headlamp assy X	\$ 486.30
17	1 pc	front bumper fog lamp right X	\$ 320.70
18	16 ps	front and rear bumper clips @ \$4.50 <i>NE</i> ✓	\$ 72.00
19	1 pc	radiator grille garnish X	\$ 48.30
20	6 ps	radiator grille garnish clips @ \$4.50 X	\$ 27.00
			\$ 5,263.80
		Less 30 %	\$ 1,579.14
			\$ 3,684.66
		<u>NETT ITEMS</u>	
21	2 ps	rear lamps @ \$319.40 <i>CRA</i> ✓	\$ 638.80
22	1 pc	tailgate lid wiper cover X	\$ 55.00
23	1 pc	tailgate lid Latio badge <i>NE</i> ✓	\$ 56.20
24	1 pc	tailgate lid centre emblem badge <i>NE</i> ✓	\$ 45.60
25	1 pc	tailgate lid inner lock <i>74</i> ✓	\$ 143.10
26	1 pc	tailgate lid inner lock motor X	\$ 253.70
27	1 pc	tailgate lid windscreen glass moulding <i>NE</i> ✓	\$ 128.70
28	1 pc	rear end panel inner trimboard <i>DE</i> ✓	\$ 73.10
29	1 pc	front radiator grille X	\$ 395.30
			\$ 1,789.50
		Less 10 %	\$ 178.95
			\$ 1,610.55
		<u>SPECIAL NETT ITEMS</u>	
30	1 pc	tailgate lid windscreen inner sponge seal <i>NE</i> ✓	\$ 40 60.00
31	1 pc	tailgate lid windscreen sealant <i>NE</i> ✓	\$ 60 100.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLN6449J
Date of Accident : 24 November 2018

Mr Nayagam Anthony

Date : 30 November 2018

Estimate To Repair SJN1742T - NISSAN LATIO 1.5 4A/T SPORT BASE ABS
Chassis No : JN1FAAC11Z0010456

S/No	Quantity	Description	Amount
<u>SPECIAL NETT ITEMS</u>			
32	1 pc	rear licence plate <i>PK /</i>	\$ 35 80.00
33	1 pc	rear bumper parking sensor <i>nu /</i>	\$ 200 450.00
			\$ 690.00
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 60.00 <i>30</i>
02		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 200.00 <i>100</i>
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00 <i>80</i>
04		To remove and refit rear windscreen glass.	\$ 150.00 <i>120</i>
05		To reinstall of rear bumper parking sensor.	\$ 100.00 <i>60</i>
06		To drop rear exhaust box and renew the same.	\$ 200.00 <i>X 1000</i>
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,600.00 <i>1000</i>
08		Putty and spray painting of the affected portion.	\$ 1,200.00 <i>1000</i>
			\$ 3,660.00
		Total	\$ 9,645.21

Passul
Hp 90010068
9 days / L/S
30/11/18 @ 1225
Resolving after repair