

A-Tec Automotive Pte Ltd
8 Kaki Bukit Avenue 4
#04-20 Premier
Singapore 415875

GBD3889M Nissan NV350

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy <i>dent</i>	\$ 1,635.50 ✓
2	1	Front right 'B' pillar <i>dent</i>	\$ 823.10 +
3	1	Front right sliding door panel assy <i>Dented</i>	\$ 1,637.20 ✓ ←
4	1	Front right door panel assy <i>Dented</i>	\$ 1,476.30 ✓
5	1	Rear right fender assy <i>dent</i>	\$ 3,810.40 +
		<i>Rear Bumper</i>	\$ 9,382.50
		Less 30%	\$ 2,814.75
			<u>\$ 6,567.75</u>

6	1	Front right bumper bracket <i>new</i>	\$ 85.20 +
7	1	Front right bumper retainer <i>apd.</i>	\$ 88.90 ✓
8	1	Front right door lock mechanism <i>new</i>	\$ 167.20 +
9	1	Front right door outer handle <i>new</i>	\$ 175.20 +
10	1	Front right door inner board <i>new</i>	\$ 310.20 +
11	1	Front right door regulator linkage with motor <i>new</i>	\$ 480.50 +
12	1	Front right step garnish <i>missing</i>	\$ 278.20 ✓
13	1	Front right sliding door outer handle <i>new</i>	\$ 78.10 +
14	1	Front right sliding door lock mechanism <i>new</i>	\$ 193.60 +
15	1	Front right headlamp <i>lt</i>	\$ 835.70 ✓
16	1	Front right fog lamp <i>new</i>	\$ 282.30 +
17	1	Front right fog lamp garnish <i>new</i>	\$ 136.40 +
18	1	Front right lower arm ?	\$ 429.30 ?
19	1	Front right shock absorber ?	\$ 385.20 ?
20	1	Front right knuckle arm ?	\$ 398.30 ?
21	1	Front right wheel hub bearing ?	\$ 252.40 ?
22	1	Front right idler arm ?	\$ 145.10 ?
23	1	Rear right shock absorber	\$ 375.10 +
24	1	Rear axle carrier complete assy <i>new</i>	\$ 4,850.20 +
25	1	Rear right leaf spring	\$ 750.10 +
		<i>Trunk</i>	\$ 10,697.20
		Less 10%	\$ 1,069.72
			<u>\$ 9,627.48</u>

Special Nett Items

1	1	Front right wheel rim <i>Distorted</i>	\$ 450.00/180.
2	1	Front right tyre <i>Pinched</i>	\$ 350.00/150.
3	1	Front right wheel rim cover <i>Missing</i>	\$ 150.00/60
4	1	Front right door company sticker <i>new</i>	\$ 50.00/30
5	1	Rear right sliding door glass sealant <i>new</i>	\$ 100.00/50.
6	1	Rear right wheel rim <i>Distorted</i>	\$ 450.00/180
7	1	Rear right tyre <i>Pinched</i>	\$ 350.00/150
8	1	Rear right wheel rim cover <i>Missing</i>	\$ 150.00/60
9	10	Front bumper clips <i>new</i>	\$ 50.00/30.
			<u>\$ 2,100.00</u>

Total parts

\$ 18,295.23

A-Tec Automotive Pte Ltd
8 Kaki Bukit Avenue 4
#04-20 Premier
Singapore 415875

GBD3889M Nissan NV350

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front right, rear right affected area and replace front right and rear right damaged parts.	\$ 2,500.00 1200
2	To putty and spray painting front right and rear right portion.	\$ 2,500.00 1200
3	To remove and install front right sliding door lock mechanism.	\$ 80.00 40
4	To remove and install front right door lock mechanism.	\$ 80.00 60
5	To apply anti rust proofing to accident affected area.	\$ 120.00 50 ←
6	To check central locking for function.	\$ 80.00 x
7	To transfer front right door glass to new door.	\$ 80.00 40 ←
8	To remove and install rear right undercarriage parts.	\$ 350.00 ?
9	To remove and install front right undercarriage parts.	\$ 350.00 ?
10	To conduct wheel alignment.	\$ 80.00 ✓
11	To balance front right wheel.	\$ 50.00 x
12	To balance rear right wheel.	\$ 50.00 x
13	To remove and install fuel tank to facilitate the repair.	\$ 180.00 x
14	To remove and install rear right inner trim to facilitate the repair.	\$ 150.00 60 ←
15	To remove and install rear right sliding door glass.	\$ 150.00 40
16	Towing service.	\$ 120.00 ✓ 120
Total labour :		\$ 6,920.00

Total parts : \$ 18,295.23

Total labour : \$ 6,920.00

Total repair cost : \$ 25,215.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj 96893735
 1/3 06/12/18

10 Days

Exam : To be Advised.

Not Authorised for repairs

* For Lump Sum repair, please provide after repair photo, shown the damaged Right Sliding door beside the vehicles.