

ASS. REC. BY:

REF:

CS/ FCL180219A / Agbn2

Special Instruction:

Surveyor:

Admin

ASSIGNMENT (Office)

From (Person):

CWS Joanne Yong

of

FCL

Date/Time:

06/12/2018 9:44am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 4536Z

Insured:

SHB 3237J

at Workshop m/s

Zero Gravity

Tel:

9694 7459

of

2 Kaki Bukit Ave 3 #01-25

Policy No:

Claim No:

D18008627MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 04/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

06/12/2018 10:01am

Person Contacted:

Stanley

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKV 4536Z - NA / FCL18021956/ZH

DFA: 04/12/18

SHB 3237J - CS/2W18009939 / KMS1

DFA: 190518

13/12/18 @ 10.34am Informed Joanne Yong, we are pending estimate from repairer.

09/1/19 @ 5.44pm revised to Joanne Yong by email

US \$ 2900, 5 days (Red \$ 6365.79, 69%)

REF:

ACCIDENT

From _____ Date _____
 Estimated Cost _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop mis

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No. SKV4536Z. Yr Regn. 2015 Sept.
 Type M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Sylphy. C/S 1598
 Colour: Bronze. A/C: Insured / Std / NI / NA

Sp. Reading 52372 T/Radio: Insured / Std / NI / NAEng/No: MNTBBA B172002.4358

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R16R: 195/60R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. D.O.I. 06/12/18.Survey held at Zero Gravity.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

TP 1st Cap.

RECEIVED 09 JAN 2019

Date/Time, File Pass to?

1) 09/11/18 typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.I. (\$)

TP
2900Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Inv (\$)☐ Weekend (\$)

Survey Fee.

Transportation

1. S. + P. \$

2. Photos

3. Others

TOTAL

170
50
50
31
301



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008627MFSH

Date: 09 January 2019

Our Ref: CS/FCI18021969/Aqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKV 4536Z .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/12/2018 at the premises of M/s ZERO GRAVITY, and have the following to report:-

Workshop Estimate Amount	: S\$ 9,265.29 .
Revised Estimate Amount	: S\$ 2,900.00 (Lump Sum) .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the o/s portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	05-12-2018	Our Ref No. D18008627MFSH
Accident Date	04-12-2018	Claim Type. Third Party
Insured Vehicle	SHB3237J	Third Party Vehicle. SKV4536Z
Survey Location	2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB	
Contact Person.	TIFFANY	
Contact No.	67412845/ 67477100	Fax No. 67412170
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ZERO GRAVITY	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 9 January 2019 5:44 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008627MFSH/1
Attachments: CSFCI18021969Aqb.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SKV 4536Z.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 13 December 2018 10:34 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008627MFSH/1

Dear Joanne,

Please be informed that we have inspected the vehicle SKV 4536Z on 06/12/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 6 December 2018 10:02 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008627MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 13 December 2018 10:34 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008627MFSH/1

Dear Joanne,

Please be informed that we have inspected the vehicle SKV 4536Z on 06/12/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 6 December 2018 10:02 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008627MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 6 December, 2018 9:44 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008627MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Buss.Reg.No. 5238887X

Attn: Adrian

QUOTATION

No : QT-000155

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Attention: Motor Claim Department

TEL : 65073843/68543466 FAX : 65073849

xiao chen

Your Ref. : SHB3237J
 Vehicle No. : SKV4536Z
 Make & Model : NISSAN SYLPHY
 Chassis No. : MNTBBAB17Z0024358
 Engine No. : HR16971868B
 Accident Date : 04/12/2018
 Policy No. : D-18091611MVPC
 Date : 06/12/2018
 Page : 1 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	DOOR (R/H/R) <i>Dented</i>	1.0 PCS	917.20	✓ 917.20
2	DOOR STICKER (FRAME) <i>new</i>	3.0 PCS	30.30	✓ 90.90
3	DOOR ANTI SPLASH PLASTIC SEAL <i>new</i>	1.0 PCS	33.70	X 33.70
4	DOOR INNER TRIM BOARD CLIP <i>new</i>	12.0 PCS	6.70	X 80.40
5	DOOR STOPPER RUBBER <i>new</i>	1.0 PCS	27.00	X 27.00
6	DOOR INNER LOCK (R/H/R) <i>Dented</i>	1.0 PCS	183.70	✓ 183.70
7	DOOR CATCH (R/H/R) <i>new</i>	1.0 PCS	55.00	X 55.00
8	DOOR FRAME BEADING <i>new</i>	1.0 PCS	214.30	X 214.30
9	DOOR WEATHER STRIP (R/H/R) <i>new</i>	1.0 PCS	117.40	✓ 117.40
10	DOOR HANDLE (OUTER)	1.0 PCS	269.90	X 269.90
11	DOOR HANDLE (INNER)	1.0 PCS	58.00	X 58.00
12	DOOR HINGE (R/H/R UPPER) <i>new</i>	1.0 PCS	62.10	X 62.10
13	DOOR HINGE (R/H/R LOWER)	1.0 PCS	62.10	X 62.10
14	STEP GARNISH (R/H/R)	1.0 PCS	75.00	X 75.00
15	WINDOW REGULATOR (R/H/R) <i>Dented</i>	1.0 PCS	115.80	✓ 115.80
16	WINDOW REGULATOR MOTOR (R/H/R) <i>new</i>	1.0 PCS	577.40	X 577.40
17	SWITCH (DOOR) <i>new</i>	1.0 PCS	49.80	X 49.80
18	BUMPER CLIP <i>new</i>	8.0 PCS	2.80	X 22.40
19	Discount 10 %			-301.71
20	SubTotal (N)			2,715.39
21	SPORT RIM (R/H/R) <i>lt</i>	1.0 PCS	480.00	✓ 480.00
22	TYRE (R/H/R) <i>new</i>	1.0 PCS	220.00	X 220.00
23	SHOCK ABSORBER (R/H/R) <i>new</i>	1.0 PCS	178.50	X 178.50
24	WHEEL BEARING (R/H/R) <i>new</i>	1.0 PCS	471.50	X 471.50
25	SIDE SKIRT (R/H) <i>Rep's</i>	1.0 PCS	630.80	X 630.80
26	MUD FLAG (R/H/R) <i>new</i>	1.0 PCS	58.80	X 58.80



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412345 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Buss.Reg.No.: 52338807X

QUOTATION

No : QT-000155

MS FIRST CAPITAL INSURANCE LIMITED

Your Ref. : SHB3237J
 Vehicle No. : SKV4536Z
 Make & Model : NISSAN SYLPHY
 Chassis No. : MNTBBAB17Z0024358
 Engine No. : HR16971868B
 Accident Date : 04/12/2018
 Policy No. : D-18091611MVPC
 Date : 06/12/2018
 Page : 2 of 3

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

Attention: Motor Claim Department

TEL : 65073848/68543466 FAX : 65073849

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
27	DOOR PROTECTOR (R/H/R) <i>new</i>	1.0	PCS 272.00	✓ 272.00
28	FENDER (R/H/R) <i>new</i>	1.0	PCS 694.80	X 694.80
29	BUMPER SIDE RETAINER (R/H/R) <i>new</i>	1.0	PCS 19.60	X 19.60
30	REAR BUMPER <i>new</i>	1.0	PCS 343.90	X 343.90
31	WINDSCREEN INNER SEAL (REAR) <i>new</i>	1.0	PCS 95.00	X 95.00
32	SEALANT (WINDSCREEN) <i>new</i>	1.0	PCS 35.00	X 35.00
33	SubTotal (S)			3,549.90
34	PANEL BEATING & REPLACING OF THE ABOVE	1.0	X	600 1,200.00
35	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0	X	750 1,000.00
36	TO PROVIDE UNDER TURFCODE	1.0	X	X 150.00
37	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0	X	80 180.00
38	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0	X	50 80.00
39	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1.0	X	X 150.00
40	TO REMOVE, TRANSFER & INSTALL RELATED COMPONENT	1.0	X	50 120.00
41	TO COMPUTERISE ADJUST WHEEL ALIGNMENT	1.0	X	80 120.00
42	SubTotal (LABOUR)			3,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

total 361730

c/s 2.9k

05/12/18

2.9k



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Buss.Reg.No.: 52888887X

QUOTATION

No : QT-000155

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

Attention: Motor Claim Department

TEL : 65073848/68543466 FAX : 65073849

Your Ref. : SHB3237J
Vehicle No. : SKV4536Z
Make & Model : NISSAN SYLPHY
Chasis No. : MNTBBA317Z0024358
Engine No. : HR16971868B
Accident Date : 04/12/2018
Policy No. : D-18091611MVPC
Date : 06/12/2018
Page : 3 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$


SINGAPORE DOLLAR NINE THOUSAND TWO HUNDRED SIXTY FIVE AND CENTS TWENTY NINE ONLY

E. & O.E

Total	S\$	9,265.29
Discount	S\$	0.00
Net Total	S\$	9,265.29

Terms: C.O.D.

Customer's Signature/Co. Stamp


ZERO GRAVITY

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18021969/Aqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3237J	Veh. Inspected	SKV 4536Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008627MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	06/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MNTBBAB17Z0024358	Colour	BRONZE	
Odometer	52372	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	195/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	195/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	195/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/12/2018	Inspection Date	06/12/2018	
Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 4536Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	DOOR (R/H/R)	DENTED	917.20	917.20
3	DOOR STICKER (FRAME) @\$30.30	NECESSARY	90.90	90.90
1	DOOR ANTI SPLASH PLASTIC SEAL	NOT NECESSARY	38.70	-
12	DOOR INNER TRIM BOARD CLIP @\$6.70	NOT NECESSARY	80.40	-
1	DOOR STOPPER RUBBER	NOT NECESSARY	27.00	-
1	DOOR INNER LOCK (R/H/R)	DAMAGED	183.70	183.70
1	DOOR CATCH (R/H/R)	NOT NECESSARY	55.00	-
1	DOOR FRAME BEADING	NOT NECESSARY	214.30	-
1	DOOR WEATHER STRIP (R/H/R)	NECESSARY	117.40	117.40
1	DOOR HANDLE (OUTER)	NOT NECESSARY	269.90	-
1	DOOR HANDLE (INNER)	NOT NECESSARY	58.00	-
1	DOOR HINGE (R/H/R UPPER)	NOT NECESSARY	62.10	-
1	DOOR HINGE (R/H/R LOWER)	NOT NECESSARY	62.10	-
1	STEP GARNISH (R/H/R)	NOT NECESSARY	75.00	-
1	WINDOW REGULATOR (R/H/R)	DAMAGED	115.80	115.80
1	WINDOW REGULATOR MOTOR (R/H/R)	NOT NECESSARY	577.40	-
1	SWITCH (DOOR)	NOT NECESSARY	49.80	-
8	BUMPER CLIP @\$2.80	NOT NECESSARY	22.40	-
	LESS 10% DISCOUNT		-301.71	-142.50
			2,715.39	1,282.50
1	DOOR PROTECTOR (R/H/R)	NECESSARY	272.00	272.00
	LESS 10% DISCOUNT		-	-27.20
			272.00	244.80
<u>SPECIAL NETT ITEMS</u>				
1	SPORT RIM (R/H/R)(SN)	CUT	480.00	480.00
1	TYRE RIM (R/H/R)(SN)	NOT NECESSARY	220.00	-
1	SHOCK ABSORBER (R/H/R)(SN)	NOT NECESSARY	178.50	-
1	WHEEL BEARING (R/H/R)(SN)	NOT NECESSARY	471.50	-

Report Ref No. CS/FCI18021969/Aqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SIDE SKIRT (R/H)(SN)	TO REPAIR SEE LABOUR	680.80	-
1	MUD FLAG (R/H/R)(SN)	NOT NECESSARY	58.80	-
1	FENDER (R/H/R)(SN)	TO REPAIR SEE LABOUR	694.80	-
1	BUMPER SIDE RETAINER (R/H/R)(SN)	NOT NECESSARY	19.60	-
1	REAR BUMPER (SN)	TO REPAIR SEE LABOUR	343.90	-
1	WINDSCREEN INNER SEAL (REAR)(SN)	NOT NECESSARY	95.00	-
1	SEALANT (WINDSCREEN)(SN)	NOT NECESSARY	35.00	-
			3,277.90	480.00
	LABOUR			
	PANEL BEATING & REPLACING OF THE ABOVE.INCLUSIVE OF THE REPAIR OF SIDE SKIRT (R/H),FENDER (R/H/R) AND REAR BUMPER.		1,200.00	600.00
	TO PUTTY AND RE-SPRAY AFFECTED PORTION.		1,000.00	750.00
	TO PROVIDE UNDER TURFCODE.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT COMPONENTS/FACILITATE THE REPAIR.		180.00	80.00
	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT.		80.00	50.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	150.00	-
	TO REMOVE,TRANSFER & INSTALL RELATED COMPONENT.		120.00	50.00
	TO COMPUTERISE ADJUST WHEEL ALIGNMENT.		120.00	80.00
			3,000.00	1,610.00
GRAND TOTAL			9,265.29	3,617.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS/FCI18021969/Aqbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.