



Section A - Accident Details

Registration Number	SHB1621X
Case Reference Number	TAX/12/18/2016
Registration Date	15/11/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SOH CHEE HOE (SU ZHIHAO)
Type of Accident	Side Swipe
Accident Date and Time	4/12/2018 2:01 AM
Accident Reported Date and Time	4/12/2018 12:22 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	4/12/2018 2:16 AM
Replacement Vehicle issued?	No
Job Card Number	24099095
Special Instruction to ARC, if any	TOWED \$40
Prepared Date and Time	5/12/2018 7:18 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Signature

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$500.00
Total Spray Cost	\$1,476.00	\$600.00
Total Spare Part Cost	\$6,383.89	\$3,106.18
Total Other Cost	\$636.00	\$136.00
TOTAL COST	\$9,340.89	\$4,342.18
Lump Sum Total	\$8,950.00	\$4,350.00 (L/S)
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Kim Ming Chin	Taufikh (LKK) / China Taiping
ARC / Surveyor Sign Off Date	05/12/2018 10:10 AM	05/12/2018 5:07 PM
Signature		L K K
Remarks	SUP = 1 DAYS	Resurvey After Repair (Lumpsum Repair) HP 9749 5749/ EMAIL: sur@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1906-0311	Invoice Number	
Quotation Date	19.06.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$845.00	\$500.00 ✓
Total Labour	\$845.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$100.00 ✓
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$100.00 ✓
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,476.00	\$600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$56.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
Total Other Costs	\$636.00	\$136.00

1236

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50 ✓	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08 ✓	Replace	Replace ✓
		52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30 ✓	Replace	Replace ✓
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.80	25.00	\$59.10 ✓	Replace	Replace ✓
		52021-47023	BUMPER REINFORCEMENT FRT	1.00	\$498.40	25.00	\$373.80 ✓	Replace	Replace ✓
		57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Check X
		53294-47030	DEFLECTOR RADIATOR LH	0.00	\$77.00	0.00	\$0.00	Replace	Check X
		52114-47014	BRACKET,FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Check X
			NUMPER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Check X

de
rec
rec
cha
bt
un

		NUMPER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	bt
	52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$18.50	25.00	\$13.88	Replace	Replace	at
	81220-12230	FOG LAMP LH	1.00	\$280.10	10.00	\$252.09	Replace	Replace	dig
	53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace	at
	82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Check	un
	81521-47050	LENS & BODY, FR TURN LH	1.00	\$511.80	10.00	\$460.62	Replace	Replace	dig
	81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check	X
	81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check	X
	81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check	X
	76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Check	X un
	52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check	X
	53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check	X
	53201-47902	SUPPORT SUB-ASSY	1.00	\$1,460.40	100.00	\$0.00	Replace	Repair	R
	81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	crea
	53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	bt
	75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	rec
	53876-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	tn
	53852-47020	FENDER LINER PAD, FR WHEEL, LH	0.00	\$49.30	0.00	\$0.00	Replace	Check	X un
	53702-47050	FENDER APRON SUB FRT/LH	1.00	\$637.80	100.00	\$0.00	Replace	Repair	R
	42611-47140(Frt)	WHEEL DISC. FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X 3un
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X 3un
Total				\$9,302.65		\$3,399.64			3404re

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	1.00	\$250.40	25.00	\$187.80	Replace	Replace
			NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace
		52114-47140	BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace
		76851-47020	BUMPER LIP FRT	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		52618-47050	BUMPER FRT ABSORBER LOWER	1.00	\$127.70	25.00	\$95.78	Replace	Replace
Total					640.10		483.08		

3882.72 ✓

-20%

3106.18 ✓

+ 500.00

+ 736.00

4342.18 ✓

US \$4350/- #

12914.24 #