

1950110

INS. CASE OWNER:

KC

CC 4 AXA 1802

1992h, 72pb352

LKK: IDAC:

ASSIGNMENT

Surveyor:

Performance

DOI:

6/12/18

Date / Time:

6/12/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SME 2289K

Name of Insured:

HEKYE LIM PBT NOI

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

01/12/18

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Van 714 honey

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SBM05AY / 86214

Policy No.:

01041251

Make / Model:

HONDA

Place of Accident:

Pungkol OK zone Pungkol EAST TRAFFIC LIGHT

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS: WSP: Tel: Liability: RMKS:

Performance



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/ Time

SMD 70321 - X

SME 2289K - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

21h 09/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

11/12/18
mt

gmmelam

6/12/18

AXA VDS.

8/12/18

TO TP. DS.

5/9/19

KCE -> Shupitube

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : 11(b).

If NO or B 28, Ass. Lia :

Repair Cost:

SS

19666.08

Loss of Rental (LOR):

SS

1100.00

(11 days)

X #1w

Loss of Use (LOU):

SS

-

(5 x days)

Loss of Income (LOI):

SS

-

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

Gl./LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

20768.08

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

20768.08

Name 1:

Performance Motors Ltd,

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: No. / Reject/Private Settle

2) Report Format:

3) Survey fee:

6/9/19
CYP
#250-00

6/9/19



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18021993/T1pb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 06-12-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SME 2389K	Veh. Inspected	SMD 7073T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/12/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/12/2018	Inspection Date	06/12/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Car In

GST REG. NO : M2 - 0020081 - X

ESTIMATE

06 DEC 2018

Estimate No.	: b1 49334	Page No. :	1 of 5
Date Estimated	: 03/12/2018		
Prepared By	: Kevin Leong Wai Kit		

- ESTIMATE REPAIR FOR - Soh Hsiu Hsien 306A Punggol Place #15-37 Singapore 821306	- ACCOUNT - 238 AXA Insurance Pte Ltd 8 Shenton Way #24-01 AXA Tower Singapore 068811
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD7073T	A548696	31/08/2018	318i	0

DESCRIPTION	VALUE
To replace rear bumper, rear RH side panel, rear RH door, RH side sill cover & all attachments cause by accident. To repair on rear RH entrance door panel.	3737.50 / 6375 8,500.00
Painting on rear bumper, rear RH side panel, rear RH door, RH side sill cover, RH trunk floor & rear RH door entrance panel	3253.90 ✓ 4,171.00
To remove and install fuel tank to facilitate repairs including extract fuel and conduct leak tests.	445.90 photo. 451? 531.00
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	667.80 829.742 873.00
To check steering geometry and conduct wheel alignment according to BMW specification (1x)	405.90 451 531.00
To replace tyre and wheel rim including balancing. (4x).	72.00 80; 94.00
To conduct water leak tests.	67.50 6375 75.00
To supply and install rear windscreen solar film.	XX 531.00
To check electrical wiring systems at the rear section for proper function.	135 (150) 177.00
To carry out body cavity preservation. (Per panel) rear RH door	90 (100) 118.00
To carry out body cavity preservation. (For cut panel) rear RH side panel	405.90 451 531.00
Sundries.	150.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total Labour 1: 16,282.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : **b1 49334** Page No. : 2 of 5
Date Estimated : **03/12/2018**
Prepared By : **Kevin Leong Wai Kit**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD7073T	A548696	31/08/2018	318i	0

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM 8.5X18 M DOUBLE SPK 441	1	1,287.10	1,287.10
HUB CAP WITH CHROME EDGE (BMW)	1	28.35	28.35
RR RH FENDER	1	1,562.75	1,562.75
REAR RH DOOR	1	1,267.50	1,267.50
RH C-PILLAR REINFORCEMENT PLATE	1	50.45	50.45
RH SILL REINFORCEMENT PLATE	1	50.45	50.45
RH LOWER REAR DOOR HINGE	1	58.60	58.60
RH UPPER REAR DOOR HINGE	1	58.60	58.60
REAR BUMPER PANEL PRIMED (M)	1	1,268.75	1,268.75
REAR WINDOW	1	733.15	733.15
RR RH DOOR OUTER DUCT COVER (GLANZS)	1	126.50	126.50
RR RH DOOR COVER COLUMN B (GLAN)	1	65.70	65.70
RH EXTERIOR COVER WINDOW GUIDE WEB	1	61.75	61.75
REAR RH DOOR WINDOW GUIDE	1	124.40	124.40
SUPPORTING LEDGE RH	1	36.25	36.25
SUPPORTING LEDGE RH	1	37.75	37.75
SUPPORTING LEDGE RH	1	37.55	37.55
RH PRIMED SILL COVER (M)	1	386.95	386.95
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
BLIND RIVET HEML OCK 813	1	2.65	2.65
BLIND RIVET AVIBVLB	12	0.55	6.60
SCREW (SF PLUS M5X15)	3	0.55	1.65
(DG/SL) BODY ADHESIVE K5B (195ML)	1	326.80	326.80
(DG) BODYWORK ADHESIVE K5A (50ML)	1	112.70	112.70
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
PUNCH RIVET N4	39	0.55	21.45
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
(S/L) SEAM SEAL 300ML	1	33.80	33.80
Total Parts :			8,111.65

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date&Time 6/2/18 1145 Excess S\$ 24397.72

Surveyor's Name Tan Jiah Sign Tan Jiah
Surveyor's Tel 97495741 Authorised Yes / No _____
Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail tanjiah@khant.com
No. of Working Days Recommend 12-13 days

Labour 1	:	16,282.00
Parts	:	8,111.65
Labour 2	:	24393.65 0.00
Excess	:	0.00
Total GST @ 7%	:	1,707.56
Grand Total	:	26,101.21

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****
**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****

25410.

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 49334 Page No. :
Date Estimated : 03/12/2018
Prepared By : Kevin Leong Wai Kit

REPAIR FOR -
Soh Hsiu Hsien
306A Punggol Place
#15-37

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Singapore 821306

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SMD7073T	A548696	31/08/2018	318i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To replace rear windscreen glass	574.00	10.00	516.60 <i>nee</i>

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	2.00	5.00	3.00	9.70
# SNAP LOCK COUPLING *	3.65	1.00	3.00	3.54
# BLIND RIVET NUT *	3.85	1.00	3.00	3.73
# BUMP STOP *	3.35	10.00	3.00	32.49
# REAR DOOR WEATHERSTRIP *	140.70	1.00	3.00	136.48

Total Labour : 516.60
Total Parts : 185.94
Total Labour & Parts : 702.54

3M S/F Premium Rear Windshield # 252.34 *nee* ✓

25096.69

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 49334
Date Estimated : 03/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Soh Hsiu Hsien
306A Punggol Place
#15-37

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Singapore 821306

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE		
SMD7073T	A548696	31/08/2018	318i	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace rear RH door and attachments, rear RH fender include making good the rear bumper, RH side skirting, RH trunk floor, RH entrance panel and knocking out dents caused by the accident	6375.00	10.00	5,737.50			
To spray paint rear bumper, rear RH fender, rear RH door, RH side skirting, RH trunk floor and RH entrance panel	4171.00	10.00	3,753.90			
* To remove and install fuel tank to facilitate repairs include extracting fuel and conducting leak tests	451.00	10.00	405.90			
* To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	742.00	10.00	667.80			
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00	10.00	405.90			
To replace wheel rim include balancing (1x)	80.00	10.00	72.00			
* To conduct water leak tests	75.00	10.00	67.50			
# To replace rear windscreen glass	574.00	10.00	516.60			
To check electrical wiring systems at the rear section for proper function	150.00	10.00	135.00			
To carry out body cavity preservation for rear RH door (Per panel)	100.00	10.00	90.00			
To carry out body cavity preservation for rear RH fender (For cut panel)	451.00	10.00	405.90			
Sundries	150.00	0.00	150.00			
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT		
# EXPANDING NUT *	2.00	5.00	3.00	9.70		
# SNAP LOCK COUPLING *	3.65	1.00	3.00	3.54		

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

ALLOY RIM 8.5X18 M DOUBLE SPK 441	1,287.10	1.00	3.00	1,248.49
3M S/F PEWMIUM REAR WINDSHIELD	252.34	1.00	0.00	252.34
RR RH FENDER	1,562.75	1.00	3.00	1,515.87
REAR RH DOOR	1,267.49	1.00	3.00	1,229.47
# BLIND RIVET NUT *	3.85	1.00	3.00	3.73
REAR WINDOW	733.15	1.00	3.00	711.16
# BUMP STOP *	3.35	10.00	3.00	32.49
# REAR DOOR WEATHERSTRIP *	140.70	1.00	3.00	136.48
BLIND RIVET HEMLOCK 813	2.65	1.00	3.00	2.57
BLIND RIVET AVIBVLB	0.55	20.00	3.00	10.67
SCREW (SF PLUS M5X15)	0.55	3.00	3.00	1.60
(DG/SL) BODY ADHESIVE K5B (195ML)	326.80	1.00	3.00	317.00
PUNCH RIVET N4	0.55	40.00	3.00	21.34
(DG) BODYWORK ADHESIVE K5A (50ML)	112.70	1.00	3.00	109.32
(DG) CLEANER R1 (100ML)	26.15	2.00	3.00	50.73
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	3.00	255.21
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00	3.00	27.01
(S/L) SEAM SEAL 300ML	33.80	1.00	3.00	32.79

SUPPLEMENTARY ITEMS

Total Labour :	12,408.00
Total Parts :	5,971.51
Total Labour & Parts :	18,379.51
Deduction for Excess :	0.00
Total Repair Costs less Excess:	18,379.51
GST @7%:	1,286.57
Grand Total :	19,666.08

◀ Service Request Details

Claim
S8M015AX

Reference
None ✎

Loss Date
December 3, 2018

Request Date
December 6, 2018

Due Date
December 13, 2018

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

*06/22/18 @ 10320am
Caroline veh in
Tawfik*

Actions

Next Step
Agree to perform service

Vehicle Information

Incident Vehicle Registration #
SMD7073T

Make
TPVD BMW

Model

318I-1:5 (A)

Service Address

...

Primary Contact/Insured

CHERYL LIM PEI NOI (LIN PEINA)
BLK 668B #11-700, EDGEFIELD PLAINS, 822668, Singapore
97360865
JIAHONG4@HOTMAIL.COM

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Catherine Chong (LKK Auto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Thursday, 6 December, 2018 9:05 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SMD7073T & SME2389K ON 03/12/2018
Attachments: SKM_558e18120609000.pdf; IMG_7663.JPG; IMG_7664.JPG; IMG_7670.JPG; IMG_7676.JPG
Categories: Pragati

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

“This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's.”

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 8 December 2018 10:07 AM
To: 'PBSP'
Cc: Admin A; CS A Team
Subject: RE: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SMD7073T & SME2389K ON 03/12/2018 *LKK REF: CC4/ASM18021993/T1pb3

Without Prejudice

Dear Sirs/ Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, 7 December 2018 5:57 PM
To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Fw: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SMD7073T & SME2389K ON 03/12/2018

Dear LKK

Please advise if your insured had reported the accident?

Kindly reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Friday, 7 December 2018 2:55 PM
To: motor.survey@axa.com.sg
Subject: Re: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SMD7073T & SME2389K ON 03/12/2018

Dear Sirs,

Kindly reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Thursday, 6 December 2018 9:05:18 AM
To: motor.survey@axa.com.sg

Subject: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SMD7073T & SME2389K ON 03/12/2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

Hsiao Tong (LKKAuto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Monday, 28 January 2019 3:48 PM
To: Taufikh (LKKAuto); Hsiao Tong (LKKAuto)
Subject: FINAL REPORT / SMD7073T
Attachments: Final Report SMD7073T_2.pdf; Final Report SMD7073T.pdf

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 12,408.00
Total Parts : 5,971.51
Total Labour & Parts : 18,379.51

Repair days: 17

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."



redefining / insurance

CLAIM REF :
INSURED :

DISCHARGE VOUCHER

We/I [Soh Hsiu Hsien , NRIC NO. S9142189E] hereby agree to accept the sum of dollars [_____] (\$\$ _____) paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. [SME2389K] as a result of an accident along [Punggol Drive] on [3/12/18] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [SMD7073T].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [SME2389K] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SME2389K].

Dated this 24 day of December 2017

Claimant's Signature : _____ &

NRIC no./ Company Stamp : _____

Occupation/ Business : _____

Address : _____

Telephone No. : _____

Witness's Name : _____

Witness's Signature : _____

Witness's NRIC No. : _____

KEVIN LEONG WAI KIT
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

 <MANDATE IA> - S8M015AX [ACCIDENT INVOLVING SME 2389K(OI) & SMD 7073T(TP) ON 03/12/2018]

Type

 Question

Message

Liability: 100%. Insured driver made U-turn and collided with third party who was driving straight. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$21,128.08(all-in). Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 25 March 2019



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 25/03/2019

Survey Details:

Date of loss	3-Dec-18
Date of appointment	6-Dec-18
Date of survey	6-Dec-18
Location of survey	PERFORMANCE MOTORS LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SMD 7073T
Make and Model	BMW 318i 1.5 A
Date of registration	31/8/2018
Excess	
Market Value	\$148,000
Parf Rebate	\$64,796
Nett Loss	\$83,204

Repair details:

Initial Estimate	\$ 24,393.65
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 5,533.23
Check items (estimate)	NIL
Labour	\$ 11,891.40
Supplementary	\$ 954.88
Total	\$ 18,379.51
Lump Sum(if applicable)	\$ -

Number of days for repair	15
---------------------------	----



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%	
Proposed repair cost (w/GST)	\$	19,666.08	
Loss of use	\$	360.00	(6days X 60.00)
Loss of rental	\$	1,100.00	(11days x \$100.00)
Loss of income		NIL	no. of days
LTA search fees	\$	2.00	
Others		NIL	
Proposed Total	\$	21,128.08	



Re:<MANDATE IA> - S8M015AX [ACCIDENT INVOLVING SME 2389K(OI) & SMD 7073T(TP) ON 03/12/2018]

Type

🗉 Question

Message

WE WILL SEEK 2ND ADVICE ON COR

Reply

Hsiao Tong (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Tuesday, 16 April 2019 7:05 PM
To: Hsiao Tong (LKKAuto)
Subject: RE: New message for service request 86234, vehicle number SMD7073T

<input type="checkbox"/>	Message Liability: 100%. Insured driver made U-turn and collided with third party who was driving straight. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$21,128.08(all-in). Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong – 25 March 2019	CHT	25/3/2019 7:53:36 AM
<input type="checkbox"/>	25/3/19 9:14 AM CHAN Kian Chuan ---WE WILL SEEK 2ND ADVICE ON COR	LSP	25/3/2019 9:18:46 AM
<input type="checkbox"/>	16/4/19 3:47 PM CHAN Kian Chuan -----PLS PROCEED DS AS FOLLOWS: COR \$19,666.08 LOR \$1,100.00 LTA \$2.00 TOTAL \$20,768.08	LSP	16/4/2019 6:51:52 PM

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)
Sent: Tuesday, 16 April 2019 3:56 PM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 86234, vehicle number SMD7073T

Best Regards,

G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: kianchuan.chan@axa.com.sg [mailto:kianchuan.chan@axa.com.sg]
Sent: Tuesday, 16 April 2019 3:49 PM
To: admin-d@lkkauto.com
Subject: New message for service request 86234, vehicle number SMD7073T

AXA Insurance has sent you a message for claim number S8M015AX.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been checked for viruses by AVG.
<https://www.avg.com>

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 27 April 2019 1:28 PM
To: PBSP
Cc: Admin A
Subject: RE: LOD REMINDER - SMD7073T & SME2389K ON 03/12/2018 *LKK REF: CC4/ASM18021993/T1pb3

**Without Prejudice
(save as to costs)**

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)	\$19,666.08
2. Loss of Rental(11 days x \$100.00)	\$ 1,100.00
3. LTA/ GIA Search Fee	\$ 2.00
Total	<u>\$20,768.08</u>

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Thursday, 18 April 2019 5:54 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: LOD REMINDER - SMD7073T & SME2389K ON 03/12/2018

LOD REMINDER

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Hsiao Tong (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 30 April 2019 4:18 PM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A
Subject: Re: LOD REMINDER - SMD7073T & SME2389K ON 03/12/2018 *LKK REF: CC4/ASM18021993/T1pb3

3/12/18 - DUA
(Mon).

6/12/18 (Thu): DO1
11/12/18 - start rental.

Dear Hsiao Tong

The least our customer will agree is total of 16 days.

LOR for 11 days (11 DEC - 21 DEC) + LOU (8 DEC, 9 DEC, 10 DEC, 22 DEC AND 23 DEC)

Please proceed with a settlement if our client's request is accepted - rental \$1100 + lou \$400.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Saturday, 27 April 2019 1:27:44 PM
To: PBSP
Cc: 甯珺 @
Subject: RE: LOD REMINDER - SMD7073T & SME2389K ON 03/12/2018 *LKK REF: CC4/ASM18021993/T1pb3

**Without Prejudice
(save as to costs)**

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)	\$19,666.08
2. Loss of Rental(11 days x \$100.00)	\$ 1,100.00
3. LTA/ GIA Search Fee	\$ 2.00
Total	\$20,768.08

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,
Hsiao Tong, Chew | Case Handler

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 5 September 2019 8:54 AM
To: PBSP
Cc: Admin A
Subject: RE: OFFER - SMD7073T & SME2389K ON 03/12/2018 *LKK REF: CC4/ASM18021993/T1pb3

Without Prejudice

Dear Sirs/Mdm,

Thank you for your email.

We confirm settlement as follows: -

1. Cost of Repair (w/GST)	\$19,666.08
2. Loss of Rental(11days x \$100.00)	\$ 1,100.00
3. LTA/ GIA Search Fee	\$ 2.00
Total	\$20,768.08

We will proceed to close file.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 3 September 2019 10:03 AM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: Re: OFFER - SMD7073T & SME2389K ON 03/12/2018 *LKK REF: CC4/ASM18021993/T1pb3

Dear Hsiao Tong

Please proceed with the Loss of rental \$1100.00

Thank you.

Regards,
Caroline

From: PBSP

Sent: Monday, 10 June 2019 11:52 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Kevin Leong Wai Kit <kevin.leong.waikit@simedarby.com.sg>

Cc: 甯珺 © <admin-a@lkkauto.com>

Subject: OFFER - SMD7073T & SME2389K ON 03/12/2018 *LKK REF: CC4/ASM18021993/T1pb3

Dear Kevin

Please advise Hsiao Tong justification on your customer's loss of use claim as per your request in the insurance checklist.

LOR for 11 days (11 DEC - 21 DEC) +

LOU (8 DEC, 9 DEC, 10 DEC, 22 DEC AND 23 DEC)

At the moment, the insurance is only willing for rental \$1100. Please provide a reason for the additional loss of use claim before and after rental.

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SME 2389K (Insd veh)	Model:	B.M.W. 318I
	SMD 7073T (TP veh)		
Date of Accident:	03/12/2018		

Global Sum Settlement	: [] Yes	[X] No	
Repair Estimate	: \$	27,188.70	
Final Repair Cost	: \$	19,666.08	
Loss of Use	: \$	1,100.00	11 days at \$0.00 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$	2.00	

Others: : \$

Final Settlement Sum : \$ 20,768.08

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ___11___

BOLA Liability: ___100___(%) Assessed Liability (*): _____(%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	PERFORMANCE MOTORS LTD	: \$ 20,768.08

NUR SHAQILAH BTE ABDOL
WAHAB

11/09/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18021993/T1pb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KIAN CHUAN		Date : 11-09-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SME 2389K	Veh. Inspected	SMD 7073T
Policy No.	GA401295/1	Coverage (\$)	0.00
Claim No.	S8M015AX	Excess (\$)	0.00
Assign From	KIAN CHUAN	Assign Date	06/12/2018
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 318i	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBA8E32030A548696	Colour	BLACK
Odometer	05651	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/40 R18	BRIDGESTONE	6 mm
L/H Front Tyre	255/40 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	255/40 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	255/40 R18	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/12/2018	Inspection Date	06/12/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 7073T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	ALLOY RIM 8.5X18 M DOUBLE SPK 441 (SN) (CONSISTENT)	CUT	1,287.10	1,248.49
1	HUB CAP WITH CHROME EDGE (BMW) (SN) (CONSISTENT)	NOT NECESSARY	28.35	-
1	RR RH FENDER (SN) (CONSISTENT)	BENT	1,562.75	1,515.87
1	REAR RH DOOR (SN) (CONSISTENT)	BENT	1,267.50	1,229.47
1	RH C-PILLAR REINFORCEMENT PLATE (SN) (CONSISTENT)	NOT NECESSARY	50.45	-
1	RH SILL REINFORCEMENT PLATE (SN) (CONSISTENT)	NOT NECESSARY	50.45	-
1	RH LOWER REAR DOOR HINGE (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	58.60	-
1	RH UPPER REAR DOOR HINGE (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	58.60	-
1	REAR BUMPER PANEL PRIMED (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	1,268.75	-
1	REAR WINDOW (SN) (CONSISTENT)	NECESSARY	733.15	711.16
1	RR RH DOOR OUTER DUCT COVER (GLANZS) (SN) (CONSISTENT)	NOT NECESSARY	126.50	-
1	RR RH DOOR COVER COLUMN B (GLAN) (SN) (CONSISTENT)	NOT NECESSARY	65.70	-
1	RH EXTERIOR COVER WINDOW GUIDE WEB (SN) (CONSISTENT)	NOT NECESSARY	61.75	-
1	REAR RH DOOR WINDOW GUIDE (SN) (CONSISTENT)	NOT NECESSARY	124.40	-
1	SUPPORTING LEDGE RH (SN) (CONSISTENT)	NOT NECESSARY	36.25	-
1	SUPPORTING LEDGE RH (SN) (CONSISTENT)	NOT NECESSARY	37.75	-
1	SUPPORTING LEDGE RH (SN) (CONSISTENT)	NOT NECESSARY	37.55	-
1	RH PRIMED SILL COVER (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	386.95	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN) (CONSISTENT)	NOT NECESSARY	20.20	-
1	BLIND RIVET HEML OCK 813 (SN) (CONSISTENT)	NECESSARY	2.65	2.57
20	BLIND RIVET AVIBVLB (SN) (CONSISTENT)	NECESSARY	10.67	10.67
3	SCREW (SF PLUS M5X15) (SN) (CONSISTENT)	NECESSARY	1.65	1.60
1	(DG/SL) BODY ADHESIVE K5B (195ML) (SN) (CONSISTENT)	NECESSARY	326.80	317.00

Report Ref No. CC4/ASM18021993/T1pb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	(DG) BODYWORK ADHESIVE K5A (50ML) (SN) (CONSISTENT)	NECESSARY	112.70	109.32
1	(DG) CLEANER R1 (100ML) (SN) (CONSISTENT) }	NECESSARY	26.15	50.73
1	(DG) CLEANER R1 (100ML) (SN) (CONSISTENT) }	NECESSARY	26.15	-
2	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) (SN) (CONSISTENT) }	NECESSARY	263.10	255.21
40	PUNCH RIVET N4 (SN) (CONSISTENT) }	NECESSARY	21.45	21.34
1	(DG/SL) GLASS PRIMER 30ML (VP206) (SN) (CONSISTENT) }	NECESSARY	27.85	27.01
1	(S/L) SEAM SEAL 300ML (SN) (CONSISTENT) }	NECESSARY	33.80	32.79
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	150.00	150.00
5	EXPANDING NUT (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	9.70	9.70
1	SNAP LOCK COUPLING (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	3.54	3.54
1	BLIND RIVET NUT (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	3.73	3.73
10	BUMP STOP (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	32.49	32.49
1	REAR DOOR WEATHERSTRIP (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	136.48	136.48
1	3M S/F PREMIUM REAR WINDSHIELD (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	252.34	252.34
			8,704.00	6,121.51
	LABOUR			
	TO REPLACE REAR BUMPER, REAR RH SIDE PANEL, REAR RH DOOR, RH SIDE SILL COVER & ALL ATTACHMENTS CAUSE BY ACCIDENT. TO REPAIR ON REAR RH ENTRANCE DOOR PANEL. INCLUSIVE OF THE REPAIR OF RH LOWER REAR DOOR HINGE, RH UPPER REAR DOOR HINGE, REAR BUMPER PANEL PRIMED AND RH PRIMED SILL COVER.		8,500.00	5,737.50
	PAINTING ON REAR BUMPER, REAR RH SIDE PANEL, REAR RH DOOR, RH SIDE SILL COVER, RH TRUNK FLOOR & REAR RH DOOR ENTRANCE PANEL.		4,171.00	3,753.90
	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS INCLUDING EXTRACT FUEL AND CONDUCT LEAK TESTS.		531.00	405.90
	TO REMOVE AND INSTALL REAR HAT-TRAY, REAR SEAT, CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS.		873.00	667.80



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION.	NOT NECESSARY	531.00	405.90
	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING.		94.00	72.00
	TO CONDUCT WATER LEAK TESTS.		75.00	67.50
	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM.		531.00	-
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	135.00
	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL) REAR RH DOOR.		118.00	90.00
	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL) REAR RH SIDE PANEL.		531.00	405.90
	TO REPLACE REAR WINDSCREEN GLASS. (ADDITIONAL)		574.00	516.60
			16,706.00	12,258.00
	GRAND TOTAL		25,410.00	18,379.51
RECOMMENDED COST OF REPAIRS				18,379.51

Report Ref No. CC4/ASM18021993/T1pb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.