

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

Car In

GST REG. NO : M2 - 0020081 - X

06 DEC 2018

ESTIMATE

Estimate No. : b1 49334	Page No. : 1 of 5
Date Estimated : 03/12/2018	
Prepared By : Kevin Leong Wai Kit	

<p>- ESTIMATE REPAIR FOR - Soh Hsiu Hsien 306A Punggol Place #15-37 Singapore 821306</p>	<p>- ACCOUNT - 238 AXA Insurance Pte Ltd 8 Shenton Way #24-01 AXA Tower Singapore 068811</p>
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD7073T	A548696	31/08/2018	318i	0

DESCRIPTION	VALUE
To replace rear bumper, rear RH side panel, rear RH door, RH side sill cover & all attachments cause by accident. To repair on rear RH entrance door panel.	6375 8,500.00
Painting on rear bumper, rear RH side panel, rear RH door, RH side sill cover, RH trunk floor & rear RH door entrance panel	✓ 4,171.00
To remove and install fuel tank to facilitate repairs including extract fuel and conduct leak tests.	photo. 451? 531.00
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	829 873.00
To check steering geometry and conduct wheel alignment according to BMW specification (1x)	451 531.00
To replace tyre and wheel rim including balancing. (1x).	80 94.00
To conduct water leak tests.	63 75.00
To supply and install rear windscreen solar film.	✓ 531.00
To check electrical wiring systems at the rear section for proper function.	150 177.00
To carry out body cavity preservation. (Per panel) rear RH door	100 118.00
To carry out body cavity preservation. (For cut panel) rear RH side panel	451 531.00
Sundries.	? 150.00
Total Labour 1: 16,282.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49334	Page No. : 2 of 5
Date Estimated : 03/12/2018	
Prepared By : Kevin Leong Wai Kit	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD7073T	A548696	31/08/2018	318i	0

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM 8.5X18 M DOUBLE SPK 441	1	1,287.10	cut 1,287.10
HUB CAP WITH CHROME EDGE (BMW)	1	28.35	it 28.35
RR RH FENDER	1	1,562.75	bt 1,562.75
REAR RH DOOR	1	1,267.50	bb 1,267.50
RH C-PILLAR REINFORCEMENT PLATE	1	50.45	? 50.45
RH SILL REINFORCEMENT PLATE	1	50.45	? 50.45
RH LOWER REAR DOOR HINGE	1	58.60	Ry 58.60
RH UPPER REAR DOOR HINGE	1	58.60	Ry 58.60
REAR BUMPER PANEL PRIMED (M)	1	1,268.75	Rx 1,268.75
REAR WINDOW	1	733.15	ne 733.15
RR RH DOOR OUTER DUCT COVER (GLANZS)	1	126.50	? 126.50
RR RH DOOR COVER COLUMN B (GLAN)	1	65.70	aa ? 65.70
RH EXTERIOR COVER WINDOW GUIDE WEB	1	61.75	? 61.75
REAR RH DOOR WINDOW GUIDE	1	124.40	? 124.40
SUPPORTING LEDGE RH	1	36.25	? 36.25
SUPPORTING LEDGE RH	1	37.75	? 37.75
SUPPORTING LEDGE RH	1	37.55	? 37.55
RH PRIMED SILL COVER (M)	1	386.95	Ry 386.95
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	x 20.20
BLIND RIVET HEML OCK 813	1	2.65	uu 2.65
BLIND RIVET AVIBVLB	12	0.55	uu 6.60
SCREW (SF PLUS M5X15)	3	0.55	uu 1.65
(DG/SL) BODY ADHESIVE K5B (195ML)	1	326.80	uu 326.80
(DG) BODYWORK ADHESIVE K5A (50ML)	1	112.70	uu 112.70
(DG) CLEANER R1 (100ML)	1	26.15	uu 26.15
(DG) CLEANER R1 (100ML)	1	26.15	uu 26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	uu 263.10
PUNCH RIVET N4	39	0.55	uu 21.45
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	uu 27.85
(S/L) SEAM SEAL 300ML	1	33.80	uu 33.80
Total Parts			8,111.65

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 6/12/18 1145 Excess S\$ _____

Surveyor's Name Tan Jiah Sign Tan Jiah

Surveyor's Tel 97495741 Authorised Yes/No _____

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes/No _____ PML Yes/No _____

Surveyor's E-mail tan.jiah@lhkauto.com

No. of Working Days Recommend 12-13 days

Labour 1	:	16,282.00
Parts	:	8,111.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,707.56
Grand Total	:	26,101.21

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****
**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****