

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 5/12/2018

Reference: SJZ3357X
CHEVROLET
ORLANDO
Make: 1.4AT TURBO

To Whom It May Concern

Dear Sir,

RE: VEHICLE .SJZ3357X
CHASSIS NO.:KL1YA7589GK333394
ENGINE NO.:A14NET153650338

Name of insured :KEK HONG SEE MRS PITT KUAN WAH
Date of accident.: 04/12/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)	
1	1	REAR BUMPER STEP PLATE	\$ 160.25	✓
2	1	REAR BUMPER UPPER	\$ 1,467.00	+
3	1	REAR BUMPER LOWER	\$ 540.00	✓
4	1	REAR BUMPER SILL PLATE(SILVER)	\$ 300.00	✓
5	1	REAR BUMPER TOWING COVER	\$ 75.00	+
6	1	LHR BUMPER REFLECTOR	\$ 95.00	+
7	1	RHR BUMPER REFLECTOR	\$ 95.00	+
8	1	REAR REVERSE LIGHT AND BRAKE LIGHT	\$ 401.00	+
9	1	REAR BUMPER CENTRE GUIDE	\$ 120.00	+
10	1	RHR BUMPER GUIDE, OTR	\$ 60.00	+
11	1	LHR BUMPER GUIDE, OTR	\$ 60.00	+
12	1	REAR BUMPER LEFT CENTRE GUIDE, INR	\$ 50.00	+
13	1	REAR BUMPER RIGHT CENTRE GUIDE, INR	\$ 50.00	+
14	1	REAR BUMPER BEAM	\$ 743.00	+
15	1	REAR END PANEL TRIM	\$ 125.00	+
16	1	REAR END PANEL OUTER	\$ 680.00	+
17	1	REAR END PANEL INNER	\$ 470.00	+
18	1	REVERSE SENSOR WIRING	\$ 325.00	x

1000.25
900.25

Parts Total: \$ 5,816.25
Less 10%: \$ 581.63
Total : \$ 5,234.63

Labour

Labour Description

No. Price (SGD)

Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$550 PER DAY)	\$ 2,200.00	550.
2	Carry out spray painting on accident affected area (\$450 PER PANEL)	\$ 1,800.00	450.
3	To conduct anti rust of under carriage tuff coat	\$ 110.00	+
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 110.00	30
5	To remove and refix reverse sensor and conduct test	\$ 110.00	50

1080

Labour Total : \$ 4,330.00

OthersOther Description

No. Qty Price (SGD)

Front portion

1	10	Rear bumper clip	new	\$ 65.00	30
2	6	Rear fender liner clips	2	\$ 39.00	+
3	10	Rear end panel trim clip	10	\$ 65.00	+
4	1	Reverse sensor (1 set)	1	\$ 440.00	+
5	1	Rear end panel insulation seal		\$ 180.00	+

30

Other Total: \$ 789.00

GRAND TOTAL: \$ 10,353.63

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Suhaimi Ong

Service Executive

Suhaimi Ong

HP : 8298 8933 Fax: 6844 5185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling
05/12/18 7/12
032yr

Total: 2010.23.