


# TAX INVOICE

<b>VEHICLE :</b> SGJ961R
<b>MAKE &amp; MODEL :</b> TOYOTA VIOS
<b>INSURANCE :</b> AIG ASIA PACIFIC INSURANCE
<b>TAX INVOICE :</b> JC/20191202/0961

	PARTS	CONDITION	COST
1.	FRONT BUMPER		\$ 298
2.	FRONT BUMPER GRILLE		\$ 245
3.	FRONT BUMPER BRACKET - LEFT		\$ 35
4.	FRONT BUMPER BRACKET - RIGHT		\$ 35
5.	FRONT BUMPER LOCK PANEL		\$ 89
6.	FRONT SUPPORT BEAM		\$ 281
7.	CONDENSOR		\$ 900
8.	RADIATOR FAN COVER		\$ 230
9.	REAR BOOT		\$ 690
10.	REAR BOOT HINGE - LEFT		\$ 75
11.	REAR BOOT HINGE - RIGHT		\$ 75
12.	REAR BOOT WEATHERSTRIP		\$ 165
13.	REAR BOOT LOCK		\$ 180
14.	REAR BUMPER		\$ 290
15.	TAILGATE LAMP - LEFT		\$ 195
16.	TAILGATE LAMP - RIGHT		\$ 195
17.	FENDER - LEFT		\$ 390
18.	REAR END PANEL		\$ 480
19.	REAR END PANEL TOP COVER		\$ 65
	<b>SPECIAL NETT</b>		
1.	FRONT NUMBER PLATE & COVER		\$ 45



2.	REAR NUMBER PLATE & COVER		\$ 30
3.	REVERSE SENSOR		\$ 200
4.	"TOYOTA" EMBLEM		\$ 75
5.	"VIOS" EMBLEM		\$ 55
6.	"1.5E" EMBLEM		\$ 35
7.	AIRCON GAS		\$ 10
8.	COOLANT		\$ 50
9.	CLIPS		\$ 60
<b>LABOUR</b>			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA		\$ 1600
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS		\$ 2000
3.	TO CHECK WIRING & REWIRE		\$ 60
4.	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY		\$ 60
5.	TO REMOVE & REINSTALL REVERSE SENSOR		\$ 50
6.	ANTI RUST TREATMENT		\$ 50
		<b>PARTS - 25% :</b>	\$ 3,684.75
		<b>SPECIAL NETT :</b>	\$ 560
		<b>LABOUR :</b>	\$ 3,820
		<b>TOTAL :</b>	\$ 8,064.75
		<b>LUMP SUM :</b>	\$ 3,500
		<b>7% GST :</b>	\$ 245
		<b>GRAND TOTAL :</b>	\$ 3,745



*S. Thanalethumi*

S.THANALETCHUMI

For JACK CARS ENTERPRISE PTE LTD