

TAX INVOICE

VEHICLE : SGJ961R
MAKE & MODEL : TOYOTA VIOS
INSURANCE : AIG ASIA PACIFIC INSURANCE
TAX INVOICE : JC/20191202/0961

PARTS		CONDITION	COST
1.	FRONT BUMPER		\$ 680
2.	FRONT BUMPER GRILLE		\$ 320
3.	FRONT BUMPER BRACKET - LEFT		\$ 55
4.	FRONT BUMPER BRACKET - RIGHT		\$ 55
5.	FRONT BUMPER LOCK PANEL		\$ 120
6.	FRONT SUPPORT BEAM		\$ 780
7.	CONDENSOR		\$ 900
8.	RADIATOR FAN COVER		\$ 230
9.	REAR BOOT		\$ 690
10.	REAR BOOT HINGE - LEFT		\$ 75
11.	REAR BOOT HINGE - RIGHT		\$ 75
12.	REAR BOOT WEATHERSTRIP		\$ 165
13.	REAR BOOT LOCK		\$ 180
14.	REAR BUMPER		\$ 550
15.	TAILGATE LAMP - LEFT		\$ 450
16.	TAILGATE LAMP - RIGHT		\$ 450
17.	FENDER - LEFT		\$ 390
18.	REAR END PANEL		\$ 480
19.	REAR END PANEL TOP COVER		\$ 120
SPECIAL NETT			
1.	FRONT NUMBER PLATE & COVER		\$ 45
2.	REAR NUMBER PLATE & COVER		\$ 30
3.	REVERSE SENSOR		\$ 200
4.	"TOYOTA" EMBLEM		\$ 75

5.	"VIOS" EMBLEM		\$ 55
6.	"1.5E" EMBLEM		\$ 35
7.	AIRCON GAS		\$ 10
8.	COOLANT		\$ 50
9.	CLIPS		\$ 60
	LABOUR		
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA		\$ 1600
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS		\$ 2000
3.	TO CHECK WIRING & REWIRE		\$ 60
4.	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY		\$ 60
5.	TO REMOVE & REINSTALL REVERSE SENSOR		\$ 50
6.	ANTI RUST TREATMENT		\$ 50
		PARTS - 25% :	\$ 5,073.75
		SPECIAL NETT :	\$ 560
		LABOUR :	\$ 3,820
		TOTAL :	\$ 9,453.75
		LUMP SUM – 20% :	\$ 7,563
		7% GST :	\$ 529.41
		GRAND TOTAL :	\$ 8,092.41

S.THANALETCHUMI

For JACK CARS ENTERPRISE PTE LTD