


MBM WHEELPOWER PTE LTD



Your Ref: SLD68S
Our Ref: SGB5588U

*Not At hand
1.B.1
Resony B4 palm
5-6 days*

To: AXA

CC

Fax

Date: 6/12/2018
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: B.M.W 520I SE AUTO
Chassis No.: WBAJA12020BJ19965
Engine No.: 20975261B48B20A
Year of Make: 2018
Accident Date: 4 December 2018

ESTIMATE FOR VEHICLE NO. : SGB5588U

DESCRIPTION	QTY		List Price
BONNET	1	\$	<i>R</i> 2,920.00 <i>7</i>
BONNET ACTOR LH	1	\$	<i>Act</i> 612.00 <i>✓</i>
BONNET ACTOR RH	1	\$	<i>Act</i> 612.00 <i>✓</i>
BONNET HINGE LH	1	\$	195.00 <i>7</i>
BONNET HINGE RH	1	\$	195.00 <i>7</i>
BONNET WEATHERSTRIP	1	\$	<i>su</i> 180.00 <i>X</i>
BONNET LH SUPPORT SEAL	1	\$	<i>su</i> 110.00 <i>X</i>
BONNET RH SUPPORT SEAL	1	\$	<i>su</i> 110.00 <i>X</i>
BONNET LH SEAL BRACKET	1	\$	<i>su</i> 70.00 <i>X</i>
BONNET RH SEAL BRACKET	1	\$	<i>su</i> 70.00 <i>X</i>
BONNET CENTER SEAL	1	\$	<i>su</i> 90.00 <i>X</i>
HEAD LAMP LH	1	\$	<i>CM</i> 3,620.00 <i>✓</i>
HEAD LAMP LH TOP SEAL	1	\$	88.00 <i>7</i>
HEAD LAMP LH LOWER BRACKET	1	\$	180.00 <i>7</i>
HEAD LAMP RH	1	\$	<i>su</i> 3,620.00 <i>X</i>
HEAD LAMP RH TOP SEAL	1	\$	<i>su</i> 88.00 <i>X</i>
HEAD LAMP RH LOWER BRACKET	1	\$	<i>su</i> 180.00 <i>X</i>
FRONT BUMPER	1	\$	<i>su</i> 2,150.00 <i>✓</i>
FRONT BUMPER CLIPS	10	\$	<i>Act</i> 80.00 <i>✓</i>
FRONT BUMPER LH SIDE RETAINER	1	\$	95.00 <i>7</i>
FRONT BUMPER RH SIDE RETAINER	1	\$	<i>su</i> 95.00 <i>X</i>
FRONT BUMPER SPONGE	1	\$	180.00 <i>7</i>
FRONT BUMPER REINFORCEMENT	1	\$	860.00 <i>7</i>
FRONT BUMPER LOWER GRILLE CENTER	1	\$	310.00 <i>7</i>
FRONT BUMPER LOWER GRILLE RH	1	\$	<i>CM</i> 245.00 <i>✓</i>

FRONT BUMPER LOWER GRILLE LH	1	\$	SL 245.00	X
FRONT BUMPER LOWER GRILLE CHROME MOULDING RH	1	\$	SL 250.00	X
FRONT BUMPER LOWER GRILLE CHROME MOULDING LH	1	\$	SL 250.00	X
FRONT RH FENDER	1	\$	N 1,520.00	X
FRONT RH FENDER INNER SHIELD	1	\$	SL 210.00	X
FRONT RH FENDER INNER SHIELD CLIPS	10	\$	SL 50.00	X
FRONT RH FENDER SPACER	1	\$	SL 65.00	X
FRONT RH FENDER SIDE PANEL BRACKET	1	\$	N 70.00	X
FRONT LH FENDER	1	\$	N 1,520.00	X
FRONT LH FENDER INNER SHIELD	1	\$	SL 210.00	X
FRONT LH FENDER INNER SHIELD CLIPS	10	\$	SL 50.00	X
FRONT LH FENDER SPACER	1	\$	N 65.00	X
FRONT LH FENDER SIDE PANEL BRACKET	1	\$	N 70.00	X
FRONT UNDERCOVER RH	1	\$	SL 225.00	X
FRONT UNDERCOVER LH	1	\$	SL 225.00	X
FRONT UNDERCOVER CENTER	1	\$	SL 420.00	X
BOOT LID	1	\$	N 2,215.00	X
BOOT LID HINGE LH	1	\$	N 195.00	X
BOOT LID HINGE RH	1	\$	N 195.00	X
BOOT LID RH SUPPORT	1	\$	SL 65.00	X
BOOT LID LH SUPPORT	1	\$	SL 65.00	X
BOOT LID POWER LOCK DRIVE	1	\$	N 990.00	X
BOOT LID PUSH BUTTON	1	\$	SL 120.00	X
BOOT LID LOCK	1	\$	N 380.00	X
BOOT LID STRIKER	1	\$	N 110.00	X
BOOT LID "BMW" LOGO	1	\$	SL 110.00	X
BOOT LID "520i" EMBLEM	1	\$	SL 80.00	X
BOOT LID LICENSE PLATE LH LAMP LED	1	\$	SL 280.00	X
BOOT LID LICENSE PLATE RH LAMP LED	1	\$	SL 280.00	X
BOOT LID LAMP RH	1	\$	SL 565.00	X
BOOT LID LAMP LH	1	\$	SL 565.00	X
BOOT LID INNER GARNISH TRIM	1	\$	SL 340.00	X
BOOT LID RH TRIM	1	\$	SL 95.00	X
BOOT LID LH TRIM	1	\$	SL 95.00	X
TAIL LAMP RH	1	\$	SL 970.00	X
TAIL LAMP LH	1	\$	SL 970.00	X
REAR BUMPER	1	\$	CM 1,830.00	✓
REAR BUMPER CLIPS	10	\$	NCC 50.00	✓
REAR BUMPER LOWER COVER	1	\$	CM 624.00	✓
REAR REINFORCEMENT	1	\$	845.00	?
REAR REINFORCEMENT LOWER	1	\$	200.00	?
REAR HEAT SHIELD RH	1	\$	110.00	?
REAR HEAT SHIELD LH	1	\$	110.00	?
REAR BUMPER CENTER GUIDE	1	\$	110.00	?
REAR BUMPER CENTER BOTTOM GUIDE	1	\$	165.00	?

REAR BUMPER TOW COVER RH	1	\$	Sn 90.00	X
REAR BUMPER LH REFLECTOR	1	\$	Sn 99.00	X
REAR BUMPER RH REFLECTOR	1	\$	Sk 99.00	X
END PANEL	1	\$	R 1,260.00	X
END PANEL TOP GARNISH	1	\$	Sn 280.00	X
REAR RH TAIL PIPE CHROME	1	\$	Na 650.00	✓
REAR LH TAIL PIPE CHROME	1	\$	650.00	?
REVERSE SENSOR @\$250 EACH	4	\$	Sn 1,000.00	X
REAR RH FENDER	1	\$	R 2,016.00	X
REAR LH FENDER	1	\$	R 2,016.00	X
HEAD REST SENSOR @ \$550 EACH	2	\$	Sk 1,100.00	X
Total: \$			44,389.00	
LESS 10% \$			(4,438.90)	
Parts Total: \$			39,950.10	

SPECIAL NETT

BODY SEALANT	1	\$	80.00	?
FRONT & REAR NUMBER PLATE WITH HOLDER	1	\$	Sn 120.00	X
TOWING FEE	1	\$	(Bill) 130.00	?

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	2,000.00	7501
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$	250.00	?
TO CONDUCT CAR-O-LINER FOR REAR CHASSIS ALIGNMENT	\$	na 450.00	X
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$	na 100.00	X
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	na 80.00	X
TO REMOVE & REPLACE EXHAUST PIPE SYSTEM TO FACILITATE REPAIR	\$	120.00	?
TO DISMANTLE & TRANSFER FITTINGS & MECHANISM TO NEW BOOTLID	\$	na 60.00	X
TO DISMANTLE & TRANSFER FITTINGS & MECHANISM TO NEW BONNET	\$	60.00	?
TO REPAIR REAR CHASSIS ALIGNMENT	\$	na 250.00	X
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	\$	na 80.00	X
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	80.00	40
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	1000 2,000.00	
Total: \$		45,810.10	
7% GST: \$		3,206.71	
Grand Total: \$		49,016.81	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Mbm wheelpowerpte ltd
160 SIN MING DRIVE #06-02
SIN MING AUTOCITY
t62628888 f64525333
Company Registration Number : 200204110W