

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1403/2018/GW
Date : 7-Dec-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Stoupas Jeremy Constantine
Address : 58 Swiss View
#01-01
Singapore 288061
Telephone : HP +65 98227714
Type of Claim : Third party Claims
Policy No. : 2100510117-01
Vehicle No : **SLP 7744 P**
Model Code : Audi Q5 2.0 TFSI Qu
Model / Year : Jun-17
Engine No : DAX 005239
Chassis No : WAUZZZF3H2022456
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Nov-18
Place of Accident : Along Bukit Timah Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 7744 P

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 ✓
2	To dismantle and renew rear bumper. Re-organize rear crash management components. Reinstall all parts removed.	\$ 1,050.00 700 ✓
3	To respray rear bumper and rear lower spoiler and both rear wheel arch covers.	\$ 2,000.00 +100 1,100 ✓
4	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00 ✓
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 3,882.00

700 : Bumper
200 x 2 = 400 : Wheel Cover
500 : Spoiler

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7744 P.

S/N	Parts Description	Damaged Parts & Prices S/Nett	
1	REAR BUMPER <i>Repair</i>	\$	1,488.00 <i>+</i>
2	REAR BUMPER SPACE HOLDER <i>new</i>	2 \$	13.00 <i>+</i>
3	REAR BUMPER COVER COVER <i>new</i>	\$	1,024.00 <i>+</i>
4	REAR BUMPER SPOILER <i>?</i>	\$	718.00 <i>+</i>
5	REAR BUMPER TOWING CAP-LH/RH	2 \$	66.00 <i>+</i>
6	REAR BUMPER CLOSING ELEMENT-RH	\$	81.00 <i>+</i>
7	REAR BUMPER CHROME TRIM-RH <i>Net</i>	\$	201.00 <i>+</i>
8	REAR BUMPER GUDIE SECTIO-RH	\$	71.00 <i>+</i>
9	REAR BUMPER SENSOR SEAL RING	4 \$	14.00 <i>+</i>
10	REAR WHEEL COVER-LH/RH <i>LH new, RH out</i>	2 \$	938.00 <i>-</i>
11	RUBBER VALVE <i>new</i>	4 \$	12.00 <i>+</i>
12	REAR RIM-RH <i>Lt</i>		TBC <i>✓</i>
13	SUNDRIES <i>?</i>	\$	300.00 <i>?</i>
TOTAL SPARE PARTS		:	\$ 4,926.00
TOTAL LABOUR CHARGES			\$ 3,882.00
GRAND TOTAL			\$ 8,808.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 12/12/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant