

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1404/2018/GW
Date : 7-Dec-18

Vehicle IN workshop. Kindly arrange for survey.

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Nicky H Gurnani
Address : 166 Meyer Road
Singapore 437952
Telephone : HP +65 90298383
Type of Claim : Own Damage Claims
Policy No. : VA1/GA129126
Vehicle No : **SLH 9999 A**
Model Code : Audi A6 C7 2.0 TFSI mu
Model / Year : Feb-14
Engine No : CDN 381040
Chassis No : WAUZZZ4G7EN062723
Mileage : 61700 KM
Date In : 6-Dec-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Dec-18
Place of Accident : Tanjong Katong rd Turning into Goodman Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLH 9999 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To recover and tow back vehicle from scene of accident.	S/N \$ 280.00 ✓	
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking sensor.	S/N \$ 480.00 ✗	
3	To remove and transfer lhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00 ✓	
4	To dismantle front bumper, lhs front door and lhs sill panel trim. To renew lhs front door and lhs wing mirror assy. To repair lhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 3,500.00	900 = 600 x 1.5
5	To respray front bumper, lhs front fender, bonnet, lhs front door, lhs wing mirror cover and lhs sill panel trim.	\$ 4,100.00	3150 600 x 500 = 3000 Mirror 150 3150
6	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
7	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 9,112.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLH 9999 A.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT WHEEL HOUSING LINER-LH <i>not new</i>	\$ 246.00	X
2	WHEEL HOUSING LINER ATTACHMENT PARTS <i>not new</i>	\$ 68.00	X
3	FRONT WHEEL SPOILER-LH <i>new</i>	\$ 202.00	X
4	FRONT STONE CHIP GUARD FILM-LH <i>new</i>	\$ 105.00	✓
5	FRONT DOOR-LH <i>Dented</i>	\$ 3,211.00	✓
5	FRONT STONE CHIP GUARD FILM-LH <i>new</i>	\$ 105.00	✓
6	FRONT DOOR ATTACHMENT PARTS-LH ?	\$ 164.00	?
7	FRONT OUTER DOOR SEAL <i>new</i>	\$ 202.00	✓
8	BONDING AGENT ?	\$ 43.00	?
9	CLEANING SOLUTION ?	\$ 64.00	?
10	FRONT DOOR CATCH-LH <i>not new</i>	\$ 105.00	X
11	FRONT DOOR CATCH COVER-LH <i>not new</i>	\$ 15.00	X
12	FRONT DOOR SEAL OUTER-LH ?	\$ 165.00	?
13	FRONT EXTERIOR MIRROR MOUNTING-LH <i>Damaged.</i>	\$ 1,237.00	✓
14	FRONT EXTERIOIR MIRROR HOUSING-LH ?	\$ 159.00	?
15	FRONT MIRROR GLASS-LH <i>shattered.</i>	\$ 1,094.00	✓
16	FRONT TURN SIGNAL INDICATOR-LH ?	\$ 111.00	?
17	FRONT STONE CHIP GUARD-LH <i>new</i>	\$ 63.00	✓
18	ADHESIVE TAPE ?	\$ 49.00	?
19	FRONT WINDOW SLOT EAL WITH TRIM STRIP-LH <i>not new</i>	\$ 294.00	X
20	MOLDING ROOF <i>not new</i>	\$ 440.00	X
SUB-TOTAL SPARE PARTS CHARGES		\$ 8,142.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLH 9999 A.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	1 SET OF ATTACHMENT PARTS FOR CLIP ?	\$ 91.00	?
22	1 SET OF ATTACHMENT PARTS FOR ADHESIVE TAPE ?	\$ 14.00	?
23	FRONT STONE GUARD FILM -LH <i>new</i>	\$ 102.00	✓
24	FRONT RIM LHS <i>lt</i>	\$ 726.00	✓
25	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS CHARGES :		\$ 9,375.00	
TOTAL LABOUR CHARGES		\$ 9,112.00	
GRAND TOTAL		\$ 18,487.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 07/12/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant